



Photo 73 (Aug 06) – Fill profile in testpit TP11



Photo 74 (Aug 06) – Retaining walls and fill in testpit TP12



Photo 75 (Aug 06) – Fill profile at testpit TP14, in north western site area



Photo 76 (Aug 06) – Brickwork and tars beneath the former retort house in testpit TP15



Photo 77 (Aug 06) – Brickwork and tars beneath the former retort house in testpit TP15



Photo 78 (Aug 06) – Fill profile including waste materials in testpit TP18 (on embankment between gasworks and stabling yard)



Photo 79 (Historic Photo) – Buried pipework (located unknown)



Photo 80 (Historic Photo) – Tarry materials (located unknown)



Photo 81 (Historic Photo) – Buried pipework (located unknown)



Photo 82 (Historic Photo) – Gasworks pipework (located unknown)