

gas holder




Current View of Site from Swanson Street Railway Bridge) top of gas holder visible in background



Simulated View of Site during remediation from Swanson Street rail bridge

Line of Sight From Swanson Street Into Site



© 2010 JBS Environmental Pty Ltd



Figure 11: Impact on External Viewing Location 3

Client: Incoll Management Job Number: 40913


Project: Visual Impact Assessment

Site: Former Macdonaldtown Gasworks

File Name: 40913 R05 Figure 11



Current View of Site from adjacent Burren Street residences into site



Line of Sight From Burren Street Into Site



Simulated View of Site during remediation from adjoining Burren Street residences

© 2010 JBS Environmental Pty Ltd



Figure 12: Impact on External Viewing Location 4

Client: Incoll Management Job Number: 40913

Project: Visual Impact Assessment


Site: Former Macdonaldtown Gasworks

File Name: 40913 R05 Figure 12

© JBS Environmental Pty Ltd 2010

This document is and shall remain the property of JBS Environmental Pty Ltd. The document may only be used for the purposes for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author(s)	Reviewer	Approved for Issue		
		Name	Name	Signature	Date
0	Sumi Dorairaj	Charlie Furr	-	-	21/07/10
1	Sumi Dorairaj	Charlie Furr	Charlie Furr		10/08/10



128 O'Riordan Street
Mascot NSW 2020
Tel: +61 2 8338 1011
Fax: +61 2 8338 1700

www.jbsgroup.com.au