




- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |

YOUNG - WAGGA WAGGA PIPELINE SECTION 2

Management Recommendations

Source: LPMA (2010), StreetPro (2009)




GDA94 - MGA Zone 55

19 Sep 2011

60189491

Fig. 11C


AECOM\\naubr\\p001\\Projects\\60189491\\APA_Gas_Pipeline_EIA\\4.7_GIS\\Maps\\G001_01_HeritageAssessment_MapSeries_110919.mxd Drafted: 19/09/2011



- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |




- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |



- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |



- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |



- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |



- | | | |
|---------------------|----------------------------|--------------------|
| Archaeological Site | Gas Pipeline Section 2 | Scarred Tree |
| Salvage Excavation | Historic Site Monitoring | Aborist Inspection |
| Surface Collection | Historic Site | Fenced |
| 200m Interval Point | Aboriginal Site Monitoring | No Direct Impacts |