

The uppermost level of the building is superficially consistent with the lower, but on close inspection the eastern, Kensington Street elevation in particular breaks from the strong discipline found on the lower levels, with windows placed irregularly along the façade.

The building is roofed with a simple flat-topped hip clad in corrugated iron.



Figure 4: The main facade of the Administration Building faces what was originally the main brewery driveway and is now to be known as Carlton Street. The main phases of the development of the building are shown.



Figure 5: Eastern elevation of the Administration Building showing the major phases in its development. The upper level was added at the same time as the northern extension but noticeably less care was given to ensuring that the fenestration patterns are consistent with those on the lower levels on this side of the building, although the overall rhythms and disciplined character of the facade are retained.