Site Regist	ration Date November 2021
Complete the follow	ving fields prior to calculating the Security Deposit.
Mine Name:	Teven Quarry
Lease(s):	N/A
Title Holder:	Holcim (Australia) Pty Ltd
Mine Operator:	Holcim (Australia) Pty Ltd
Expiry of MOP:	
Current Security:	NIL (expired) Date of last Security Deposit review
Mine Contact:	Shilpa Shashi
Position:	Planning and Environment Coordinator NSW / ACT
Address:	Level 7 Tower B - 799 Pacific Highway Chatswood NSW 2067
Phone:	0427 859 852 Email: <u>shilpa.shashi@lafargeholcim.com</u>

Summary of Mine Activities Total annual production (tonnes):	Environmental Sensitivities
Total annual production (tonnes):	
	Surrounding land use (tick all that apply):
Mine lease area (ha): N/A	Cropping
	✓ Pasture
Area of extraction (ha):	12.9 Forest
Area of disturbance (ha):	18.6 VIndisturbed habitat
Rehabilitation in progress (ha):	0.7 Urban
Rehabilitation complete (ha):         Assumed Nil           Achieved ecosystem sustainability         Assumed Nil	Environmental Issues affecting site (tick all t
	Threatened flora
MOP Utilised:	Threatened fauna
Reference MOP no. version and date	Cultural heritage items
MOP Plan(s) utilised: 1	Natural heritage features
Reference Plan no. version and date	Mine subsidence
2	Surface water pollution
Plan(s) attached	Ground water pollution
5	Hydrocarbon contamination
	Methane drainage/venting
	Spontaneous combustion
	Acid Mine Drainage
	Within drinking water catchment
NOTE: Ensure rehabilitation cost estimation reflects all environme	Other (describe below)
issues affecting the lease. Contingencies should be allocated	
where costs have not been incorporated elswhere in th	
estimation.	