

Sydney Children's Hospital
Ainsworth Building
Building 1 centre & south sections

James Townsend Dilapidation Surveys Pty. Ltd.

42 Corymbia Circuit, Oxford Falls. N.S.W. 2100

ABN 84 066 436 780

jamestownsend@tpg.com.au

Telephone 02 9975 7939

Mobile 0418 965 852

DILAPIDATION SURVEY REPORT

CONTRACTOR: Lend Lease Building Pty Limited

CONTRACT SITE: Randwick Campus Redevelopment

DATE OF SURVEY: 25th November & 2nd December 2019

BUILDING SURVEYED: Sydney Children's Hospital Randwick

Ainsworth Building facade & interior

Building 1 centre section facade.


Building 1 south section facade & interior

LEGEND


- 1A SYDNEY CHILDREN'S HOSPITAL
- 1B SCH SOUTH EAST WING
- 1C SCH SOUTH WEST WING
- 2A SCH EMERGENCY WING
- 2B HIGH STREET BUILDING
- 3 RADIATION ONCOLOGY
- 3A THE BRIGHT ALLIANCE BUILDING
- 4 MEDICAL SUPERINTENDANTS COTTAGE
- 5 EDMUND BLACKET BUILDING
- 6 EDMUND BLACKET BUILDING WEST WING (COMPUTER ROOM)
- 7 PARKES BUILDING
- 8 CLINICAL SCIENCES BUILDING
- 9 HYPERBARIC UNIT
- 10 ELECTRICAL SUBSTATION
- 11 EUROA
- 12 CATHERINE HAYES BUILDING
- 13 McNEVIN DICKSON
- 14A ADMINISTRATION BUILDING 2
- 14B DIABETES CENTRE
- 15 DICKINSON BUILDING
- 15A PSYCHIATRIC EMERGENCY CARE CENTRE
- 16 CAMPUS CENTRE
- 17 ROYAL HOSPITAL FOR WOMEN
- 18 PALLIATIVE CARE
- 19 MENTAL HEALTH INTENSIVE CARE UNIT
- 20 SYDNEY CHILDREN'S COMMUNITY HEALTHCENTRE
- 21 RONALD McDONALD HOUSE
- 22 POW CHILDCARE CENTRE
- 23 HUT U
- 24 METRO CAR PARK 8
- 25 KILOH CENTRE
- 26 BLACK DOG INSTITUTE
- 27 NEUROSCIENCES RESEARCH AUSTRALIA
- 28 UNSW BOOKSHOP

 Gate Numbers

Current scope



0m 10m 50m 100m





Ainsworth Building

25 November 2019 at 07:07:11



Ainsworth Building

Loading dock

25 November 2019 at 07:07:48



Ainsworth Building

Loading dock

25 November 2019 at 07:07:49



Ainsworth Building

Loading dock

25 November 2019 at 07:08:31



Ainsworth Building

Loading dock


25 November 2019 at 07:08:34



Ainsworth Building

Loading dock

25 November 2019 at 07:08:36



Ainsworth Building

Loading dock

25 November 2019 at 07:08:37



Ainsworth Building

Loading dock

25 November 2019 at 07:08:38



Ainsworth Building

Loading dock

25 November 2019 at 07:08:39



Ainsworth Building

Loading dock

25 November 2019 at 07:08:46



Ainsworth Building

Loading dock

25 November 2019 at 07:08:47



Ainsworth Building

Loading dock

25 November 2019 at 07:08:49



Ainsworth Building

Loading dock

25 November 2019 at 07:08:51



Ainsworth Building

Loading dock

25 November 2019 at 07:08:53



Ainsworth Building

Loading dock

25 November 2019 at 07:09:00



Ainsworth Building

Loading dock

25 November 2019 at 07:09:01



Ainsworth Building

Loading dock
25 November 2019 at 07:09:02



Ainsworth Building

Loading dock
25 November 2019 at 07:09:05



Ainsworth Building

Loading dock
25 November 2019 at 07:09:07



Ainsworth Building

Loading dock
25 November 2019 at 07:09:10



Ainsworth Building

Loading dock


25 November 2019 at 07:09:15



Ainsworth Building

Loading dock


25 November 2019 at 07:09:22



Ainsworth Building

Loading dock

25 November 2019 at 07:09:25



Ainsworth Building

Loading dock

25 November 2019 at 07:09:29



Ainsworth Building

Loading dock

25 November 2019 at 07:09:33



Ainsworth Building

Loading dock


25 November 2019 at 07:09:35



Ainsworth Building

Loading dock


25 November 2019 at 07:09:37



Ainsworth Building

Loading dock

25 November 2019 at 07:09:39



Ainsworth Building

Loading dock
25 November 2019 at 07:09:44



Ainsworth Building

Loading dock
25 November 2019 at 07:09:45



Ainsworth Building

Loading dock
25 November 2019 at 07:09:47



Ainsworth Building

Loading dock
25 November 2019 at 07:09:55



Ainsworth Building

Loading dock
25 November 2019 at 07:09:56



Ainsworth Building

Loading dock
25 November 2019 at 07:09:59



Ainsworth Building

Loading dock
25 November 2019 at 07:10:01



Ainsworth Building

Loading dock
25 November 2019 at 07:10:02



Ainsworth Building

Loading dock


25 November 2019 at 07:10:04



Ainsworth Building

Loading dock


25 November 2019 at 07:10:06



Ainsworth Building

Loading dock

25 November 2019 at 07:10:08



Ainsworth Building

Loading dock

25 November 2019 at 07:10:09



Ainsworth Building

Loading dock
25 November 2019 at 07:10:12



Ainsworth Building

Loading dock
25 November 2019 at 07:10:15

Ainsworth Building

Loading dock
25 November 2019 at 07:10:13



Ainsworth Building

Loading dock
25 November 2019 at 07:10:17



Ainsworth Building

Loading dock


25 November 2019 at 07:10:23



Ainsworth Building

Loading dock

25 November 2019 at 07:10:27



Ainsworth Building

Loading dock



25 November 2019 at 07:10:27



Ainsworth Building

Loading dock

25 November 2019 at 07:10:33



Ainsworth Building


Loading dock

25 November 2019 at 07:10:34

Ainsworth Building

Loading dock

25 November 2019 at 07:10:41



Ainsworth Building

Loading dock

25 November 2019 at 07:10:46

Ainsworth Building

Loading dock

25 November 2019 at 07:10:48



Ainsworth Building

Loading dock


25 November 2019 at 07:10:49



Ainsworth Building

Loading dock


25 November 2019 at 07:10:54



Ainsworth Building

Loading dock

25 November 2019 at 07:10:56



Ainsworth Building

Loading dock

25 November 2019 at 07:10:58



25/11/19, 07:11

Ainsworth Building

Loading dock

25 November 2019 at 07:11:04



25/11/19, 07:11

Ainsworth Building

Loading dock

25 November 2019 at 07:11:07



25/11/19, 07:11

Ainsworth Building

Loading dock

25 November 2019 at 07:11:10



25/11/19, 07:11

Ainsworth Building

Loading dock

25 November 2019 at 07:11:15



Ainsworth Building

Loading dock

25 November 2019 at 07:11:19



Ainsworth Building

East facade

25 November 2019 at 07:12:05

Ainsworth Building

Loading dock

25 November 2019 at 07:11:25



Ainsworth Building

East facade

25 November 2019 at 07:12:07



Ainsworth Building

East facade

25 November 2019 at 07:14:02



Ainsworth Building

East facade

25 November 2019 at 07:14:03



Ainsworth Building

East facade

25 November 2019 at 07:14:05



Ainsworth Building

East facade

25 November 2019 at 07:14:06



Ainsworth Building

East facade

25 November 2019 at 07:14:09



Ainsworth Building

East facade

25 November 2019 at 07:14:20



Ainsworth Building

East facade

25 November 2019 at 07:14:23



Ainsworth Building

East facade

25 November 2019 at 07:14:24



Ainsworth Building

East facade


25 November 2019 at 07:14:25



Ainsworth Building

East facade


25 November 2019 at 07:14:36



Ainsworth Building

East facade


25 November 2019 at 07:14:40



Ainsworth Building

East facade

25 November 2019 at 07:14:41



Ainsworth Building

East facade


25 November 2019 at 07:14:43



Ainsworth Building

East facade


25 November 2019 at 07:14:45



Ainsworth Building

East facade


25 November 2019 at 07:14:47



Ainsworth Building

East facade

25 November 2019 at 07:14:48



Ainsworth Building

East facade

25 November 2019 at 07:14:49



Ainsworth Building

East facade

25 November 2019 at 07:14:52



Ainsworth Building

East facade

25 November 2019 at 07:14:53



Ainsworth Building

East facade

25 November 2019 at 07:14:55



Ainsworth Building

East facade


25 November 2019 at 07:14:56



Ainsworth Building

East facade

25 November 2019 at 07:14:58



Ainsworth Building

East facade

25 November 2019 at 07:14:59



Ainsworth Building

East facade


25 November 2019 at 07:15:00



Ainsworth Building

East facade

25 November 2019 at 07:15:01



Ainsworth Building

East facade

25 November 2019 at 07:15:02



Ainsworth Building

East facade

25 November 2019 at 07:15:03



Ainsworth Building

South facade. Water penetration through window frames.

25 November 2019 at 07:15:37



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:15:53




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:15:54




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:15:55




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:15:56




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:16




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:17




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:18



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:19



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:21

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:22



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:23

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:25



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:26

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:37




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:39

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:41




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:42




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:52




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:54



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:55



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:56




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:57




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:16:59




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:00



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:01



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:14



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:16




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:18



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:19




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:27


Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:20



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:29



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:30



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:31



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:38

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:39



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:40



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:48



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:50



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:51



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:52



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:01

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:17:53



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:02



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:03



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:04



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:05



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:15



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:17



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:33




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:34



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:35



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:18:45



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:21



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:22




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:23



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:24



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:25



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:35



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:37



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:38



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:39



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:40



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:46



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:48



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:50



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:51



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:56



25/11/19, 07:19



25/11/19, 07:19

Ainsworth Building


South facade. Water penetration through window frames.
25 November 2019 at 07:19:58

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:19:59



25/11/19, 07:20




25/11/19, 07:20

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:03

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:08



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:09




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:17




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:18



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:19



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:27



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:37

Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:29



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:37



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:38




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:42



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:43




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:44



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:48



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:20:58



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:01




Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:09



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:15



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:16



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:16



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:20



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:21



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:22



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:22



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:23



Ainsworth Building

South facade. Water penetration through window frames.
25 November 2019 at 07:21:25




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:21:48




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:19




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:25




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:26



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:27



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:28



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:30



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:33



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:37



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:40



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:42



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:43




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:53



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:55



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:56



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:58




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:22:59



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:07



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:08




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:09




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:14



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:15



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:16



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:19

Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:20



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:24

Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:26



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:36



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:39



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:39




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:40



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:42



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:51



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:50



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:52



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:57



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:23:58



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:02




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:03




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:13




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:15




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:20



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:21




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:26



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:32




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:30




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:39



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:47



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:24:51




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:01



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:02



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:03



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:07

Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:04



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:12




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:14




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:21



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:29



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:32



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:40




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:42



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:52




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:53



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:54




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:25:56




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:26:04



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:26:05



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:26:08



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:26:19



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:26:10



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:26:20




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:05

Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:07




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:08


Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:09



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:11



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:14




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:15



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:16




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:17




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:18




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:21




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:22




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:23




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:37




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:38




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:39




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:41



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:42



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:42



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:55



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:27:58




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:04




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:10




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:12



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:24



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:26




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:28




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:28:43




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:30:04



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:30:05




Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:30:06



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:30:07



Ainsworth Building

West facade. Water penetration through window frames
25 November 2019 at 07:30:08



Ainsworth Building

North facade
25 November 2019 at 07:31:06



Ainsworth Building

North facade
25 November 2019 at 07:31:21



Ainsworth Building

North facade
25 November 2019 at 07:31:22



Ainsworth Building

North facade

2 December 2019 at 07:08:39



Ainsworth Building

North facade

2 December 2019 at 07:08:40


Damaged shade



Ainsworth Building

North facade


2 December 2019 at 07:08:40



Ainsworth Building

North facade

2 December 2019 at 07:08:41



Ainsworth Building

North facade


2 December 2019 at 07:08:51



Ainsworth Building

North facade


2 December 2019 at 07:08:52



Ainsworth Building

North facade

2 December 2019 at 07:08:53



Ainsworth Building

North facade

2 December 2019 at 07:08:54



Ainsworth Building

North facade

25 November 2019 at 07:31:24



Ainsworth Building

North facade

25 November 2019 at 07:31:25



Ainsworth Building

North facade

25 November 2019 at 07:31:26



Ainsworth Building

North facade

25 November 2019 at 07:31:29



Ainsworth Building

North facade


25 November 2019 at 07:31:30



Ainsworth Building

North facade

25 November 2019 at 07:31:31



Ainsworth Building

North facade

25 November 2019 at 07:31:32



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:44:58



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:12

Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:15



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:18

Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:19



Ainsworth Building

Level 4 Room D16a


25 November 2019 at 07:45:26



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:28



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:39



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:45:41



Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:46:33



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:47:28

Ainsworth Building

Level 4 Room D16a

25 November 2019 at 07:46:34



Ainsworth Building

Level 4 Room D15a/b


25 November 2019 at 07:47:32



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:47:56



Ainsworth Building

Level 4 Room D15a/b


25 November 2019 at 07:47:58



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:47:59



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:48:13



Ainsworth Building

Level 4 Room D15a/b
25 November 2019 at 07:48:14

Ainsworth Building

Level 4 Room D15a/b
25 November 2019 at 07:48:15




Ainsworth Building

Level 4 Room D15a/b
25 November 2019 at 07:48:20

Ainsworth Building


Level 4 Room D15a/b
25 November 2019 at 07:48:20



Ainsworth Building

Level 4 Room D15a/b


25 November 2019 at 07:48:25



Ainsworth Building

Level 4 Room D15a/b


25 November 2019 at 07:48:31



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:48:38



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:48:39



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:48:49



Ainsworth Building

Level 4 Room D15a/b


25 November 2019 at 07:48:50



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:49:05



Ainsworth Building

Level 4 Room D15a/b

25 November 2019 at 07:49:12



Ainsworth Building

Level 4 Room D14a

25 November 2019 at 07:51:18



Ainsworth Building

Level 4 Room D14a


25 November 2019 at 07:51:22



Ainsworth Building

Level 4 Room D14a


25 November 2019 at 07:51:24



Ainsworth Building

Level 4 Room D14a

25 November 2019 at 07:51:25



Ainsworth Building

Level 4 Room D14a

25 November 2019 at 07:51:33



Ainsworth Building

L 4 plant room access

25 November 2019 at 07:52:26



Ainsworth Building

L 4 plant room access

25 November 2019 at 07:52:24



Ainsworth Building

L 4 plant room access

25 November 2019 at 07:52:36



Ainsworth Building

Level 4 Plant Room 2094

25 November 2019 at 07:53:34



Ainsworth Building

Level 4 Plant Room 2094

25 November 2019 at 07:53:56



Ainsworth Building

Level 4 Plant Room 2094


25 November 2019 at 07:53:58



Ainsworth Building

Level 4 Plant Room 2094

25 November 2019 at 07:54:44



Ainsworth Building

Level 4 Plant Room 2094
25 November 2019 at 07:55:17



Ainsworth Building

Level 4 South toilet shower near kitchen. Damage to ceiling
25 November 2019 at 07:57:57



Ainsworth Building

Level 4 South toilet shower near kitchen. Damage to ceiling
25 November 2019 at 07:58:01



Ainsworth Building

South hall abutting Room 2087 ceiling
25 November 2019 at 07:59:28



Ainsworth Building

25 November 2019 at 07:59:33

Ainsworth Building

Level 4 ift lobby ceiling
25 November 2019 at 08:00:11



Ainsworth Building

Level 3 room 2055 Water entry through facade
25 November 2019 at 08:02:55

Ainsworth Building

Level 3 room 2055 Water entry through facade
25 November 2019 at 08:03:16



Ainsworth Building

Level 3 room 2055 Water entry through facade
25 November 2019 at 08:03:22



Ainsworth Building

Level 3 Courtyard
25 November 2019 at 08:05:11

Ainsworth Building

Level 3 room 2055 Water entry through facade
25 November 2019 at 08:03:25



Ainsworth Building


Level 3 Courtyard
25 November 2019 at 08:07:04



Ainsworth Building

Level 3 Courtyard

25 November 2019 at 08:07:46



Ainsworth Building


Level 3 Courtyard

25 November 2019 at 08:15:59



Ainsworth Building

25 November 2019 at 08:16:25



Ainsworth Building

25 November 2019 at 08:16:35



Ainsworth Building

25 November 2019 at 08:16:36



Ainsworth Building

Level 3 room 2016

25 November 2019 at 08:17:12



Ainsworth Building


Level 3 room 2016

25 November 2019 at 08:17:24

Ainsworth Building

Level 3 room 2016

25 November 2019 at 08:17:31




Ainsworth Building

Level 3 room 2016
25 November 2019 at 08:17:35

Ainsworth Building

Level 3 room 2016
25 November 2019 at 08:17:42



Ainsworth Building

Level 3 room 2016
25 November 2019 at 08:17:43

Ainsworth Building

Level 3 room 2020
25 November 2019 at 08:18:15




25/11/19, 08:18

Ainsworth Building

Level 3 room 2020

25 November 2019 at 08:18:23




25/11/19, 08:18

Ainsworth Building

Level 3 room 2020

25 November 2019 at 08:18:26




25/11/19, 08:18

Ainsworth Building

Level 3 room 2020

25 November 2019 at 08:18:30




25/11/19, 08:19

Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:02




Ainsworth Building

Level 3 room 2017
25 November 2019 at 08:19:14

Ainsworth Building

Level 3 room 2017
25 November 2019 at 08:19:15




Ainsworth Building

Level 3 room 2017
25 November 2019 at 08:19:17

Ainsworth Building

Level 3 room 2017
25 November 2019 at 08:19:18



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:21

Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:25



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:26

Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:27



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:37



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:39



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:47



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:19:49



Ainsworth Building

Level 3 room 2017


25 November 2019 at 08:19:50



Ainsworth Building

Level 3 room 2017

25 November 2019 at 08:20:42



Ainsworth Building

Level 3 room 2018


25 November 2019 at 08:21:07



Ainsworth Building

Level 3 room 2018

25 November 2019 at 08:21:16



Ainsworth Building

Level 3 room 2018

25 November 2019 at 08:21:21



Ainsworth Building

Level 3 room 2018


25 November 2019 at 08:21:33



Ainsworth Building

Level 3 room 2018


25 November 2019 at 08:21:41



Ainsworth Building

Level 3 room 2018

25 November 2019 at 08:21:57



Ainsworth Building

Level 3 room 2018

25 November 2019 at 08:21:59



Ainsworth Building

Level 3 room 2021

25 November 2019 at 08:22:30



Ainsworth Building

Level 3 room 2021

25 November 2019 at 08:22:37



Ainsworth Building

Level 3 room 2021

25 November 2019 at 08:22:38



Ainsworth Building

Level 3 room 2019.

25 November 2019 at 08:23:18



Ainsworth Building

Level 3 room 2019.

25 November 2019 at 08:23:32



Ainsworth Building

Level 3 room 2019.


25 November 2019 at 08:23:58



Ainsworth Building

Level 3 room 2019.

25 November 2019 at 08:24:02



Ainsworth Building

Level 2
25 November 2019 at 08:30:59

Ainsworth Building

Level 2
25 November 2019 at 08:31:10




Ainsworth Building

Level 2 Occupational therapy north west office ceiling
25 November 2019 at 08:35:22

Ainsworth Building

Level 2 Occupational therapy north west office ceiling
25 November 2019 at 08:35:28



Ainsworth Building

Level 2 Occupational therapy north west office ceiling
25 November 2019 at 08:35:31



Ainsworth Building

.
25 November 2019 at 08:37:20



Ainsworth Building

.
25 November 2019 at 08:37:22



Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:22




Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:31




Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:31



Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:38



Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:38



Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:39



Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:40



Ainsworth Building

Level 2 Cerebral palsy office ceiling
25 November 2019 at 08:37:44




Ainsworth Building

Level 1 room 1025 ceiling
25 November 2019 at 08:42:24



Ainsworth Building

Level 1 room 1025 ceiling
25 November 2019 at 08:42:33



Ainsworth Building

.
25 November 2019 at 08:45:32



Ainsworth Building

.
25 November 2019 at 08:50:04



Ainsworth Building

.
25 November 2019 at 08:50:42



Ainsworth Building

.
25 November 2019 at 08:50:44



Ainsworth Building

.
25 November 2019 at 08:50:47



Ainsworth Building

.
25 November 2019 at 08:50:53



Ainsworth Building


.
25 November 2019 at 08:50:55



Ainsworth Building

Level 1 room 3054

25 November 2019 at 08:52:49



Ainsworth Building

Level 1 room 3054


25 November 2019 at 08:52:53



Ainsworth Building

Level 1 room 3055. Water entry

25 November 2019 at 08:53:24



Ainsworth Building


Level 1 room 3055. Water entry

25 November 2019 at 08:53:43




Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:53:47




Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:53:48



Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:53:49




Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:53:50



Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:53:51



Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:53:52



Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:54:04



Ainsworth Building

Level 1 room 3055. Water entry
25 November 2019 at 08:54:12




Ainsworth Building

Level 1 room 3056 water entry
25 November 2019 at 08:54:14



Ainsworth Building

Level 1 room 3056 water entry
25 November 2019 at 08:55:22



Ainsworth Building

Level 1 room 3056 water entry
25 November 2019 at 08:55:25



Ainsworth Building

Level 1 room 3056 water entry
25 November 2019 at 08:55:27



Ainsworth Building

Level 0 Child protection offices.
25 November 2019 at 08:59:28




Ainsworth Building

Level 0 Child protection offices. Room 1906 water
penetration
25 November 2019 at 09:04:44



Ainsworth Building

Level 0 Child protection offices. Room 1906 water
penetration
25 November 2019 at 09:06:01



Ainsworth Building

Level 0 Child protection offices. Room 1906 water
penetration
25 November 2019 at 09:06:45



Ainsworth Building

Level 0 Child protection offices. Room 1906 water penetration

25 November 2019 at 09:06:46

Ainsworth Building

Level 0 Child protection offices. Room 1906 water penetration

25 November 2019 at 09:06:52



Ainsworth Building

Level 0 Child protection offices. Room 1906 water penetration

25 November 2019 at 09:06:53

Ainsworth Building

Level 0 Child protection offices. Kitchen room 9098

25 November 2019 at 09:07:57



Ainsworth Building

Level 0 Child protection offices. Kitchen room 9098
25 November 2019 at 09:08:15

Ainsworth Building

Level 0 Child protection offices. Hall abutting room1927
25 November 2019 at 09:09:51




Ainsworth Building

Level 0 Child protection offices. Hall abutting room1927
25 November 2019 at 09:09:55

Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:12:07



Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:12:09

Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:12:24




Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:12:34

Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:12:35




Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:12:36



Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:13:04



Ainsworth Building

Level 0 Child protection offices. Reception ceiling
25 November 2019 at 09:13:06



Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:04




Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:18



Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:19




Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:20



Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:23



Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:27

Ainsworth Building

Level 0 Child protection offices. North hall entry
25 November 2019 at 09:14:28




Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:17

Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:18




Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:21

Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:22




Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:27

Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:27



Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:28

Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:28



Ainsworth Building

Level 3 lift lobby ceiling abutting west hall
25 November 2019 at 09:20:29

Ainsworth Building

North Level 3 link bridge ceiling
25 November 2019 at 09:21:20



Ainsworth Building

North Level 3 link bridge ceiling
25 November 2019 at 09:21:23



Ainsworth Building

North Level 3 link bridge ceiling
25 November 2019 at 09:21:32



Ainsworth Building

North Level 3 link bridge ceiling
25 November 2019 at 09:22:00



Ainsworth Building

North Level 3 link bridge ceiling
25 November 2019 at 09:22:04



Ainsworth Building

North Level 3 link bridge ceiling
25 November 2019 at 09:22:19



Ainsworth Building

Level 2 lift lobby ceiling
25 November 2019 at 09:24:35



Ainsworth Building

Level 2 lift lobby ceiling
25 November 2019 at 09:24:43

Ainsworth Building

Level 2 lift lobby ceiling
25 November 2019 at 09:24:47



Ainsworth Building

Level 2 lift lobby ceiling

25 November 2019 at 09:24:48



Ainsworth Building

Level 2 lift lobby ceiling

25 November 2019 at 09:24:50

Ainsworth Building

Level 2 lift lobby ceiling

25 November 2019 at 09:24:49



Ainsworth Building

Level 2 North Link bridge ceiling

25 November 2019 at 09:25:42



Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:25:48




Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:25:56



Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:26:00




Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:26:05



Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:26:06



Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:26:17



Ainsworth Building

Level 2 North Link bridge ceiling
25 November 2019 at 09:26:28



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:07



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:08



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:08



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:11



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:14



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:17



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:19



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:20



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:22



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:23



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:24



Ainsworth Building

Level 2 South link bridge roof
25 November 2019 at 09:27:26



Ainsworth Building

Level 1 lift lobby ceiling
25 November 2019 at 09:29:28



Ainsworth Building

Level 1 lift lobby ceiling

25 November 2019 at 09:29:32



Ainsworth Building

Level 1 lift lobby ceiling

25 November 2019 at 09:29:33



Ainsworth Building

Level 1 lift lobby ceiling

25 November 2019 at 09:29:33



Ainsworth Building

Level 1 lift lobby ceiling

25 November 2019 at 09:29:34



Ainsworth Building

Level 1 lift lobby ceiling

25 November 2019 at 09:29:36



Ainsworth Building

South west fire stair level 4 airlock

25 November 2019 at 09:34:39



Ainsworth Building

South west fire stair level 4 airlock

25 November 2019 at 09:34:52



Ainsworth Building

South west fire stair level 4 airlock

25 November 2019 at 09:34:57



Ainsworth Building

South west fire stair level 4 airlock
25 November 2019 at 09:34:58




Ainsworth Building

South west fire stair level 4 airlock
25 November 2019 at 09:34:59




Ainsworth Building

South west fire stair level 4 airlock
25 November 2019 at 09:35:02



Ainsworth Building

South west fire stair level 4 airlock
25 November 2019 at 09:35:05



Ainsworth Building

South west fire stair level 4 airlock
25 November 2019 at 09:35:06



Ainsworth Building

Level 4 fire stairs south wall fracture under window
west end
25 November 2019 at 09:36:10


Ainsworth Building

South west fire stair level 4 airlock
25 November 2019 at 09:35:11



Ainsworth Building

Level 4 fire stairs south wall fracture under window
west end
25 November 2019 at 09:36:44



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end


25 November 2019 at 09:36:47



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:36:55



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end


25 November 2019 at 09:36:58




Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:04



25/11/19, 09:37



25/11/19, 09:37

Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:05

Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:05



25/11/19, 09:37



25/11/19, 09:37

Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:06

Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:07



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:08



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:09



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:12



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end


25 November 2019 at 09:37:23



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:24



Ainsworth Building

Level 4 fire stairs south wall fracture under window west end

25 November 2019 at 09:37:25



Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head


25 November 2019 at 09:38:56



Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head

25 November 2019 at 09:39:10



Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head
25 November 2019 at 09:39:11



Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head
25 November 2019 at 09:39:13



Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head
25 November 2019 at 09:39:18



Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head
25 November 2019 at 09:39:19



25/11/19, 09:39

Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head

25 November 2019 at 09:39:31



25/11/19, 09:39

Ainsworth Building

Level 3 fire stairs south wall fractures under east and west ends of window sill and over west end window head

25 November 2019 at 09:39:48



25/11/19, 09:41

Ainsworth Building

Level 3-2 fire stairs. Staining to walls

25 November 2019 at 09:41:07




25/11/19, 09:41

Ainsworth Building

Level 3-2 fire stairs. Staining to walls

25 November 2019 at 09:41:07



Ainsworth Building

Level 3-2 fire stairs. Staining to walls
25 November 2019 at 09:41:08

Ainsworth Building

Level 3-2 fire stairs. Staining to walls
25 November 2019 at 09:41:21



Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:01

Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:15



Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:17

Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:18



Ainsworth Building


Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:19

Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:20



25/11/19, 09:42



25/11/19, 09:42

Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:21

Ainsworth Building

Level 2 fire stairs fractures above and below window
25 November 2019 at 09:42:27



25/11/19, 09:43



25/11/19, 09:43

Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:43:32

Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:43:37



Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:43:46



Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:44:04



Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:44:05



Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:44:07



Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:44:08

Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:44:09




Ainsworth Building

Level 2-1 fire stairs . Poor finish above window
25 November 2019 at 09:44:10



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:04



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:12



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:13



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:22



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:27



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:28

Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:32



Ainsworth Building

Level 1 fire stairs. Fractures above and below window
25 November 2019 at 09:45:33

Ainsworth Building

Fire stairs between Level 2-1 damage to the ceiling
25 November 2019 at 09:46:19



Ainsworth Building

Fire stairs between Level 2-1 damage to the ceiling
25 November 2019 at 09:46:21

Ainsworth Building

Fire stairs between Level 2-1 damage to the ceiling
25 November 2019 at 09:46:22



Ainsworth Building

Fire stairs between Level 2-1 damage to the ceiling
25 November 2019 at 09:46:23

Ainsworth Building

Fire stairs between Level 2-1 damage to the ceiling
25 November 2019 at 09:46:24



25/11/19, 09:46

Ainsworth Building


Fire stairs between Level 2-1 damage to the ceiling
25 November 2019 at 09:46:31



25/11/19, 09:47

Ainsworth Building

Fire stairs Level 0 temporary patch to ceiling
25 November 2019 at 09:47:28



25/11/19, 09:47

Ainsworth Building


Fire stairs Level 0 temporary patch to ceiling
25 November 2019 at 09:47:35



25/11/19, 09:48

Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint,
rubbish & debris
25 November 2019 at 09:48:51



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint, rubbish & debris

25 November 2019 at 09:49:01



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint, rubbish & debris

25 November 2019 at 09:49:02



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint, rubbish & debris

25 November 2019 at 09:49:03



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint, rubbish & debris

25 November 2019 at 09:49:47



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint,
rubbish & debris

25 November 2019 at 09:49:48



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint,
rubbish & debris

25 November 2019 at 09:49:49



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint,
rubbish & debris

25 November 2019 at 09:49:50



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint,
rubbish & debris

25 November 2019 at 09:49:51



Ainsworth Building

Fire stairs Exit landing fracture to north east wall joint,
rubbish & debris


25 November 2019 at 09:49:52



Ainsworth Building

B 1 pump room

2 December 2019 at 11:02:43



Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:18



Ainsworth Building

B 1 pump room


2 December 2019 at 11:03:20



Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:21



Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:30



Ainsworth Building

B 1 pump room



2 December 2019 at 11:03:31



Ainsworth Building

B 1 pump room


2 December 2019 at 11:03:40



Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:41



Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:47

Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:42



Ainsworth Building

B 1 pump room

2 December 2019 at 11:03:48



Ainsworth Building

B 1 pump room
2 December 2019 at 11:03:57



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:10



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:11



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:22



Ainsworth Building

B 1 pump room


2 December 2019 at 11:04:23



Ainsworth Building

B 1 pump room

2 December 2019 at 11:04:23



Ainsworth Building

B 1 pump room

2 December 2019 at 11:04:24



Ainsworth Building

B 1 pump room

2 December 2019 at 11:04:27



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:29



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:33




Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:35



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:41



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:42

Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:42



Ainsworth Building

B 1 pump room
2 December 2019 at 11:04:50

Ainsworth Building


B 1 pump room
2 December 2019 at 11:04:52



Ainsworth Building

B 1 pump room


2 December 2019 at 11:04:53



Ainsworth Building

B 1 pump room


2 December 2019 at 11:04:54



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:07



Ainsworth Building

B 1 pump room


2 December 2019 at 11:05:08



Ainsworth Building

B 1 pump room


2 December 2019 at 11:05:09



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:15



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:16



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:25



Ainsworth Building

B 1 pump room


2 December 2019 at 11:05:26



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:27



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:28



Ainsworth Building

B 1 pump room

2 December 2019 at 11:05:42



Building 1 South

West facade poor state of repair
2 December 2019 at 07:06:48



Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:15



Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:28



Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:31



Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:32

Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:37



Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:38

Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:39




Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:41

Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:41



Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:42

Building 1 South

West facade poor state of repair
2 December 2019 at 07:07:43



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:07:50



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:07:51



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:07:58



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:07:59



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:00



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:06



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:09



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:09




Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:10

Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:10




Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:11

Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:11




Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:12

Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:12



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:18



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:22



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:23



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:24



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:25



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:26



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:31



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:32




Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:38



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:52



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:55



Building 1 South

West facade poor state of repair
2 December 2019 at 07:08:56



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:01

Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:02



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:03

Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:04



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:05



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:08




Building 1 South

West facade poor state of repair
 2 December 2019 at 07:09:08



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:09:10



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:09:13



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:09:16



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:24

Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:24



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:26

Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:27



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:33



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:33



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:34



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:35



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:36



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:37



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:38



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:38



Building 1 South

West facade poor state of repair
2 December 2019 at 07:09:39



Building 1 South

West facade poor state of repair
2 December 2019 at 07:10:22



Building 1 South

West facade poor state of repair
2 December 2019 at 07:10:24



Building 1 South

West facade poor state of repair
2 December 2019 at 07:10:25



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:10:28



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:11:09

Building 1 South

West facade poor state of repair
 2 December 2019 at 07:10:29



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:11:10



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:11:22



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:11:23



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:11:31



Building 1 South

West facade poor state of repair
 2 December 2019 at 07:11:39



2/12/19, 07:11

Building 1 South


West facade poor state of repair
2 December 2019 at 07:11:41



2/12/19, 07:11

Building 1 South

West facade poor state of repair
2 December 2019 at 07:11:51



2/12/19, 07:11

Building 1 South

West facade poor state of repair
2 December 2019 at 07:11:52



2/12/19, 07:11

Building 1 South

West facade poor state of repair
2 December 2019 at 07:11:53




Building 1 South

West facade poor state of repair
2 December 2019 at 07:11:56

Building 1 South

West facade poor state of repair
2 December 2019 at 07:11:58



Building 1 South

West facade poor state of repair
2 December 2019 at 07:11:59

Building 1 South

West facade poor state of repair
2 December 2019 at 07:12:00



Building 1 South

West facade poor state of repair
2 December 2019 at 07:12:04

Building 1 South

West facade poor state of repair
2 December 2019 at 07:12:05



Building 1 South

West facade poor state of repair
2 December 2019 at 07:12:06

Building 1 South

West facade poor state of repair
2 December 2019 at 07:12:07



Building 1 South

West facade poor state of repair
2 December 2019 at 07:12:08



Building 1 South

South facade poor state of repair
2 December 2019 at 07:12:26



Building 1 South

South facade poor state of repair
2 December 2019 at 07:12:28



Building 1 South

South facade poor state of repair
2 December 2019 at 07:12:29



Building 1 South

South facade poor state of repair
2 December 2019 at 07:12:30



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:36



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:49



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:51



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:52



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:54



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:55



Building 1 South

South facade poor state of repair
2 December 2019 at 07:13:56



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:01



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:02



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:03



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:04




Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:04



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:05



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:06



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:11



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:15



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:27



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:38



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:48




Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:52




Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:54



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:55



Building 1 South

South facade poor state of repair
2 December 2019 at 07:14:56



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:07



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:09



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:13



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:14




Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:15



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:16



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:27




Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:29



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:30




Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:31





Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:32



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:32




Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:35

Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:36




Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:51

Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:52



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:53



Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:59


Building 1 South

South facade poor state of repair
2 December 2019 at 07:15:55




Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:00



Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:04




Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:04




Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:08



Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:09




Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:12




Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:17



Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:18



Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:19



Building 1 South

South facade poor state of repair
2 December 2019 at 07:16:20



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:13




Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:17



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:18



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:20




Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:21



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:23




Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:24



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:25



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:31



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:33




Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:37




Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:38



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:44



Building 1 South

South facade poor state of repair
2 December 2019 at 07:17:45



Building 1 South


South facade poor state of repair
2 December 2019 at 07:17:46



Building 1 South

South facade poor state of repair

2 December 2019 at 07:17:47



Building 1 South

South facade poor state of repair

2 December 2019 at 07:17:49



Building 1 South

South facade poor state of repair

2 December 2019 at 07:17:50



Building 1 South

South facade poor state of repair

2 December 2019 at 07:18:02




Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:03



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:04



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:05



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:26



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:29



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:30



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:31



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:34



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:35

Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:36



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:38

Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:39



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:40



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:43



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:44



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:45




Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:47

Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:47




Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:49



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:50



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:52



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:54




Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:56



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:58



Building 1 South

South facade poor state of repair
2 December 2019 at 07:18:59



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:00



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:01



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:02



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:14



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:27



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:28



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:29



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:31



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:31



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:32



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:33



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:35



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:36



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:37



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:38



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:40

Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:41



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:43

Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:43



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:44

Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:46



Building 1 South

South facade poor state of repair
2 December 2019 at 07:19:46

Building 1 South

ground floor wesr facade & carpark
2 December 2019 at 07:19:49



Building 1 South

gound floor wesr facade & carpark

2 December 2019 at 07:19:55



Building 1 South

gound floor wesr facade & carpark

2 December 2019 at 07:19:56



Building 1 South

gound floor wesr facade & carpark

2 December 2019 at 07:20:02



Building 1 South

gound floor wesr facade & carpark

2 December 2019 at 07:20:03



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:07



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:10

Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:08



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:11



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:17




Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:18



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:19



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:24



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:26

Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:27



Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:28

Building 1 South

gound floor wesr facade & carpark
2 December 2019 at 07:20:30



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:41



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:42




Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:43



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:43



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:44



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:45




Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:46



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:47



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:48



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:48



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:49




Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:50




Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:51



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:52



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:53



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:54



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:57



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:59



Building 1 South

South facade poor state of repair
2 December 2019 at 07:20:59



Building 1 South

South facade poor state of repair
2 December 2019 at 07:21:00



Building 1 South

South facade poor state of repair
 2 December 2019 at 07:21:01



Building 1 South

South facade poor state of repair
 2 December 2019 at 07:21:04



Building 1 South

South facade poor state of repair
 2 December 2019 at 07:21:05



Building 1 South

South facade poor state of repair
 2 December 2019 at 07:21:06



Building 1 South

South facade poor state of repair
2 December 2019 at 07:21:07



Building 1 South

South facade poor state of repair
2 December 2019 at 07:21:07



Building 1 South

South facade poor state of repair
2 December 2019 at 07:21:09



Building 1 South

South facade poor state of repair
2 December 2019 at 07:21:10



Building 1 South

Room C1187. Ceiling & tiles
2 December 2019 at 07:48:41



Building 1 South

Room C1187. Ceiling & tiles
2 December 2019 at 07:48:57



Building 1 South

Room C1187. Ceiling & tiles
2 December 2019 at 07:49:00



Building 1 South

Room C1187. Ceiling & tiles
2 December 2019 at 07:50:34



Building 1 South



Room C1187. Ceiling & tiles

2 December 2019 at 07:50:35

Building 1 South

Room C1187. Ceiling & tiles

2 December 2019 at 07:50:36



Building 1 South

Room C1187. Ceiling & tiles

2 December 2019 at 07:51:04

Building 1 South

Room C1187. Ceiling & tiles

2 December 2019 at 07:51:07



Building 1 South

Room C1187. Ceiling & tiles
2 December 2019 at 07:51:08

Building 1 South

Room C1187. Ceiling & tiles
2 December 2019 at 07:51:12



Building 1 South

Room Plant C1188
2 December 2019 at 07:53:32

Building 1 South

Room Plant C1188
2 December 2019 at 07:53:52



Building 1 South

Room Plant C1188

2 December 2019 at 07:53:59



Building 1 South

Room Plant C1188


2 December 2019 at 07:54:01



Building 1 South

Room Plant C1188

2 December 2019 at 07:54:02



Building 1 South

Room Plant C1188

2 December 2019 at 07:54:06



Building 1 South

Room Plant C1188
2 December 2019 at 07:54:43

Building 1 South

Room Plant C1188
2 December 2019 at 07:54:44



Building 1 South

Room Plant C1188
2 December 2019 at 07:54:46

Building 1 South


Room Plant C1188
2 December 2019 at 07:54:54



Building 1 South

Room Plant C1188

2 December 2019 at 07:54:55



Building 1 South

Room Plant C1188

2 December 2019 at 07:54:56



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:01



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:05



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:07



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:15



Building 1 South

Room Plant C1188


2 December 2019 at 07:55:22



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:27



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:29



Building 1 South

Room Plant C1188

2 December 2019 at 07:55:59

Building 1 South

Room Plant C1188

2 December 2019 at 07:55:57



Building 1 South

Room Plant C1188

2 December 2019 at 07:56:05



Building 1 South

Room Plant C1188

2 December 2019 at 07:56:07



Building 1 South

Room Plant C1188

2 December 2019 at 07:56:14



Building 1 South

Room Plant C1188

2 December 2019 at 07:56:15



Building 1 South

Room Plant C1188

2 December 2019 at 07:56:17



Building 1 South

Room C1183

2 December 2019 at 07:58:45



Building 1 South

Room C1183

2 December 2019 at 07:59:21



Building 1 South

Room C1183

2 December 2019 at 07:59:40



Building 1 South

Ceiling near Room C1183

2 December 2019 at 08:00:39



Building 1 South

Level 2
2 December 2019 at 08:03:01

Building 1 South

Level 2
2 December 2019 at 08:03:13





Building 1 South

Level 2
2 December 2019 at 08:04:07

Building 1 South

Level 2 North west Lounge ceiling
2 December 2019 at 08:04:33



Building 1 South

Level 2 North west facade

2 December 2019 at 08:05:33



Building 1 South

Level 2 North west facade

2 December 2019 at 08:05:39

Building 1 South

Level 2 North west facade

2 December 2019 at 08:05:35



Building 1 South

Level 2 North west facade

2 December 2019 at 08:06:13



Building 1 South

Level 2 North west facade
2 December 2019 at 08:06:19




Building 1 South

Level 2 North west facade
2 December 2019 at 08:06:20



Building 1 South

Level 2 plant C2189
2 December 2019 at 08:07:27



Building 1 South


Level 2 plant C2189
2 December 2019 at 08:08:03



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:07



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:11



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:13



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:14



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:16



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:19



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:20



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:21



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:25



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:27



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:42



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:42



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:52



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:57



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:08:58



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:09:01



Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:06

Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:08



Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:16

Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:16



Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:20



Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:30

Building 1 South

Level 2 plant C2189
2 December 2019 at 08:09:22



Building 1 South


Level 2 plant C2189
2 December 2019 at 08:09:41



Building 1 South

Level 2 plant C2189


2 December 2019 at 08:09:47



Building 1 South

Level 2 plant C2189


2 December 2019 at 08:09:57



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:09:58



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:09:59



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:10:00



Building 1 South

Level 2 plant C2189

2 December 2019 at 08:10:02



Building 1 South

Level 3


2 December 2019 at 08:12:38




Building 1 South

Level 3

2 December 2019 at 08:12:51



Building 1 South
 Level 3 West room
 2 December 2019 at 08:14:34



Building 1 South
 Level 3 West room
 2 December 2019 at 08:14:35



Building 1 South
 Level 3 West facade
 2 December 2019 at 08:15:00



Building 1 South
 Level 3 West facade
 2 December 2019 at 08:15:06



2/12/19, 08:15



2/12/19, 08:15

Building 1 South

Level 3 West facade

2 December 2019 at 08:15:08

Building 1 South

Level 3 West facade

2 December 2019 at 08:15:09



2/12/19, 08:15



2/12/19, 08:15

Building 1 South

Level 3 West facade

2 December 2019 at 08:15:16

Building 1 South

Level 3 West facade

2 December 2019 at 08:15:18



Building 1 South

Level 3 West facade

2 December 2019 at 08:15:19



Building 1 South

Level 3 west facade

2 December 2019 at 08:16:48



Building 1 South

Level 3 west facade


2 December 2019 at 08:16:49



Building 1 South

Level 3 west facade


2 December 2019 at 08:16:49



Building 1 South

Level 3 west facade


2 December 2019 at 08:16:50



Building 1 South

Level 3 west facade

2 December 2019 at 08:16:51



Building 1 South

Level 3 west facade

2 December 2019 at 08:16:52



Building 1 South

Level 3 west facade

2 December 2019 at 08:16:53



Building 1 South
Level 3 west facade
2 December 2019 at 08:16:56




Building 1 South
Level 3 west facade
2 December 2019 at 08:17:00



Building 1 South
Level 3 west facade
2 December 2019 at 08:17:02



Building 1 South
Level 3 west facade
2 December 2019 at 08:17:05



Building 1 South

Level 3 west facade
2 December 2019 at 08:17:10

Building 1 South

Level 3 west facade
2 December 2019 at 08:17:18



Building 1 South

Level 3 west facade
2 December 2019 at 08:18:50

Building 1 South

Level 3 west facade
2 December 2019 at 08:18:51



Building 1 South

Level 3 west facade

2 December 2019 at 08:19:08



Building 1 South

Level 3 west facade

2 December 2019 at 08:19:15



Building 1 South

Level 3 Hall near fire exit ceiling


2 December 2019 at 08:19:43



Building 1 South


South west Fire stairs level 3 to exit

2 December 2019 at 08:20:40



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:20:42



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:20:45



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:20:50



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:20:55



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:00



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:04




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:12



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:14



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:16

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:19



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:21

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:22




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:25

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:28



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:29



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:30



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:31



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:32



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:33



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:34




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:36



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:38




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:42



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:44



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:46




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:50

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:48



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:54



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:56

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:57




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:58


Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:21:59



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:01




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:02



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:03



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:05



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:06



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:07




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:10



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:12



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:15



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:17



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:20



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:22



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:24



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:32




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:34



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:35



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:37



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:39




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:42




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:43



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:44




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:46



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:53



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:54



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:56

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:57




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:57

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:22:58



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:00




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:03



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:05




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:06



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:07




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:09



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:10



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:11



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:12



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:13



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:14



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:15



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:16



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:18

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:17



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:18



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:19



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:20




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:21



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:22



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:23



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:24




Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:25



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:27



2/12/19, 08:23

Building 1 South


South west Fire stairs level 3 to exit
2 December 2019 at 08:23:28



2/12/19, 08:23

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:29



2/12/19, 08:23

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:31



2/12/19, 08:23

Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:32



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:33



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:34



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:36



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:37



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:38



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:41



Building 1 South

South west Fire stairs level 3 to exit
2 December 2019 at 08:23:45



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:24:31



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:24:36



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:24:39



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:24:51



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:01



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:06



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:07




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:08



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:09



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:10



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:11



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:12



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:13



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:14




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:18



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:26



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:31




Building 1 South

Basement room CO.247 void and boiler room
 2 December 2019 at 08:25:32



Building 1 South

Basement room CO.247 void and boiler room
 2 December 2019 at 08:25:33



Building 1 South

Basement room CO.247 void and boiler room
 2 December 2019 at 08:25:52



Building 1 South

Basement room CO.247 void and boiler room
 2 December 2019 at 08:25:53




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:55



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:25:56




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:00



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:01



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:14



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:24

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:19



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:34



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:42




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:49




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:54



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:56



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:26:57



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:01



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:02



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:51




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:52

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:54



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:55

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:58



2/12/19, 08:27

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:27:59



2/12/19, 08:28

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:28:00



2/12/19, 08:28

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:28:02



2/12/19, 08:28

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:28:04



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:28:07



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:02



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:03



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:11



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:13

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:25



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:33

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:35



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:42



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:47



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:48



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:53



2/12/19, 08:29

2/12/19, 08:30

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:29:55

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:01



2/12/19, 08:30

2/12/19, 08:30

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:06

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:08



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:13



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:15



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:16



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:19



2/12/19, 08:30

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:21



2/12/19, 08:30

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:23



2/12/19, 08:30

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:24



2/12/19, 08:30

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:26



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:30



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:34



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:35



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:41




Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:42

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:50



Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:51

Building 1 South

Basement room CO.247 void and boiler room
2 December 2019 at 08:30:58



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 06:58:43



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 06:58:45



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 06:58:52




Building 1 Centre

West facade poor state of repair
 2 December 2019 at 06:58:54



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:58:56



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:04



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:07



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:10



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:13



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:18


Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:16



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:19



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:26

Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:35




Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:36

Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:37



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:39



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:40



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:47

Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:49



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:50

Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:51



Building 1 Centre

West facade poor state of repair
2 December 2019 at 06:59:54



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:00



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:02



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:07



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:09



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:11



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:13



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:15



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:17



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:18



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:28



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:30



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:32



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:34




Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:34



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:37



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:38



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:40



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:45



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:50



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:50



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:55



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:00:59



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:01:07

Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:01:00



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:01:09



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:01:23

Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:01:30



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:01:36

Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:01:41



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:01:52



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:01:53




Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:01:56



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:02:04



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:02:09


Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:02:10



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:02:11



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:02:18



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:02:19



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:02:22



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:02:29



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:02:51



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:02:52



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:02:58



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:03:08



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:03:17




Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:03:18



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:03:26



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:03:27



Building 1 Centre

West facade poor state of repair
 2 December 2019 at 07:03:34



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:36

Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:37



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:41



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:51



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:52



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:53



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:03:59




Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:04:07



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:04:12



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:04:13



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:04:33



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:04:44



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:05:03



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:05:05



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:05:06



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:05:12



Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:05:15




Building 1 Centre

West facade poor state of repair
2 December 2019 at 07:05:24

This survey and accompanying photographs is intended to present, as reasonable as possible, a record of the condition, by visible inspection only, of the aforementioned building.

James Townsend Dilapidation Surveys Pty. Ltd. disclaim all responsibility for any loss howsoever occasioned by any error in, or omission from, this report.

A handwritten signature in black ink, appearing to read 'James Townsend', is written over a horizontal dotted line.

for James Townsend Dilapidation Surveys Pty. Ltd.