

**Elizabeth Street**

**Goulburn Street.**

**Campbell Street**

**Liverpool**

# James Townsend Dilapidation Surveys Pty. Ltd.

42 Corymbia Circuit, Oxford Falls. N.S.W. 2100

ABN 84 066 436 780

[jamestownsend@tpg.com.au](mailto:jamestownsend@tpg.com.au)

Mobile 0418 965 852

## **DILAPIDATION SURVEY REPORT**

**CONTRACTOR:** Lend Lease Pty Limited

**CONTRACT SITE:** Liverpool Hospital

**DATE OF SURVEY:** 20th August 2021

**ROAD SURVEYED:** Elizabeth Street Liverpool

Road surface, kerb, gutter, footpath & assets  
abutting site from ED to Goulburn Street.

Goulburn Street Liverpool.

Road surface, kerb, gutter, footpath & assets  
abutting site from Elizabeth St to Campbell Street.

Campbell Street Liverpool.

Road surface, kerb, gutter, footpath & assets  
abutting site from Elizabeth St to High School.

All areas are in a dilapidated state of repair due to heavy vehicles, high  
traffic volumes, previous works & lack of maintenance by council.



**Elizabeth Street Liverpool.**

20 August 2021 at 08:27:10



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:27:13



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:27:14



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:27:15



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:15



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:16



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:18



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:19





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:19



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:20



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:21



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:22



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:23



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:24



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:24



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:26



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:26



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:27



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:28



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:28





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:29

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:31



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:32

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:32



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:33



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:35



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:35



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:36



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:37



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:37



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:38



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:39





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:39



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:41



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:42



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:42





### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:43



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:44



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:45



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:46



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:46



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:54

### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.


20 August 2021 at 08:27:47



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:57



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:27:57



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:00



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:00



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:01





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:28:02



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:28:02




**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:28:03



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:28:04



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:05



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:06



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:06



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:07



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.


20 August 2021 at 08:28:08



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:08



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:09



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:10





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:10



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:11



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:12



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:12





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:13



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:14



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:14



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:18



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:26



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:28



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:28



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:29





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:30



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:30



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:31



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:32



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:33



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:35



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:36

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:36





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:39



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:39



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:40

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:40



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:43

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:43





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:44



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:45



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:46




**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:46





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:47



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:48



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:49



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:49



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:51



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:52



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:54



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:54



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:57

### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:57



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:28:58

### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:06





### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:07



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:09



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:08



### **Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:25



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:36



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:38



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:39



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:43



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:51



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:53



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:54

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:29:55



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:01

**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:02





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:03



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:08



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:09



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:10



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:15



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:16



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:21



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:22



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:30:23



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:30:26



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:30:27



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:30:29





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:30



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:31



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:33



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:34



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:35



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:36



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:38



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:39



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.


20 August 2021 at 08:30:41



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:42



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:43





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:44



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:45



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:47



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:30:52



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:19



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:20



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:21



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:22



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:22



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:27



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:28



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:29





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:29



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:30



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:31



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:32



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:32



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:34



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:35



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:36





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:37



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:38



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:39





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:40



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:41



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:42



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:43



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:43



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:45



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:45



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:46





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:47



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:48



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:49



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:49





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:50



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:51



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:52



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.  
20 August 2021 at 08:31:52



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:53



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:54



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:55



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:56





**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:31:59



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:00



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:02



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:02





### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:03



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:04



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:06



### Elizabeth Street Liverpool.

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:07



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:07



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:09



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:09



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:10



**Elizabeth Street Liverpool.**

Road surface & assets from ED/College St. west to Goulburn St. Poor state of repair, from previous works, buses & lack of maintenance.

20 August 2021 at 08:32:11



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:33



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:34



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:35





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:35



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:36



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:37



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:38



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:38



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:39



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:40



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:41





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:41



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:42



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:43



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:44





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:44



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:45



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:46



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:47



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:48



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:48



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:49



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:50





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:52



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:53



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:54



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:55





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:55



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:13

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:33:56



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:14



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:14



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:15



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:16



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:17





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:18

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:18



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:19

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:20





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:21



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:22



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:23



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:24



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:27



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:28



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:29



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:30





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:30



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:31



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:32



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:33





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:34

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:35



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:35

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:36



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:37



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:38



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:39



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:39






### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:40



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:41



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:41



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:43





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:44



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:45



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:46



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:47



### **Elizabeth Street Liverpool.**


North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:47

### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:49



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:50

### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:51





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:52



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:53



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:54



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:55





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:56



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:57



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:59



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:34:59



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:00



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:01



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:02



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:05





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:06



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:07



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:07



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:08





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:09

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:10



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:10

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:11





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:12

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:13



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:14

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:14





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:15



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:16



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:17



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:17



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:18



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:19



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:20



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:20





#### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:22



#### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:23



#### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:24



#### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:25



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:25



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:28



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:29



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:29





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:30



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:31



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:32



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:32



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:33



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:34



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:35



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:36





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:37



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:38



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:39



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:39



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:40



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:41



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:42



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:43





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:43



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:45



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:46



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:47






**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.


20 August 2021 at 08:35:48



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:49



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:50



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:52





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:53

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:54



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:56

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:57



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:58



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:35:59



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:00



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:01





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:02



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:05



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:07



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:08



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:08



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:09



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:11



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:12





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:13



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:19



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:18



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:20



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:20



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:21



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:22



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:24





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:24



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:26

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:25



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:27



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:28



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:30

### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:29



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:31





### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:32



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:32



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:34



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:34



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:35



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:36



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:37



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:37





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:38



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:39



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:40



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:41





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:42



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:43



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:44



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:45





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:46



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:48



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:47



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.  
20 August 2021 at 08:36:49



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:50



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:51



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:51



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:52





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:53

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:54



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:55

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:55



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:56



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:58



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:36:59



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:05





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:06

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:07



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:08

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:09



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:10



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:12

**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:10



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:12





### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:13



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:14



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:15



### **Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:15



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:16



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:17



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:19



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:20





**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:20



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:21



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:22



**Elizabeth Street Liverpool.**

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:23



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:24



### Elizabeth Street Liverpool.

North footpath kerb gutter and assets. ED/College St. west to Goulburn St. Dilapidated state of repair, lack of maintenance, tree root damage at Goulburn St.

20 August 2021 at 08:37:25



### Goulburn Street Liverpool.

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:15



### Goulburn Street Liverpool.

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:25





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:25



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:26



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:27



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:28



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:28



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:31



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:32



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:33





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:38:34



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:38:35



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:38:36



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:38:37



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:40



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:40



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:41





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:42



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:43



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:44



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:44



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:45



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:46



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:47



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:48





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:49



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:50



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:51



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:52



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:52



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:53



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:54



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:55





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:56



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:56



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:58



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:58



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:38:59



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:39:00



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:01



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:02





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:03

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:04



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:05

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:05



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:06



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:07



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:08



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:09





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:09

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:10



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:11

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:12



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:13



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:13



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:15



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:16





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:17



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:18



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:19



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:20



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:21



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:22



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:22



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:24





### Goulburn Street Liverpool.

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:25



### Goulburn Street Liverpool.

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:25



### Goulburn Street Liverpool.

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:26



### Goulburn Street Liverpool.

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:31



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:32



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:33



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:34



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:34





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:35



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:36



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:37



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:39



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:40



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:41



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:41





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:48



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:49



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:50



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:51



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:52



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:53



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:54



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:39:55





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:55



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:56



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:57



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:58



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:39:59



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:00



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:01




**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:02





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:40:03



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:40:04



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:05



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:05



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:06



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:07



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:08



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:09





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:10



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:11



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:12



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:13



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:14



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:15



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:15



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:16





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:17



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:18



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:19



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:20



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:21



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:22



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:23



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:24





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:24



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:25



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:26



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:27



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:28



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:29



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:29



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:30





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:31



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:33



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:34



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:35



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:36



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:40:37



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:39





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:39



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:47



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:41



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:40:48



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:03



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:03



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:04



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:05





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:06



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:07



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:08



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:09



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:10



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:11



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:12



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:13





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:14

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:15



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:16

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:17



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:18

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:19



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:20

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:20





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:21

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:22



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:23

**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:23



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:24



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:25



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:26



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:30





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:31



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:32



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:37



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:40



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:41



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:42





### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:43



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:45

### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:44



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:46



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:47



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:47



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:48



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:41:49





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:50



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:54



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:54



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:55



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:56



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:57



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:58



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:41:59





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:00



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:01



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:02



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:03



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:03



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:04



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:05




**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:07





### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:08



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:10

### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:09



### **Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:11



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:12



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:12



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:14



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:14





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:15



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:17



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:17



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:18



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:20



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:21



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:21



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:22





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:23



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:25



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:26



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:26



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:27



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:28



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:29



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:30





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:30



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:31



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:32



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:33



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:34



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:34



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:35



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:36





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:37



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:38



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:39



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:40



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:41



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:42



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:43





**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:43



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:44



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:45



**Goulburn Street Liverpool.**

East footpath from Elizabeth St. north to entrance S driveway Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:42:46



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:20



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:20



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:21



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:25





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:25



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:26



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:27



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:28



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:45:29



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:45:29



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:45:30



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:45:31





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:45:32



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:33



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:34



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:35



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:36



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:37



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:38



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:38





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:39



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:41



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:42



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:44



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:45



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:46



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:46



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:48





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:48



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:49



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:50



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:51



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 08:45:52

**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 08:45:53



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 08:45:54

**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 08:45:54





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:56



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:56



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:57



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:58



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:45:59



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:00



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:00



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:01





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:02



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:03



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:04



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:04



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:05



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:06



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:07



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:08





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:09



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:09



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:10



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:11



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:11



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:13



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:13



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:14





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:15



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:16



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:17



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:18



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:20



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:20



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:22



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:22





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:23



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:24



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:25



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:26



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:27



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:28



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:28



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:29





#### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:30

#### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:31



#### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:31

#### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:32



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:33



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:46:34



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:34



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:35





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:36



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:37



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:37



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:38



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:39



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:41



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:42



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:42





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:43



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:45



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:46



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:47



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:48



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:48



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:49



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:50





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:51



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:52



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:46:53



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:54



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:46:54



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:46:55



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:56



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:46:57





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:58



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:59




**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:46:59



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:00



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:01



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:02



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:04



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:05





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:06

**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:06



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:07

**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:47:08



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:09



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:10



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:10



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:11





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:12



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:13



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:14



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:14



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:15



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:16



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:17



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:18





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:18



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:19



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:20



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:21



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:22



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:22



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:23



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:24






**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:25



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:26



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:27



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:28



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:28



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:29



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:30



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:31





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:32



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:33



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:33



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:34



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:47:35



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:36



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:37



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:38





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:38



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:39



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:40



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:41



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:42

**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:42



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:43

**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:44





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:45



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:46



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:47



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:48



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:48



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:49



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:50



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:51





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:52



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:53



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:54



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:55



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:56



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:57



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:58



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:47:59





**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:47:59



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:48:00



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:48:01



**Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:48:02



### **Goulburn Street Liverpool.**

East footpath kerb gutter and asset from entrance S dock to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:48:02



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:35



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:08



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:35





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:36



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:37



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:45



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:46



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:46



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:47



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:50



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:51





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:52



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:53



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:53



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:54



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:55



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:56



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:56



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:52:57





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:00



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:02



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:03



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:04



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:04



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:06



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:07



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:07





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:08



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:10



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:11



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:11



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:12



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:13



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:14



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:15





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:15



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:16



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:17



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:18



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:21



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:22



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:23



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:24





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:24



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:25



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:26



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:27



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:28



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:29



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:29



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:30





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:33



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:34



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:35



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:36



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:37



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:38



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:39



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:40





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:41



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:42



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:42



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:43



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:44



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:45



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:46



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:47





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:48



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:49



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:50



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:50



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:51



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:52



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:53



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:55





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:55



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:56



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:57



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:53:58



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:53:58



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:53:59



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:02



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:03





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:04



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:06



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:07



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:07



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:09



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:10



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:15



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:16





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:17



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:20



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:54:21



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:22



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:24



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:25



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:26



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:30





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:31



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:32



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:36



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:37



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:38



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:38



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:40



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:41





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:42



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:43



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:46



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:46



### Goulburn Street Liverpool.

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:47



### Goulburn Street Liverpool.

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:48



### Goulburn Street Liverpool.

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:49



### Goulburn Street Liverpool.

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:54:50





### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:54:51



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:05



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:06



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:06



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:07



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:08



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:11



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:11






**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:55:12



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:55:13



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:14



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:14



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:18



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:19



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:20



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:21






**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:21



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:22



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:55:23



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:24



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:55:25



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:26



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:27



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:28






**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:29



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:31



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:32



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:33



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:34

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:36



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:38

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:39






**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:40



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:41



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:42



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:43



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:43



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:55:44



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:45



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:45





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:46



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:47



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:48



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:48



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:49



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:50



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:51



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:52





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:53

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:53



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:56

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:55:57



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:03



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:03



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:04



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:09





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:10



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:10



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:15



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:15



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:56:16



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:18



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:18




### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:19





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:21

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:21



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:22

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:23



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:56:23

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:56:24



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:56:25

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:56:26





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:27



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:28



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:28



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:29



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:30



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:31



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:32



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:32





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:33



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:35

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:34



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:36



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:37



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:38



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:38



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:39





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:40

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:41



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:41

**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:48



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:49



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:50



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:51



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:52





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:53



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:56:53



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:54



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:55



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:56



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:56



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:57



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:58





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:56:59



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:00



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:01



**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:06



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:07



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:08



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:09



### **Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:10





**Goulburn Street Liverpool.**

Road surface & assets from Elizabeth St. to S dock driveway. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:10



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:59



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:57:59



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:00



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:01



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:01



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:02



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:03





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:04



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:04



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:05



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:06



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:07

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:08



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:11

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:12





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:13



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:14



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:15



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:15



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:16



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:17



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:18



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:19





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:19



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:20



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:21



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:22



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:58:22



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:23



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:24



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:25





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:26



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:26



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:27



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:28



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:28



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:29



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:30



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:31





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:58:32



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:58:33



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:58:34



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 08:58:35



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:36



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:37



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:38



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:38





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:39



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:40



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:42



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:43



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:43



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:44



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:45



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:46





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:46



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:47



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:48



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:49



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:50



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:50



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:51



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:52





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:53



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:53



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:55



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:56



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:57

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:58



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:58:59

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:02






**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:59:03



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:04



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:05



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:05



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 08:59:06



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:07



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:08



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:09





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:10

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:11



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:11

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:12



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:13



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:14



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:14



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:15





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:16

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:19



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:20

**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:20



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:21



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:22



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:23



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:23





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:24



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:25



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:28



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:29



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:30



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:31



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:32



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:32





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:33



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:35



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:36



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:37



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:37



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:38



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:39



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:40





### **Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:43



### **Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:44



### **Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:45



### **Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:46



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:47



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:47



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:48



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:49





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:50



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:51



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:51



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:55



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:56



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:56



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:57



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 08:59:59





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:00



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:00



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:01



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:02



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:03



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:04



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:05



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:08





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:09



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:10



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:11



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:12



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:12



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:13



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:14



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:15





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:16



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:16



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:17



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:18



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:19



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:20



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:22



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:00:23





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:23



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:24



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:25



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:26



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:27



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:28



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:29



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:29





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:30



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:31



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:38



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:38



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:39



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:40



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:44



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:44





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:45



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:46



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:00:46



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:48



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:52



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:53



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:54



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:55





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:55



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:57



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:58



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:58



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:00:59



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:05



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:06



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:06





**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:07



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:08



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:09



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:10



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:10



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:11



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:12



**Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:13





### **Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:01:13



### **Goulburn Street Liverpool.**

Road surface & assets from S dock driveway to Campbell St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:02



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:16



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:21



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:22



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:22



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:23



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:25





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:25



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:26



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:27



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:28



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:29



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:29



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:30



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:30





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:31



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:32:32



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:32



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:33



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:34



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:35



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:35



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:32:37





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:38

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:39



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:39

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:40



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:41



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:42



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:42



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:44





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:44



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:45



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:46



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:46



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:47



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:48



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:49



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:49





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:50



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:51



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:52



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:54



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:54



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:55



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:56



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:56





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:57



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:58



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:58



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:32:59



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:00



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:01



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:01



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:03





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:03



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:04



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:05



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:06



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:07



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:07



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:08



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:09





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:10



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:11



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:11



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:12



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:13



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:14



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:15



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:16





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:18



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:18



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:19



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:20



#### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:21



#### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:24



#### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:23



#### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:25






**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:25



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:26



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:28



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:28



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:29



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:33:31



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:31



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:32





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:34



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:33:34



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:35



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:36



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:37



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:38



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:39



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:33:40





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:33:40



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:33:45



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:33:46



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:33:47



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:47



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:48



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:49



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:50





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:50



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:51



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:52



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:53



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:56

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:33:57



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:34:02

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:34:03





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:34:03

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:34:06



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:34:07

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from Goulburn to pathology exit. Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:34:08



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:18



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:19



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:20



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:22





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:22



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:25



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:25



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:35:27



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:28



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:28



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:29



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:30





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:31



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:31



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:32




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:34




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:35



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:36



**Campbell Street Liverpool.**



South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:36



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:37





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:38

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:39



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:40

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:40




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:41




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:42



**Campbell Street Liverpool.**


South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:44



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:44





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:45




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:45



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:46



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:47



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:47



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:48



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:49



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:50





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:51



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:51



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:52



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:53




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:54



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:55



**Campbell Street Liverpool.**


South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:55



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:56





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:57



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:58




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:58



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:35:59




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:00



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:01



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:02



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:02





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:03

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:04



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:05

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:06



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:07

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:08



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:09

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:09





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:10



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:11




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:12



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:12



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:13

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:14



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:15

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:15





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:16



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:17



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:17



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:18



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:19

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:20



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:20

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:21





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:22

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:23



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:24

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:25



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:25



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:26



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:27



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:28





### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:28

### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:29



### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:30

### **Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:31



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:32



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:32



**Campbell Street Liverpool.**


South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:33



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:34





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:35

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:35




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:36

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:37




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:38



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:39



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:40



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:40





**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:42




**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:43



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:44



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road  
20 August 2021 at 09:36:45



**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:46

**Campbell Street Liverpool.**

South footpath kerb gutter and asset from pathology east to school carpark. Poor state of repair, from previous works & lack of maintenance. Road

20 August 2021 at 09:36:46



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:37:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St. Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:37:59





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:00



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:00



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:02



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:38:03



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:03



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:04



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:05



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:06





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:38:06



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:07



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:08



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:23



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:25



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:26





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:38:26



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:38:27



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:38:28



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:38:29



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:29



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:30



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:31



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:31





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:32



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:33



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:33



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:34



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:36



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:37



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:38





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:39



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:40



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:40



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:41



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:46



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:47





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:48



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:48



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:50



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:50



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:51



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:52



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:54



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:54





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:55



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:57



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:38:59



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:00



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:02



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:03





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:04



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:05



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:05



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:06



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:39:07



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:39:08



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:39:08



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:39:09





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:10



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:11



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:12



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:13



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:13



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:14



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:15



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:16





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:20



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:21



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:22



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:23



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:25



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:26





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:27

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:27



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:28

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:29



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:29



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:30



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:31



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:32





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:33



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:33



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:36



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:37



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:38



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:39





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:40

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:44



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:47

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:48



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:48



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:49



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:51



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:53





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:53



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:54



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:55



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:55



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:56



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:57



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:39:59





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:00



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:01



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:02



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:03



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:03



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:04



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:05




**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:06





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:06



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:07



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:09



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:09



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:10



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:12



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:12



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:13





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 09:40:15



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 09:40:16



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 09:40:17



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
 Poor state of repair, from previous works & lack of maintenance.  
 20 August 2021 at 09:40:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:40:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:19



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:21



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:22





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:23



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:40:25



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:26



### **Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:40:27



### **Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:28



### **Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:30



### **Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:33





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:34



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:34



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:36



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:39

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:40



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:41

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:42





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:43



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:44



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:45



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:46



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:40:46



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:47



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:48





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:40:49

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:40:51



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:40:51

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:40:52



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:53



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:54



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:56



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:57





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:59



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:40:59



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:00



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:01



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:06



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:07



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:07





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:08



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:09



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:10



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:11



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:11



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:12



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:13



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:14






**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:15



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:16



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:17



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:19



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:20



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:21





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:21

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:22



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:23

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:25



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:26



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:27



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:33





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:41:34

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:41:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:41:36

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:41:37



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:38

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:38



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:39

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:41





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:42

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:43

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:44



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:45



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:47



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:47



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:48





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:49



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:49



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:50



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:51



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:52

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:53



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:54

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:55





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:56



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:56



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:57



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:41:59



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:00



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:01



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:02





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:42:02



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:42:05



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:42:05



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.  
20 August 2021 at 09:42:06



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:42:08



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:10



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:11



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:12





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:12



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:13



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:14



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:15



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:16



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:19





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:20



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:22



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:23



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:24



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:25



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:26



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:27





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:28



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:29



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:33



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:34



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:37



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:37



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:38





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.


20 August 2021 at 09:42:39



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:40



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:40



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:43



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:44



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:44





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:46



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:47



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:47



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:49



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of  
maintenance.

20 August 2021 at 09:42:49



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of  
maintenance.

20 August 2021 at 09:42:50



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of  
maintenance.

20 August 2021 at 09:42:53



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of  
maintenance.

20 August 2021 at 09:42:54





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:55



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:42:56



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:02



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:03



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:07



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:08



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:09



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:10





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:11



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:18



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:19



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:20



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:20



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:21



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:22



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:26





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:27



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:27



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:28



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:34



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:35



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:36



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:37



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:38





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:39



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:41



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:42



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:43



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:44



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:45



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:45



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:46





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:47



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:48



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:49



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:50



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:51



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:51



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:52



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:53





**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:54



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:55



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:56



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:57



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:58



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:43:59



**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of maintenance.

20 August 2021 at 09:44:00





**Campbell Street Liverpool.**


Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of  
maintenance.  
20 August 2021 at 09:44:01

**Campbell Street Liverpool.**

Road surface & assets from school west to Goulburn St.  
Poor state of repair, from previous works & lack of  
maintenance.  
20 August 2021 at 09:44:02

**This survey and accompanying photographs is intended to present, as reasonable as possible, a record of the condition, by visible inspection only, of the aforementioned building.**

**James Townsend Dilapidation Surveys Pty. Ltd. disclaim all responsibility for any loss howsoever occasioned by any error in, or omission from, this report.**

A handwritten signature in black ink, appearing to read 'James Townsend', is written over a horizontal dotted line.

**for James Townsend Dilapidation Surveys Pty. Ltd.**