



Figure: 0082

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0083

Longitudinal cracking
in the roadway on
Kanadah Road.



Figure: 0084

Bleeding/flushing
in the roadway on
Kanadah Road.

Figure: 0085

**PINNACLES ROAD,
BROKEN HILL**

Alligator cracking
in the roadway on
Pinnacles Road.



Figure: 0086

Alligator cracking
in the roadway on
Pinnacles Road.



Figure: 0087

Alligator cracking
in the roadway on
Pinnacles Road.





Figure: 0088

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0089

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0090

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0091

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0092

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0093

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0094

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0095

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0096

Spalling in the roadway on Pinnacles Road.



Figure: 0097

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0098

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0099

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0100

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0101

Chipping in the kerbs on Pinnacles Road.



Figure: 0102

Chipping in the kerbs on Pinnacles Road.



Figure: 0103

Chipping in the kerbs on Pinnacles Road.



Figure: 0104

Longitudinal cracking in the roadway on Pinnacles Road.



Figure: 0105

Asphalt depression in the roadway on Pinnacles Road.



Figure: 0106

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0107

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0108

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0109

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0110

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0111

Transverse cracking in the roadway on Pinnacles Road.

Figure: 0112

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0113

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0114

Alligator cracking in the roadway on Pinnacles Road.





Figure: 0115

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0116

Alligator cracking in the roadway on Pinnacles Road.



Figure: 0117

KANADAH ROAD, BROKEN HILL

Transverse cracking in the roadway on Kanadah Road.



Figure: 0118

Longitudinal cracking
in the roadway on
Kanadah Road.



Figure: 0119

Longitudinal cracking
in the roadway on
Kanadah Road.



Figure: 0120

Longitudinal cracking
in the roadway on
Kanadah Road.



Figure: 0121

Transverse cracking in the roadway on Kanadah Road.



Figure: 0122

Pot hole in the roadway on Kanadah Road.



Figure: 0123

Transverse cracking in the roadway on Kanadah Road.



Figure: 0124

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0125

Alligator cracking
in the roadway on
Kanadah Road.



Figure: 0126

Alligator cracking
in the roadway on
Kanadah Road.



Figure: 0127

Alligator cracking
in the roadway on
Kanadah Road.



Figure: 0128

Alligator cracking
in the roadway on
Kanadah Road.



Figure: 0129

Alligator cracking
in the roadway on
Kanadah Road.



Figure: 0130

Longitudinal cracking in the roadway on Kanadah Road.



Figure: 0131

Alligator cracking in the roadway on Kanadah Road.



Figure: 0132

Alligator cracking in the roadway on Kanadah Road.



Figure: 0133

Failed patching in the roadway on Kanadah Road.



Figure: 0134

Transverse cracking in the roadway on Kanadah Road.



Figure: 0135

Transverse cracking in the roadway on Kanadah Road.



Figure: 0136

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0137

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0138

Spalling in the
roadway on Kanadah
Road.

Figure: 0139

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0140

Longitudinal cracking
in the roadway on
Kanadah Road.



Figure: 0141

Alligator cracking
in the roadway on
Kanadah Road.





Figure: 0142

Bleeding/flushing
in the roadway on
Kanadah Road.



Figure: 0143

Alligator cracking
in the roadway on
Kanadah Road.



Figure: 0144

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0145

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0146

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0147

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0148

Transverse cracking
in the roadway on
Kanadah Road.



Figure: 0149

Bleeding/flushing
in the roadway on
Kanadah Road.



Figure: 0150

Bleeding/flushing
in the roadway on
Kanadah Road.



Figure: 0151

Bleeding/flushing and alligator cracking in the roadway on Kanadah Road.



Figure: 0152

Transverse cracking in the roadway on Kanadah Road.



Figure: 0153

Transverse cracking in the roadway on Kanadah Road.



Figure: 0154

Alligator cracking in the roadway on Kanadah Road.



Figure: 0155

Alligator cracking in the roadway on Kanadah Road.



Figure: 0156

Alligator cracking in the roadway on Kanadah Road.



Figure: 0157

Video 2 - BARRIER HIGHWAY, BROKEN HILL

Bleeding/flushing in the roadway on Barrier Highway.



Figure: 0158

Bleeding/flushing in the roadway on Barrier Highway.



Figure: 0159

Transverse cracking in the roadway on Barrier Highway.



Figure: 0160

Transverse cracking in the roadway on Barrier Highway.



Figure: 0161

Alligator cracking in the roadway on Barrier Highway.



Figure: 0162

Alligator cracking in the roadway on Barrier Highway.



Figure: 0163

Alligator cracking in the roadway on Barrier Highway.



Figure: 0164

Longitudinal cracking in the roadway on Barrier Highway.



Figure: 0165

Alligator cracking in the roadway on Barrier Highway.



Figure: 0166

Alligator cracking in the roadway on Barrier Highway.



Figure: 0167

Longitudinal cracking in the roadway on Barrier Highway.



Figure: 0168

Longitudinal cracking in the roadway on Barrier Highway.



Figure: 0169

Alligator cracking in the roadway on Barrier Highway.



Figure: 0170

Alligator cracking in the roadway on Barrier Highway.



Figure: 0171

Alligator cracking in the roadway on Barrier Highway.



Figure: 0172

Alligator cracking in the roadway on Barrier Highway.



Figure: 0173

Alligator cracking in the roadway on Barrier Highway.



Figure: 0174

Alligator cracking in the roadway on Barrier Highway.



Figure: 0175

Alligator cracking in the roadway on Barrier Highway.



Figure: 0176

Alligator cracking in the roadway on Barrier Highway.



Figure: 0177

Alligator cracking in the roadway on Barrier Highway.



Figure: 0178

Alligator cracking in the roadway on Barrier Highway.



Figure: 0179

Upheaval in the roadway on Barrier Highway.



Figure: 0180

Alligator cracking in the roadway on Barrier Highway.