


The contractor shall check and verify all work on site (including work by others) before commencing the landscape installation. Any discrepancies are to be reported to the Project Manager or Landscape Architect prior to commencing work. Do not scale this drawing. Any required dimensions not shown shall be referred to the Landscape Architect for confirmation.

Issue	Revision Description	Drawn	Check	Date
O	Architectural Coordination	LH	NM	19.06.2024
N	Architectural Coordination	LH	NM	13.06.2024
M	Architectural Coordination	LH	NM	20.03.2024
L	Architectural Coordination	LW	NM	15.11.2023
K	Issue Updated	LW	NM	15.05.2023
J	Tree Amendment	LW	NM	27.04.2023
I	Architectural Coordination	LH	NM	05.04.2023
H	Architectural Coordination	LH	NM	20.03.2023
G	Update DA Package	SJ	NM	02.03.2023
F	Architectural Coordination	LW	NM	12.08.2022
E	Tree Retention Updated	LW	NM	06.07.2022
D	Architectural Coordination	LW	NM	04.07.2022
C	Architectural Coordination	LH	NM	01.07.2022
B	Architectural Coordination	LW	NM	29.06.2022
A	For Review	CK	NM	20.06.2022

Legend refer to 001



Key Plan

Client



Project

242-244 Beecroft Road, Epping

SITE IMAGE

Level 1, 3-5 Baptist Street
Redfern NSW 2016
Australia

Tel: (61 2) 8332 5600
Fax: (61 2) 9698 2877
www.siteimage.com.au

Site Image (NSW) Pty Ltd
ABN 44 801 262 380



Landscape Architects


DEVELOPMENT APPLICATION

Drawing Name

Landscape Plan

Ground Floor Masterplan

Scale 1:250 @ A1



Job Number

Drawing Number Issue

SS21-4819

002 O

NOT FOR CONSTRUCTION