

# Appendix F

## POEO Public Register Search

**Material Science Building Development  
University of New South Wales, Union Rd Kensington  
Supplementary Environmental Assessment**



**You are here:** [Home](#) > [Environment protection licences](#) > [POEO Public Register](#) > [Search for licences, applications and notices](#)

## Search results

Your search for: **General Search** with the following criteria

**Suburb** - Kensington

returned 3 results

[Export to excel](#)

1 of 1 Pages

[Search Again](#)

| <u>Number</u>           | <u>Name</u>                      | <u>Location</u>                                                           | <u>Type</u>         | <u>Status</u> | <u>Issued date</u> |
|-------------------------|----------------------------------|---------------------------------------------------------------------------|---------------------|---------------|--------------------|
| <a href="#">11415</a>   | DENWIL PTY LIMITED               | Level 1, 91 Anzac Parade, KENSINGTON, NSW 2033                            | POEO licence        | Surrendered   | 16 Oct 2001        |
| <a href="#">1038443</a> | DENWIL PTY LIMITED               | Level 1, 91 Anzac Parade, KENSINGTON, NSW 2033                            | S 58 Licence Issued |               | 07 Jul 2004        |
| <a href="#">5906</a>    | LEIGHTON CONTRACTORS PTY LIMITED | FROM CAHILL EXPRESSWAY, WOOLLOOMOOLOO TO LINK ROAD,, KENSINGTON, NSW 2033 | POEO licence        | Surrendered   | 30 Mar 2000        |

20 February 2013



Environment  
& Heritage



You are here: [Home](#) > [Environment protection licences](#) > [POEO Public Register](#) > [Search for licences, applications and notices](#)

## Licence summary

[Search Again](#)
[Return to Previous Page](#)

### Summary Licence No: 5906

[View this licence](#) (PDF document 158 kb)

**Licence holder:** LEIGHTON CONTRACTORS PTY LIMITED

**Premises:** EASTERN DISTRIBUTOR PROJECT  
FROM CAHILL EXPRESSWAY, WOOLLOOMOOLOO TO LINK ROAD,,  
KENSINGTON, NSW, 2033  
**LGA:** SYDNEY **Catchment:** Sydney Coast & Georges River

**Administrative fee:** \$5,500.00

**Licence status:** Surrendered

**Activity type:** Road construction

**Licence review:** Complete date 02 Apr 2002  
Due date 01 Jul 2002

### Applications

| <u>Number</u>           | <u>Application type</u>     | <u>Current status</u> | <u>Date received</u> |
|-------------------------|-----------------------------|-----------------------|----------------------|
| <a href="#">1013246</a> | s.80 Surrender of a Licence | Issued                | 15 Nov 2000          |

### Notices

| <u>Number</u>           | <u>Issue date</u> | <u>Notice type</u>          |
|-------------------------|-------------------|-----------------------------|
| <a href="#">1013246</a> | 17 Jan 2002       | s.80 Surrender of a Licence |

### Annual Returns

| <u>Start date</u> | <u>End date</u> | <u>Date received</u> | <u>Non-compliance</u> | <u>LBL data</u> |
|-------------------|-----------------|----------------------|-----------------------|-----------------|
| 27-Aug-2001       | 11-Feb-2002     | 20-May-2002          | No                    | Not available   |
| 27-Aug-2000       | 26-Aug-2001     | 20-May-2002          | No                    | Not available   |
| 27-Aug-1999       | 26-Aug-2000     | 13-Sep-2000          | No                    | Not available   |



You are here: [Home](#) > [Environment protection licences](#) > [POEO Public Register](#) > [Search for licences, applications and notices](#)

## Licence summary

[Search Again](#)
[Return to Previous Page](#)

### Summary Licence No: 11415

[View this licence](#) (PDF document 195 kb)

**Licence holder:** DENWIL PTY LIMITED  
**Trading as:** ACCORD DIAGNOSTICS  
**Premises:** Accord Diagnostics  
 Level 1, 91 Anzac Parade, KENSINGTON, NSW, 2033  
**LGA:** RANDWICK **Catchment:** Sydney Coast & Georges River  
**Administrative fee:** \$760.00  
**Licence status:** Surrendered  
**Activity type:** Hazardous, Industrial or Group A Waste Generation or Storage  
**Licence review:** Complete date 07 Jul 2004  
 Due date 07 Jul 2007

### Applications

| <u>Number</u>           | <u>Application type</u>     | <u>Current status</u> | <u>Date received</u> |
|-------------------------|-----------------------------|-----------------------|----------------------|
| <a href="#">1050717</a> | s.80 Surrender of a Licence | Issued                | 05 Jul 2005          |

### Notices

| <u>Number</u>           | <u>Issue date</u> | <u>Notice type</u>          |
|-------------------------|-------------------|-----------------------------|
| <a href="#">1038443</a> | 07 Jul 2004       | S 58 Licence Variation      |
| <a href="#">1050717</a> | 16 Aug 2005       | s.80 Surrender of a Licence |

### Annual Returns

| <u>Start date</u> | <u>End date</u> | <u>Date received</u> | <u>Non-compliance</u> | <u>LBL data</u> |
|-------------------|-----------------|----------------------|-----------------------|-----------------|
| 16-Oct-2004       | 09-Sep-2005     |                      |                       |                 |
| 16-Oct-2003       | 15-Oct-2004     | 28-Oct-2004          | No                    | Not available   |
| 16-Oct-2002       | 15-Oct-2003     | 02-Dec-2003          | No                    | Not available   |
| 16-Oct-2001       | 15-Oct-2002     | 12-Dec-2002          | No                    | Not available   |

[Download Annual Return Form](#)

Environment  
& Heritage

**You are here:** [Home](#) > [Environment protection licences](#) > [POEO Public Register](#) > [Search for licences, applications and notices](#)

## Notice summary

[Search Again](#)[Return to Previous Page](#)

### Summary of Notice No: 1038443

[View report](#) (PDF document 930 kb)

**Organisation:** DENWIL PTY LIMITED  
**Location:** Accord Diagnostics  
Level 1, 91 Anzac Parade, KENSINGTON, NSW, 2033  
**LGA:** RANDWICK  
**Catchment:** Sydney Coast & Georges River  
**Issue date:** 07 Jul 2004  
**Notice type:** S 58 Licence Variation

### Licence

Number[11415](#)Name

DENWIL PTY LIMITED

Licence status

Surrendered

# Appendix G


## Groundwater Bore Search

**Material Science Building Development  
University of New South Wales, Union Rd Kensington  
Supplementary Environmental Assessment**

## Bore Search

Map created with NSW Natural Resource Atlas - <http://www.nratlas.nsw.gov.au>

Friday, March 01, 2013



0

1 Km

### Legend

Symbol

Layer

Custodian



Cities and large towns  
renderImage: Cannot build image from features



Populated places  
renderImage: Cannot build image from features



Towns



Groundwater Bores



Catchment Management Authority  
boundaries



Major rivers



## Topographic base map

Copyright © 2013 New South Wales Government. Map has been compiled from various sources and may contain errors or omissions. No representation is made as to its accuracy or suitability.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 6, 2013

[Print Report](#)

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111846

### Works Details [\(top\)](#)

|                        |                              |
|------------------------|------------------------------|
| GROUNDWATER NUMBER     | GW111846                     |
| LIC-NUM                | 10BL602843                   |
| AUTHORISED-PURPOSES    | MONITORING BORE              |
| INTENDED-PURPOSES      | MONITORING BORE              |
| WORK-TYPE              | Bore                         |
| WORK-STATUS            | Equipped - bore used for obs |
| CONSTRUCTION-METHOD    | Auger - Solid Flight         |
| OWNER-TYPE             | Local Govt                   |
| COMMENCE-DATE          |                              |
| COMPLETION-DATE        | 2009-08-11                   |
| FINAL-DEPTH (metres)   | 5.60                         |
| DRILLED-DEPTH (metres) | 5.60                         |
| CONTRACTOR-NAME        |                              |
| DRILLER-NAME           |                              |
| PROPERTY               | 7 ELEVEN                     |
| GWMA                   | -                            |
| GW-ZONE                | -                            |
| STANDING-WATER-LEVEL   | 2.95                         |
| SALINITY               |                              |
| YIELD                  |                              |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6245120.00              |
| EASTING          | 336962.00               |

**LATITUDE** 33 55' 18"  
**LONGITUDE** 151 14' 10"  
**GS-MAP**  
**AMG-ZONE** 56  
**COORD-SOURCE**  
**REMARK**

### Form-A [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 3//620777

### Licensed [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 1 83413

### Construction [\(top\)](#)

Negative depths indicate Above Ground Level;H-Hole;P-Pipe;OD-Outside Diameter;  
ID-Inside Diameter;C-Cemented;SL-Slot Length;A-Aperture;GS-Grain Size;Q-Quantity

| HOLE-<br>NO | PIPE-<br>NO | COMPONENT-<br>CODE | COMPONENT-<br>TYPE | DEPTH-<br>FROM<br>(metres) | DEPTH-<br>TO<br>(metres) | OD<br>(mm) | ID<br>(mm) | INTERVAL | DETAIL                                                      |
|-------------|-------------|--------------------|--------------------|----------------------------|--------------------------|------------|------------|----------|-------------------------------------------------------------|
| 1           |             | Hole               | Hole               | 0.00                       | 5.60                     | 150        |            |          | Auger -<br>Solid Flight                                     |
| 1           | 1           | Casing             | PVC Class 18       | 0.00                       | 1.40                     | 60.2       | 56.2       |          | Screwed;<br>Cemented;<br>End cap                            |
| 1           | 1           | Opening            | Slots - Diagonal   | 1.40                       | 4.90                     | 60.2       |            |          | PVC Class<br>18; Casing -<br>Machine<br>Slotted;<br>Screwed |
| 1           |             | Annulus            | Waterworn/Rounded  | 0.50                       | 6.00                     |            |            |          | Graded;<br>GS: 8-<br>16mm                                   |

### Water Bearing Zones [\(top\)](#)

| FROM-<br>DEPTH<br>(metres) | TO-DEPTH<br>(metres) | THICKNESS<br>(metres) | ROCK-<br>CAT-<br>DESC | S-<br>W-L | D-<br>D-<br>L | YIELD | TEST-HOLE-<br>DEPTH<br>(metres) | DURATION | SALINITY |
|----------------------------|----------------------|-----------------------|-----------------------|-----------|---------------|-------|---------------------------------|----------|----------|
| 1.40                       | 4.90                 | 3.50                  |                       | 2.95      |               |       |                                 |          |          |

### Drillers Log [\(top\)](#)

| FROM TO THICKNESS |      |      | DESC                                      | GEO-MATERIAL | COMMENT |
|-------------------|------|------|-------------------------------------------|--------------|---------|
| 0.00              | 0.20 | 0.20 | BITUMEN                                   |              |         |
| 0.20              | 0.50 | 0.30 | FILL,MOIST,BROWN,DENSE,SAND,MINOR ASPHALT |              |         |
| 0.50              | 5.60 | 5.10 | SAND,DENSE,MOIST,ORANGE,BROWN,SANDSTONE   |              |         |

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 6, 2013

[Print Report](#)

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111845

### Works Details [\(top\)](#)

|                        |                              |
|------------------------|------------------------------|
| GROUNDWATER NUMBER     | GW111845                     |
| LIC-NUM                | 10BL602843                   |
| AUTHORISED-PURPOSES    | MONITORING BORE              |
| INTENDED-PURPOSES      | MONITORING BORE              |
| WORK-TYPE              | Bore                         |
| WORK-STATUS            | Equipped - bore used for obs |
| CONSTRUCTION-METHOD    | Auger - Solid Flight         |
| OWNER-TYPE             | Local Govt                   |
| COMMENCE-DATE          |                              |
| COMPLETION-DATE        | 2009-08-11                   |
| FINAL-DEPTH (metres)   | 3.00                         |
| DRILLED-DEPTH (metres) | 3.00                         |
| CONTRACTOR-NAME        |                              |
| DRILLER-NAME           |                              |
| PROPERTY               | 7 ELEVEN                     |
| GWMA                   | -                            |
| GW-ZONE                | -                            |
| STANDING-WATER-LEVEL   | 2.69                         |
| SALINITY               |                              |
| YIELD                  |                              |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6245092.00              |
| EASTING          | 336901.00               |

**LATITUDE** 33 55' 19"  
**LONGITUDE** 151 14' 8"  
**GS-MAP**  
**AMG-ZONE** 56  
**COORD-SOURCE**  
**REMARK**

### Form-A [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** E//346805

### Licensed [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 1 83413

### Construction [\(top\)](#)

Negative depths indicate Above Ground Level;H-Hole;P-Pipe;OD-Outside Diameter;  
ID-Inside Diameter;C-Cemented;SL-Slot Length;A-Aperture;GS-Grain Size;Q-Quantity

| HOLE-<br>NO | PIPE-<br>NO | COMPONENT-<br>CODE | COMPONENT-<br>TYPE | DEPTH-<br>FROM<br>(metres) | DEPTH-<br>TO<br>(metres) | OD<br>(mm) | ID<br>(mm) | INTERVAL | DETAIL                                                      |
|-------------|-------------|--------------------|--------------------|----------------------------|--------------------------|------------|------------|----------|-------------------------------------------------------------|
| 1           |             | Hole               | Hole               | 0.00                       | 3.00                     | 150        |            |          | Auger -<br>Solid Flight                                     |
| 1           | 1           | Casing             | PVC Class 18       | 0.00                       | 1.50                     | 60.2       | 56.2       |          | Cemented;<br>End cap                                        |
| 1           | 1           | Opening            | Slots - Diagonal   | 1.50                       | 3.00                     | 60.2       |            |          | PVC Class<br>18; Casing -<br>Machine<br>Slotted;<br>Screwed |
| 1           |             | Annulus            | Waterworn/Rounded  | 0.50                       | 6.00                     |            |            |          | Graded;<br>GS: 8-<br>16mm                                   |

### Water Bearing Zones [\(top\)](#)

| FROM-<br>DEPTH<br>(metres) | TO-DEPTH<br>(metres) | THICKNESS<br>(metres) | ROCK-<br>CAT-<br>DESC | S-<br>W-L | D-<br>D-<br>L | YIELD | TEST-HOLE-<br>DEPTH<br>(metres) | DURATION | SALINITY |
|----------------------------|----------------------|-----------------------|-----------------------|-----------|---------------|-------|---------------------------------|----------|----------|
| 1.50                       | 3.00                 | 1.50                  |                       | 2.69      |               |       |                                 |          |          |

### Drillers Log [\(top\)](#)

| FROM TO |      |      | THICKNESS | DESC                               | GEO-MATERIAL COMMENT |
|---------|------|------|-----------|------------------------------------|----------------------|
| 0.00    | 0.20 | 0.20 |           | BITUMEN                            |                      |
| 0.20    | 1.00 | 0.80 |           | FILL, MOIST,ORANGE BROWN AND BLACK |                      |
| 1.00    | 3.00 | 2.00 |           | SAND MOIST,PALE,M/DENSE,COARSE     |                      |

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 6, 2013

Print Report

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111844

### Works Details [\(top\)](#)

|                        |                              |
|------------------------|------------------------------|
| GROUNDWATER NUMBER     | GW111844                     |
| LIC-NUM                | 10BL602843                   |
| AUTHORISED-PURPOSES    | MONITORING BORE              |
| INTENDED-PURPOSES      | MONITORING BORE              |
| WORK-TYPE              | Bore                         |
| WORK-STATUS            | Equipped - bore used for obs |
| CONSTRUCTION-METHOD    | Auger - Solid Flight         |
| OWNER-TYPE             | Local Govt                   |
| COMMENCE-DATE          |                              |
| COMPLETION-DATE        | 2009-08-11                   |
| FINAL-DEPTH (metres)   | 4.80                         |
| DRILLED-DEPTH (metres) | 4.80                         |
| CONTRACTOR-NAME        |                              |
| DRILLER-NAME           |                              |
| PROPERTY               | 7 ELEVEN                     |
| GWMA                   | -                            |
| GW-ZONE                | -                            |
| STANDING-WATER-LEVEL   | 2.67                         |
| SALINITY               |                              |
| YIELD                  |                              |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6245077.00              |
| EASTING          | 336993.00               |

**LATITUDE** 33 55' 20"  
**LONGITUDE** 151 14' 12"  
**GS-MAP**  
**AMG-ZONE** 56  
**COORD-SOURCE**  
**REMARK**

### Form-A [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 1//83413

### Licensed [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 1 83413

### Construction [\(top\)](#)

Negative depths indicate Above Ground Level;H-Hole;P-Pipe;OD-Outside Diameter;  
ID-Inside Diameter;C-Cemented;SL-Slot Length;A-Aperture;GS-Grain Size;Q-Quantity

| HOLE-<br>NO | PIPE-<br>NO | COMPONENT-<br>CODE | COMPONENT-<br>TYPE | DEPTH-<br>FROM<br>(metres) | DEPTH-<br>TO<br>(metres) | OD<br>(mm) | ID<br>(mm) | INTERVAL | DETAIL                                                      |
|-------------|-------------|--------------------|--------------------|----------------------------|--------------------------|------------|------------|----------|-------------------------------------------------------------|
| 1           |             | Hole               | Hole               | 0.00                       | 4.80                     | 150        |            |          | Auger -<br>Solid Flight                                     |
| 1           | 1           | Casing             | PVC Class 18       | 0.00                       | 1.80                     | 30.2       | 26.2       |          | Screwed;<br>Cemented;<br>End cap                            |
| 1           | 1           | Opening            | Slots - Diagonal   | 1.80                       | 4.80                     | 60.2       |            |          | PVC Class<br>18; Casing -<br>Machine<br>Slotted;<br>Screwed |
| 1           |             | Annulus            | Waterworn/Rounded  | 0.50                       | 6.00                     |            |            |          | Graded;<br>GS: 8-<br>16mm                                   |

### Water Bearing Zones [\(top\)](#)

| FROM-<br>DEPTH<br>(metres) | TO-DEPTH<br>(metres) | THICKNESS<br>(metres) | ROCK-<br>CAT-<br>DESC | S-<br>W-<br>L | D-<br>D-<br>L | YIELD | TEST-HOLE-<br>DEPTH<br>(metres) | DURATION | SALINITY |
|----------------------------|----------------------|-----------------------|-----------------------|---------------|---------------|-------|---------------------------------|----------|----------|
| 1.80                       | 4.80                 | 3.00                  |                       |               |               | 2.67  |                                 |          |          |

### Drillers Log [\(top\)](#)

| FROM TO |      |      | THICKNESS | DESC                                   | GEO-MATERIAL COMMENT |
|---------|------|------|-----------|----------------------------------------|----------------------|
| 0.00    | 0.15 | 0.15 |           | FILL,MOIST,GREY BROWN,LOOSE,SAND       |                      |
| 0.15    | 3.00 | 2.85 |           | SAND,MEDIUM DENSE,MOIST,GREY,M/GRAINED |                      |
| 3.00    | 4.80 | 1.80 |           | SAND,WET,PALE BROWN,COARSE GRAINED     |                      |

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 6, 2013

Print Report

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111696

### Works Details [\(top\)](#)

|                        |                 |
|------------------------|-----------------|
| GROUNDWATER NUMBER     | GW111696        |
| LIC-NUM                | 10WA113782      |
| AUTHORISED-PURPOSES    | DOMESTIC        |
| INTENDED-PURPOSES      | DOMESTIC        |
| WORK-TYPE              | Bore            |
| WORK-STATUS            | Supply Obtained |
| CONSTRUCTION-METHOD    | Auger           |
| OWNER-TYPE             | Private         |
| COMMENCE-DATE          |                 |
| COMPLETION-DATE        | 2008-10-01      |
| FINAL-DEPTH (metres)   | 22.00           |
| DRILLED-DEPTH (metres) | 22.00           |
| CONTRACTOR-NAME        |                 |
| DRILLER-NAME           |                 |
| PROPERTY               | LYNCH           |
| GWMA                   | -               |
| GW-ZONE                | -               |
| STANDING-WATER-LEVEL   | 16.00           |
| SALINITY               |                 |
| YIELD                  | 1.00            |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6245347.00              |
| EASTING          | 335211.00               |

**LATITUDE** 33 55' 10"  
**LONGITUDE** 151 13' 2"  
**GS-MAP**  
**AMG-ZONE** 56  
**COORD-SOURCE**  
**REMARK**

### Form-A [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 448//10752

### Licensed [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 448 10752

### Construction [\(top\)](#)

Negative depths indicate Above Ground Level;H-Hole;P-Pipe;OD-Outside Diameter;  
ID-Inside Diameter;C-Cemented;SL-Slot Length;A-Aperture;GS-Grain Size;Q-Quantity

| HOLE-<br>NO | PIPE-<br>NO | COMPONENT-<br>CODE | COMPONENT-<br>TYPE | DEPTH-<br>FROM<br>(metres) | DEPTH-<br>TO<br>(metres) | OD<br>(mm) | ID<br>(mm) | INTERVAL | DETAIL                                     |
|-------------|-------------|--------------------|--------------------|----------------------------|--------------------------|------------|------------|----------|--------------------------------------------|
| 1           |             | Hole               | Hole               | 0.00                       | 22.00                    | 100        |            |          | Auger                                      |
| 1           | 1           | Casing             | P.V.C.             | 0.00                       | 21.00                    | 100        |            |          | Driven into<br>small hole                  |
| 1           | 1           | Opening            | Screen             | 21.00                      | 22.00                    | 60         |            |          | Stainless<br>Steel; A:<br>.3mm;<br>Riveted |

### Water Bearing Zones [\(top\)](#)

| FROM-<br>DEPTH<br>(metres) | TO-DEPTH<br>(metres) | THICKNESS<br>(metres) | ROCK-<br>CAT-<br>DESC | S-W-<br>L | D-<br>D-<br>L | YIELD | TEST-HOLE-<br>DEPTH<br>(metres) | DURATION | SALINITY |
|----------------------------|----------------------|-----------------------|-----------------------|-----------|---------------|-------|---------------------------------|----------|----------|
| 16.00                      | 22.00                | 6.00                  |                       | 16.00     |               | 1.00  | 20.00                           |          |          |

### Drillers Log [\(top\)](#)

| FROM | TO    | THICKNESS | DESC | GEO-MATERIAL | COMMENT |
|------|-------|-----------|------|--------------|---------|
| 0.00 | 22.00 | 22.00     |      | SAND         |         |

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 6, 2013

Print Report

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111615

### Works Details [\(top\)](#)

|                        |                 |
|------------------------|-----------------|
| GROUNDWATER NUMBER     | GW111615        |
| LIC-NUM                | 10WA113635      |
| AUTHORISED-PURPOSES    | DOMESTIC        |
| INTENDED-PURPOSES      | DOMESTIC        |
| WORK-TYPE              | Spear           |
| WORK-STATUS            | Supply Obtained |
| CONSTRUCTION-METHOD    | (Unknown)       |
| OWNER-TYPE             | Private         |
| COMMENCE-DATE          |                 |
| COMPLETION-DATE        | 2004-10-01      |
| FINAL-DEPTH (metres)   | 7.00            |
| DRILLED-DEPTH (metres) | 7.00            |
| CONTRACTOR-NAME        |                 |
| DRILLER-NAME           |                 |
| PROPERTY               | SIMICOS         |
| GWMA                   | -               |
| GW-ZONE                | -               |
| STANDING-WATER-LEVEL   |                 |
| SALINITY               |                 |
| YIELD                  |                 |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6245514.00              |
| EASTING          | 335563.00               |

LATITUDE 33 55' 5"  
LONGITUDE 151 13' 16"  
GS-MAP  
AMG-ZONE 56  
COORD-SOURCE  
REMARK

**Form-A** [\(top\)](#)

COUNTY CUMBERLAND  
PARISH ALEXANDRIA  
PORTION-LOT-DP 109//11570

**Licensed** [\(top\)](#)

COUNTY CUMBERLAND  
PARISH ALEXANDRIA  
PORTION-LOT-DP 109 11570

**Construction** [\(top\)](#)

Negative depths indicate Above Ground Level;H-Hole;P-Pipe;OD-Outside Diameter;  
ID-Inside Diameter;C-Cemented;SL-Slot Length;A-Aperture;GS-Grain Size;Q-Quantity

| HOLE-<br>NO | PIPE-<br>NO | COMPONENT-<br>CODE | COMPONENT-<br>TYPE | DEPTH-<br>FROM<br>(metres) | DEPTH-<br>TO<br>(metres) | OD<br>(mm) | ID<br>(mm) | INTERVAL | DETAIL    |
|-------------|-------------|--------------------|--------------------|----------------------------|--------------------------|------------|------------|----------|-----------|
| 1           |             | Hole               | Hole               | 0.00                       | 7.00                     |            |            |          | (Unknown) |
| 1           | 1           | Casing             | P.V.C.             | 0.00                       | 0.00                     | 60         |            |          |           |

**Water Bearing Zones** [\(top\)](#)

no details

**Drillers Log** [\(top\)](#)

no details

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 20, 2013

Print Report

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111592

### Works Details [\(top\)](#)

|                        |                 |
|------------------------|-----------------|
| GROUNDWATER NUMBER     | GW111592        |
| LIC-NUM                | 10WA113966      |
| AUTHORISED-PURPOSES    | DOMESTIC        |
| INTENDED-PURPOSES      | DOMESTIC        |
| WORK-TYPE              | Bore            |
| WORK-STATUS            | Supply Obtained |
| CONSTRUCTION-METHOD    | (Unknown)       |
| OWNER-TYPE             | Private         |
| COMMENCE-DATE          |                 |
| COMPLETION-DATE        | 2005-01-01      |
| FINAL-DEPTH (metres)   | 20.00           |
| DRILLED-DEPTH (metres) | 20.00           |
| CONTRACTOR-NAME        |                 |
| DRILLER-NAME           |                 |
| PROPERTY               | ROWLEY          |
| GWMA                   | -               |
| GW-ZONE                | -               |
| STANDING-WATER-LEVEL   |                 |
| SALINITY               |                 |
| YIELD                  |                 |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6246589.00              |
| EASTING          | 334957.00               |

**LATITUDE** 33 54' 29"  
**LONGITUDE** 151 12' 53"  
**GS-MAP**  
**AMG-ZONE** 56  
**COORD-SOURCE**  
**REMARK**

### Form-A [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 35/12/5759

### Licensed [\(top\)](#)

**COUNTY** CUMBERLAND  
**PARISH** ALEXANDRIA  
**PORTION-LOT-DP** 35 5759

### Construction [\(top\)](#)

Negative depths indicate Above Ground Level;H-Hole;P-Pipe;OD-Outside Diameter; ID-Inside Diameter;C-Cemented;SL-Slot Length;A-Aperture;GS-Grain Size;Q-Quantity

| HOLE-<br>NO | PIPE-<br>NO | COMPONENT-<br>CODE | COMPONENT-<br>TYPE | DEPTH-<br>FROM<br>(metres) | DEPTH-<br>TO<br>(metres) | OD<br>(mm) | ID<br>(mm) | INTERVAL | DETAIL    |
|-------------|-------------|--------------------|--------------------|----------------------------|--------------------------|------------|------------|----------|-----------|
| 1           |             | Hole               | Hole               | 0.00                       | 20.00                    | 76.2       |            |          | (Unknown) |
| 1           | 1           | Casing             | P.V.C.             | 0.00                       | 0.00                     | 76.2       |            |          |           |

### Water Bearing Zones [\(top\)](#)

no details

### Drillers Log [\(top\)](#)

no details

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.

# Groundwater Works Summary

For information on the meaning of fields please see [Glossary](#)  
Document Generated on Wednesday, February 6, 2013

Print Report

[Works Details](#) [Site Details](#) [Form A](#) [Licensed](#) [Construction](#) [Water Bearing Zones](#) [Drillers Log](#)

## Work Requested -- GW111585

### Works Details [\(top\)](#)

|                        |                 |
|------------------------|-----------------|
| GROUNDWATER NUMBER     | GW111585        |
| LIC-NUM                | 10WA114280      |
| AUTHORISED-PURPOSES    | DOMESTIC        |
| INTENDED-PURPOSES      | DOMESTIC        |
| WORK-TYPE              | Bore            |
| WORK-STATUS            | Supply Obtained |
| CONSTRUCTION-METHOD    | (Unknown)       |
| OWNER-TYPE             | Private         |
| COMMENCE-DATE          |                 |
| COMPLETION-DATE        | 2007-01-01      |
| FINAL-DEPTH (metres)   | 21.00           |
| DRILLED-DEPTH (metres) | 21.00           |
| CONTRACTOR-NAME        |                 |
| DRILLER-NAME           |                 |
| PROPERTY               | MASTROCOSTAS    |
| GWMA                   | -               |
| GW-ZONE                | -               |
| STANDING-WATER-LEVEL   |                 |
| SALINITY               |                 |
| YIELD                  |                 |

### Site Details [\(top\)](#)

|                  |                         |
|------------------|-------------------------|
| REGION           | 10 - SYDNEY SOUTH COAST |
| RIVER-BASIN      |                         |
| AREA-DISTRICT    |                         |
| CMA-MAP          |                         |
| GRID-ZONE        |                         |
| SCALE            |                         |
| ELEVATION        |                         |
| ELEVATION-SOURCE |                         |
| NORTHING         | 6245391.00              |
| EASTING          | 335239.00               |

LATITUDE 33 55' 9"  
LONGITUDE 151 13' 4"  
GS-MAP  
AMG-ZONE 56  
COORD-SOURCE  
REMARK

**Form-A** [\(top\)](#)

COUNTY CUMBERLAND  
PARISH ALEXANDRIA  
PORTION-LOT-DP 21//815679

**Licensed** [\(top\)](#)

COUNTY CUMBERLAND  
PARISH ALEXANDRIA  
PORTION-LOT-DP 21 815679

**Water Bearing Zones** [\(top\)](#)

no details

**Drillers Log** [\(top\)](#)

no details

---

**Warning To Clients:** This raw data has been supplied to the Department of Infrastructure, Planning and Natural Resources (DIPNR) by drillers, licensees and other sources. The DIPNR does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.