



APPENDIX C

Photo Catalogue

Image/ File No	Description – Wambo Homestead	
	Subject and Detail	Orientation
WH_001	Carriage House	East
WH_002	Carriage House	South
WH_003	Carriage House	Northeast
WH_004	Carriage House	Southeast
WH_005	Carriage House	North
WH_006	Carriage House interior	
WH_007	Carriage House	West
WH_008	Carriage House	West
WH_009	Carriage House	
WH_010	Carriage House	
WH_011	Carriage House interior	
WH_012	Carriage House interior	
WH_013	Carriage House interior	
WH_014	Servants Wing	West
WH_015	Servants Wing	West
WH_016	Servants Wing	South
WH_017	Servants Wing	Southeast
WH_018	Servants Wing	Southeast
WH_019	Servants Wing	South
WH_020	Servants Wing	West
WH_021	Servants Wing	West
WH_022	Servants Wing	Northwest
WH_023	Servants Wing	East
WH_024	Servants Wing	Northeast
WH_025	Kitchen Wing	East
WH_026	Kitchen Wing	North
WH_027	Kitchen Wing	East
WH_028	Kitchen Wing	East
WH_029	Kitchen Wing interior	
WH_030	Kitchen Wing interior	
WH_031	Kitchen Wing detail	East
WH_032	Kitchen Wing	Northeast
WH_033	Kitchen Wing detail	East
WH_034	Stud Master's Cottage	West
WH_035	Kitchen Wing and Servants Wing	South
WH_036	Kitchen Wing	Southwest
WH_037	Kitchen Wing	West
WH_038	Kitchen Wing detail	

Wambo Homestead



WH_001.JPG



WH_002.JPG



WH_003.JPG



WH_004.JPG



WH_005.JPG



WH_006.JPG



WH_007.JPG



WH_008.JPG



WH_009.JPG



WH_010.JPG



WH_011.JPG



WH_012.JPG



WH_013.JPG



WH_014.JPG



WH_015.JPG



WH_016.JPG



WH_017.JPG



WH_018.JPG



WH_019.JPG



WH_020.JPG



WH_021.JPG



WH_022.JPG



WH_023.JPG



WH_024.JPG



WH_025.JPG



WH_026.JPG



WH_027.JPG



WH_028.JPG



WH_029.JPG



WH_030.JPG



WH_031.JPG



WH_032.JPG



WH_033.JPG



WH_034.JPG



WH_035.JPG

Image/ File No	Description – Wambo Homestead	
	Subject and Detail	Orientation
WH_039	Kitchen Wing detail	
WH_040	Kitchen Wing detail (cellar stairs)	
WH_041	Kitchen Wing - new house transition	West
WH_042	Kitchen Wing	Northwest
WH_043	New House	South
WH_044	New House	South
WH_045	New House	Southeast
WH_046	New House interior	
WH_047	New House interior	
WH_048	New House interior	
WH_049	New House detail	
WH_050	New House	West
WH_051	New House	West
WH_052	New House - front verandah	West
WH_053	New House - front verandah	West
WH_054	New House - front verandah	North
WH_055	New House - front verandah	Northwest
WH_056	New House - front verandah	North
WH_057	New House - front verandah	North
WH_058	New House - front verandah	North
WH_059	New House - front verandah detail	
WH_060	New House - front verandah detail	
WH_061	New House - view from front door	South
WH_062	New House interior	
WH_063	New House - front verandah steps	South
WH_064	New House - front verandah	East
WH_065	Kitchen Wing	Northeast
WH_066	Butchers Hut	
WH_067	Butchers Hut interior detail	
WH_068	Butchers Hut interior	
WH_069	Butchers Hut	
WH_070	Butchers Hut detail	
WH_071	Butchers Hut detail	
WH_072	Butchers Hut	
WH_073	Stud Master's Cottage	Northwest
WH_074	Servants Wing	
WH_075	Stud Master's Cottage	West
WH_076	Stud Master's Cottage	West

Wambo Homestead



WH_036.JPG



WH_037.JPG



WH_038.JPG



WH_039.JPG



WH_040.JPG



WH_041.JPG



WH_042.JPG



WH_043.JPG



WH_044.JPG



WH_045.JPG



WH_046.JPG



WH_047.JPG



WH_048.JPG



WH_049.JPG



WH_050.JPG



WH_051.JPG



WH_052.JPG



WH_053.JPG



WH_054.JPG



WH_055.JPG



WH_056.JPG



WH_057.JPG



WH_058.JPG



WH_059.JPG



WH_060.JPG



WH_061.JPG



WH_062.JPG



WH_063.JPG



WH_064.JPG



WH_065.JPG



WH_066.JPG



WH_067.JPG



WH_068.JPG



WH_069.JPG



WH_070.JPG

Image/ File No	Description – Wambo Homestead	
	Subject and Detail	Orientation
WH_077	Stud Master's Cottage	West
WH_078	Stud Master's Cottage	West
WH_079	Stud Master's Cottage interior	
WH_080	Stud Master's Cottage exterior detail	
WH_081	Stud Master's Cottage interior	
WH_082	Stud Master's Cottage	North
WH_083	Stud Master's Cottage	Southeast
WH_084	Stud Master's Cottage	
WH_085	Stud Master's Cottage	Southwest
WH_087	Slab Horse Boxes	North
WH_088	Carriage House	South
WH_089	Slab Horse Boxes	West
WH_090	Slab Horse Boxes	South
WH_091	Slab Horse Boxes	East
WH_092	Mounting Yard	East
WH_093	Structures associated with Mounting Yard	North
WH_094	Structures associated with Mounting Yard	North
WH_095	Structures associated with Mounting Yard	East
WH_096	Structures associated with Mounting Yard	Southeast
WH_097	Structures associated with Mounting Yard	South
WH_098	Structures associated with Mounting Yard	North
WH_099	Yards	
WH_100	Yards	
WH_101	Yards	
WH_102	Yards	

Wambo Homestead



WH_071.JPG



WH_072.JPG



WH_073.JPG



WH_074.JPG



WH_075.JPG



WH_076.JPG



WH_077.JPG



WH_078.JPG



WH_079.JPG



WH_080.JPG



WH_081.JPG



WH_082.JPG



WH_083.JPG



WH_084.JPG



WH_085.JPG



WH_086.JPG



WH_087.JPG



WH_088.JPG



WH_089.JPG



WH_090.JPG



WH_091.JPG



WH_092.JPG



WH_093.JPG



WH_094.JPG



WH_095.JPG



WH_096.JPG



WH_097.JPG



WH_098.JPG



WH_099.JPG



WH_100.JPG



WH_101.JPG



WH_102.JPG

Image/ File No	Description – St Philips Church	
	Subject and Detail	Orientation
SPC_01	St Philips Church - gate post plaque	
SPC_02	St Philips Church - church	South
SPC_03	St Philips Church - church	Southeast
SPC_04	St Philips Church - church	North
SPC_05	St Philips Church - cemetery	Southwest
SPC_06	St Philips Church - church	East
SPC_07	St Philips Church - church	Northeast
SPC_08	St Philips Church - church	West

St Phillips Church



SPC_01.JPG



SPC_02.JPG



SPC_03.JPG



SPC_04.JPG



SPC_05.JPG



SPC_06.JPG



SPC_07.JPG



SPC_08.JPG

Image/ File No	Description – Former Queen Victoria Inn – Ruins Archaeological site	
	Subject and Detail	Orientation
FQVI_01	Former Queen Victoria Inn site – brick cistern	
FQVI_02	Former Queen Victoria Inn site – water tank	
FQVI_03	Former Queen Victoria Inn site	

Former Queen Victoria Inn



FQVI_01.JPG



FQVI_02.JPG



FQVI_03.JPG

Image/ File No	Description – Dog Leg Fence	
	Subject and Detail	Orientation
DLF_01	Dog Leg Fence	
DLF_02	Dog Leg Fence	
DLF_03	Dog Leg Fence	
DLF_04	Dog Leg Fence	
DLF_05	Dog Leg Fence	
DLF_06	Dog Leg Fence	
DLF_07	Dog Leg Fence	
DLF_08	Dog Leg Fence	
DLF_09	Dog Leg Fence	
DLF_10	Dog Leg Fence	
DLF_11	Dog Leg Fence	
DLF_12	Dog Leg Fence	
DLF_13	Dog Leg Fence	
DLF_14	Dog Leg Fence	
DLF_15	Dog Leg Fence	
DLF_16	Dog Leg Fence	
DLF_17	Dog Leg Fence	
DLF_18	Dog Leg Fence	
DLF_19	Dog Leg Fence	
DLF_20	Dog Leg Fence	
DLF_21	Dog Leg Fence	
DLF_22	Dog Leg Fence	
DLF_23	Dog Leg Fence	
DLF_24	Dog Leg Fence	
DLF_25	Dog Leg Fence	
DLF_26	Dog Leg Fence	
DLF_27	Dog Leg Fence	
DLF_28	Dog Leg Fence	
DLF_29	Dog Leg Fence	
DLF_30	Dog Leg Fence	
DLF_31	Dog Leg Fence	
DLF_32	Dog Leg Fence	
DLF_33	Dog Leg Fence	
DLF_34	Dog Leg Fence	
DLF_35	Dog Leg Fence	
DLF_36	Dog Leg Fence	
DLF_37	Dog Leg Fence	
DLF_38	Dog Leg Fence	



DLF_35.JPG

Image/ File No	Description – Dog Leg Fence	
	Subject and Detail	Orientation
DLF_39	Dog Leg Fence	
DLF_40	Dog Leg Fence	
DLF_41	Dog Leg Fence	
DLF_42	Dog Leg Fence	
DLF_43	Dog Leg Fence	
DLF_44	Dog Leg Fence	
DLF_45	Dog Leg Fence	
DLF_46	Dog Leg Fence	
DLF_47	Dog Leg Fence	
DLF_48	Dog Leg Fence	
DLF_49	Dog Leg Fence	
DLF_50	Dog Leg Fence	
DLF_51	Dog Leg Fence	
DLF_52	Dog Leg Fence	
DLF_53	Dog Leg Fence	
DLF_54	Dog Leg Fence	
DLF_55	Dog Leg Fence	
DLF_56	Dog Leg Fence	
DLF_57	Dog Leg Fence	
DLF_58	Dog Leg Fence	
DLF_59	Dog Leg Fence	
DLF_60	Dog Leg Fence	
DLF_61	Dog Leg Fence	
DLF_62	Dog Leg Fence	
DLF_63	Dog Leg Fence	
DLF_64	Dog Leg Fence	
DLF_65	Dog Leg Fence	
DLF_66	Dog Leg Fence	
DLF_67	Dog Leg Fence	
DLF_68	Dog Leg Fence	
DLF_69	Dog Leg Fence	
DLF_70	Dog Leg Fence	
DLF_71	Dog Leg Fence	
DLF_72	Dog Leg Fence	
DLF_73	Dog Leg Fence	
DLF_74	Dog Leg Fence	
DLF_75	Dog Leg Fence	
DLF_76	Dog Leg Fence	

Dog Leg Fence



DLF_36.JPG



DLF_37.JPG



DLF_38.JPG



DLF_39.JPG



DLF_40.JPG



DLF_41.JPG



DLF_42.JPG



DLF_43.JPG



DLF_44.JPG



DLF_45.JPG



DLF_46.JPG




DLF_47.JPG



DLF_48.JPG



DLF_49.JPG



DLF_50.JPG



DLF_51.JPG



DLF_52.JPG



DLF_53.JPG



DLF_54.JPG



DLF_55.JPG



DLF_56.JPG



DLF_57.JPG



DLF_58.JPG



DLF_59.JPG



DLF_60.JPG



DLF_61.JPG



DLF_62.JPG



DLF_63.JPG



DLF_64.JPG



DLF_65.JPG



DLF_66.JPG



DLF_67.JPG



DLF_68.JPG



DLF_69.JPG



DLF_70.JPG

Image/ File No	Description – Dog Leg Fence	
	Subject and Detail	Orientation
DLF_77	Dog Leg Fence	
DLF_78	Dog Leg Fence	
DLF_79	Dog Leg Fence	
DLF_80	Dog Leg Fence	
DLF_81	Dog Leg Fence	
DLF_82	Dog Leg Fence	
DLF_83	Dog Leg Fence	
DLF_84	Dog Leg Fence	
DLF_86	Dog Leg Fence	
DLF_87	Dog Leg Fence	
DLF_88	Dog Leg Fence	
DLF_89	Dog Leg Fence	
DLF_90	Dog Leg Fence	

Dog Leg Fence



DLF_71.JPG



DLF_72.JPG



DLF_73.JPG



DLF_74.JPG



DLF_75.JPG



DLF_76.JPG



DLF_77.JPG



DLF_78.JPG



DLF_79.JPG



DLF_80.JPG



DLF_81.JPG



DLF_82.JPG



DLF_83.JPG



DLF_84.JPG



DLF_85.JPG



DLF_86.JPG



DLF_87.JPG



DLF_88.JPG



DLF_89.JPG



DLF_90.JPG

Image/ File No	Description – Former House Site	
	Subject and Detail	Orientation
FHS_01	Former House site - concrete slab with corrugated iron and timber block.	
FHS_02	Former House site - brick rubble	
FHS_03	Former House site - brick rubble	
FHS_04	Former House site - brick rubble	
FHS_05	Former House site – detail of bricks	
FHS_06	Former House site - ceramic and glass artefactual material	
FHS_07	Former House site - ceramic and glass artefactual material	
FHS_08	Former House site - detail of bricks	
FHS_09	Former House site - sandstone pavers and bricks	
FHS_10	Former House site - brick cistern	
FHS_11	Former House site - brick cistern	
FHS_12	Former House site - brick cistern	
FHS_13	Former House site - metal artefactual material	
FHS_14	Former House site - timber block in concrete slab	
FHS_15	Former House site - horseshoes	
FHS_16	Former House site - clear glass coffee & chicory essence bottle	
FHS_17	Former House site - clear glass coffee & chicory essence bottle	
FHS_18	Former House site - clear glass coffee & chicory essence bottle	
FHS_19	Former House site - clear glass coffee & chicory essence bottle	
FHS_20	Former House site – sandstone block	
FHS_21	Former House site – sandstone block	
FHS_22	Former House site – timber fence post	
FHS_23	Former House site – timber fence post	


Former House Site



FHS_01.JPG



FHS_02.JPG



FHS_03.JPG



FHS_04.JPG



FHS_05.JPG



FHS_06.JPG



FHS_07.JPG



FHS_08.JPG



FHS_09.JPG



FHS_10.JPG



FHS_11.JPG



FHS_12.JPG



FHS_13.JPG



FHS_14.JPG



FHS_15.JPG



FHS_16.JPG



FHS_17.JPG



FHS_18.JPG



FHS_19.JPG



FHS_20.JPG



FHS_21.JPG



FHS_22.JPG



FHS_23.JPG

Image/ File No	Description – Well and Windmill Site	
	Subject and Detail	Orientation
WWS_01	Well and Windmill Site - dam	
WWS_02	Well and Windmill Site - failure in dam wall	
WWS_03	Well and Windmill Site - pipe from windmill to dam wall	
WWS_04	Well and Windmill Site - pipe from windmill to dam wall	
WWS_05	Well and Windmill Site - pipe from windmill to dam wall	
WWS_06	Well and Windmill Site - well	
WWS_07	Well and Windmill Site - pipe from windmill to dam wall	
WWS_08	Well and Windmill Site - concrete base of windmill detail	
WWS_09	Well and Windmill Site – windmill over well	
WWS_10	Well and Windmill Site - windmill over well	
WWS_11	Well and Windmill Site - windmill over well detail	
WWS_12	Well and Windmill Site - windmill over well	
WWS_13	Well and Windmill Site - windmill over well detail	
WWS_14	Well and Windmill Site - windmill over well detail	
WWS_15	Well and Windmill Site - windmill over well detail	
WWS_16	Well and Windmill Site - windmill over well detail	
WWS_17	Well and Windmill Site - windmill over well detail	

Well and Windmill Site



WWS_01.JPG



WWS_02.JPG



WWS_03.JPG



WWS_04.JPG



WWS_05.JPG



WWS_06.JPG



WWS_07.JPG



WWS_08.JPG



WWS_09.JPG



WWS_10.JPG



WWS_11.JPG



WWS_12.JPG



WWS_13.JPG



WWS_14.JPG



WWS_15.JPG



WWS_16.JPG



WWS_17.JPG

	Description - Derelict Windmill Site	
	Subject and Detail	Orientation
DWS_01	Derelict Windmill Site - windmill structure	
DWS_02	Derelict Windmill Site - windmill structure	
DWS_03	Derelict Windmill Site – borehole	
DWS_04	Derelict Windmill Site - windmill structure	
DWS_05	Derelict Windmill Site - windmill structure	
DWS_06	Derelict Windmill Site - turbine	

Derelict Windmill Site



DWS_01.JPG



DWS_02.JPG



DWS_03.JPG



DWS_04.JPG



DWS_05.JPG



DWS_06.JPG

Image/ File No	Description – Shearing Shed and Creamery	
	Subject and Detail	Orientation
SHC_01	Shearing Shed and Creamery	Southeast
SHC_02	Creamery	Southwest
SHC_03	Creamery	West
SHC_04	Creamery	North northwest
SHC_05	Creamery - interior	
SHC_06	Creamery - interior	
SHC_07	Shearing Shed and Creamery	Southeast
SHC_08	Shearing Shed	Southwest
SHC_09	Shearing Shed	West
SHC_10	Shearing Shed	West
SHC_11	Shearing Shed - interior	
SHC_12	Shearing Shed - interior	
SHC_13	Shearing Shed - interior	
SHC_14	Shearing Shed - interior	
SHC_15	Shearing Shed - interior	
SHC_16	Shearing Shed - interior	
SHC_17	Shearing Shed - interior	
SHC_18	Shearing Shed - interior	
SHC_19	Shearing Shed - interior	
SHC_20	Shearing Shed - interior	
SHC_21	Shearing Shed - interior	
SHC_22	Shearing Shed - interior	
SHC_23	Shearing Shed - interior	
SHC_24	Shearing Shed - interior	
SHC_25	Shearing Shed - interior	
SHC_26	Shearing Shed - interior	
SHC_27	Shearing Shed	West
SHC_28	Shearing Shed and Creamery - cistern	
SHC_29	Shearing Shed	North northwest
SHC_30	Shearing Shed - corrugated iron stamp detail	
SHC_31	Shearing Shed and Creamery	East
SHC_32	Shearing Shed and Creamery – water tank stand	West
SHC_33	Shearing Shed - corrugated iron stamp detail	
SHC_34	Shearing Shed and Creamery	South

Shearing Shed and Creamery



SHC_01.JPG



SHC_02.JPG



SHC_03.JPG



SHC_04.JPG



SHC_05.JPG



SHC_06.JPG



SHC_07.JPG



SHC_08.JPG



SHC_09.JPG



SHC_10.JPG



SHC_11.JPG



SHC_12.JPG



SHC_13.JPG



SHC_14.JPG



SHC_15.JPG



SHC_16.JPG



SHC_17.JPG



SHC_18.JPG



SHC_19.JPG



SHC_20.JPG



SHC_21.JPG



SHC_22.JPG



SHC_23.JPG



SHC_24.JPG



SHC_25.JPG



SHC_26.JPG



SHC_27.JPG



SHC_28.JPG



SHC_29.JPG



SHC_30.JPG



SHC_31.JPG



SHC_32.JPG



SHC_33.JPG



SHC_34.JPG

Image/ File No	Description – Montrose Property	
	Subject and Detail	Orientation
MH_01	Montrose Property - garage	Southwest
MH_02	Montrose Property - house	Southwest
MH_03	Montrose Property - house	Southwest
MH_04	Montrose Property - house	Southwest
MH_05	Montrose Property - house	West
MH_06	Montrose Property - house detail	
MH_07	Montrose Property - house	South
MH_08	Montrose Property - house	Southeast
MH_09	Montrose Property - house	Northeast
MH_10	Montrose Property - house	Northeast
MH_11	Montrose Property - house	North
MH_12	Montrose Property - house foundations	
MH_13	Montrose Property - house	North East
MH_14	Montrose Property - view from rear of house	South
MH_15	Montrose Property - rear gate post	East
MH_16	Montrose Property - water tank	
MH_17	Montrose Property - driveway entrance	Southwest
MH_18	Montrose Property - house	Southwest
MH_19	Montrose Property - house	West
MH_20	Montrose Property - house	West
MH_21	Montrose Property - second house on property	West
MH_22	Montrose Property - shed associated with second house on property	West
MH_23	Montrose Property - shed associated with second house on property	West
MH_24	Montrose Property - shed associated with second house on property	West
MH_25	Montrose Property - shearing shed exterior	Southeast
MH_26	Montrose Property - shearing shed exterior	Southeast
MH_27	Montrose Property - shearing shed exterior	Southeast
MH_28	Montrose Property - shearing shed exterior	Northeast
MH_29	Montrose Property - shearing shed exterior	North
MH_30	Montrose Property - sheep dip near shearing shed	
MH_31	Montrose Property - shearing shed exterior	Northwest
MH_32	Montrose Property - shearing shed exterior	West
MH_33	Montrose Property - shearing shed exterior	Southwest
MH_34	Montrose Property - shearing shed exterior	Southwest
MH_35	Montrose Property - bricks stored inside shearing shed	
MH_36	Montrose Property - shearing shed interior	
MH_37	Montrose Property - shearing shed interior	
MH_38	Montrose Property - shearing shed interior	

Montrose Homestead



MH_01.JPG



MH_02.JPG



MH_03.JPG



MH_04.JPG



MH_05.JPG



MH_06.JPG



MH_07.JPG



MH_08.JPG



MH_09.JPG



MH_10.JPG



MH_11.JPG



MH_12.JPG



MH_13.JPG



MH_14.JPG



MH_15.JPG



MH_16.JPG



MH_17.JPG



MH_18.JPG



MH_19.JPG



MH_20.JPG



MH_21.JPG



MH_22.JPG



MH_23.JPG



MH_24.JPG



MH_25.JPG



MH_26.JPG



MH_27.JPG



MH_28.JPG



MH_29.JPG



MH_30.JPG



MH_31.JPG



MH_32.JPG



MH_33.JPG



MH_34.JPG



MH_35.JPG

Image/ File No	Description – Montrose Property	
	Subject and Detail	Orientation
MH_39	Montrose Property - shearing shed interior	
MH_40	Montrose Property - shearing shed interior	
MH_41	Montrose Property - shearing shed interior, shearing machinery detail	
MH_42	Montrose Property - shearing shed interior	
MH_43	Montrose Property - shearing shed interior	
MH_44	Montrose Property - shearing shed interior	
MH_45	Montrose Property - shearing shed interior	
MH_46	Montrose Property - shearing shed interior, redcliff trademark stamp on corrugated iron	
MH_47	Montrose Property - shearing shed interior	

Montrose Homestead



MH_36.JPG



MH_37.JPG



MH_38.JPG



MH_39.JPG



MH_40.JPG



MH_41.JPG



MH_42.JPG



MH_43.JPG



MH_44.JPG



MH_45.JPG



MH_46.JPG



MH_47.JPG

Image/ File No	Description – Warkworth Public School	
	Subject and Detail	Orientation
WPS_01	Warkworth Public School	Northwest
WPS_02	Warkworth Public School	West
WPS_03	Warkworth Public School – dressed stone	



WPS_01.JPG



WPS_02.JPG



WPS_03.JPG

Image/ File No	Description – Springwood Homestead (Abandoned Homestead B)	
	Subject and Detail	Orientation
SH_01	Springwood Homestead - house	South
SH_02	Springwood Homestead - house	South
SH_03	Springwood Homestead - house	Southwest
SH_04	Springwood Homestead - house	Southwest
SH_05	Springwood Homestead - house interior	
SH_06	Springwood Homestead - house interior	
SH_07	Springwood Homestead - house interior	
SH_08	Springwood Homestead - house interior	
SH_09	Springwood Homestead - house interior, sandstone fireplace	
SH_10	Springwood Homestead - house interior	
SH_11	Springwood Homestead - house	Northwest
SH_12	Springwood Homestead - house	North
SH_13	Springwood Homestead - house, wall detail	
SH_14	Springwood Homestead - house interior	
SH_15	Springwood Homestead - house interior	
SH_16	Springwood Homestead - house interior	
SH_17	Springwood Homestead - house interior, wall covering detail	
SH_18	Springwood Homestead - house interior, wall covering detail	
SH_19	Springwood Homestead - house interior, sandstone fireplace	
SH_20	Springwood Homestead - house interior	
SH_21	Springwood Homestead - house interior	
SH_22	Springwood Homestead - house, wall detail	
SH_23	Springwood Homestead - house interior	
SH_24	Springwood Homestead - house interior	
SH_25	Springwood Homestead - ruins of shed	East
SH_26	Springwood Homestead - ruins of shed	Northwest
SH_27	Springwood Homestead - ruins of shed	West
SH_28	Springwood Homestead - house	East
SH_29	Springwood Homestead - house	East
SH_30	Springwood Homestead - bricks	
SH_31	Springwood Homestead - house	North
SH_32	Springwood Homestead - house	North

Springwood Homestead



SH_01.JPG



SH_02.JPG



SH_03.JPG



SH_06.JPG



SH_07.JPG



SH_11.JPG



SH_12.JPG



SH_16.JPG



SH_17.JPG



SH_21.JPG



SH_22.JPG



SH_26.JPG



SH_27.JPG

SH_31.JPG



SH_32.JPG

**Newcastle**

75 York Street
Teralba NSW 2284

Ph. 02 4950 5322

Perth

PO Box 8177
Subiaco East WA 6008
33 Ventnor Avenue
West Perth WA 6005

Ph. 08 6260 0700

Canberra

PO Box 6135
56 Bluebell Street
O'Connor ACT 2602

Ph. 02 6262 9484

Sydney

50 York Street
Sydney NSW 2000

Ph. 1300 793 267

Brisbane

GPO Box 459
Brisbane QLD 4001

Ph. 1300 793 267

www.umwelt.com.au