

Approx development site
Existing sparse woodland and scrub
Pedestrian footpath
Fence of 8 Ramosus Way



Figure 34: Viewpoint 3 - Baseline Photo

Building 2



Figure 34: Photomontage Year 0



Figure 34: Photomontage Year 15

Figure 34: Viewpoint 3 - Ramosus Way, Bidwill - Close to Public Footpath Looking North East (Photomontaged)