

Environmental Audit

Description
existing pits identified and
covered

Taken Date
22/8/2022 at 08:51 am

Upload Date
22/8/2022 at 08:52 am

Uploaded By
Adrien Clements

File Name
[BBE98F67-C017-4998-A...](#)



Environmental Audit

Description
existing pits identified and
covered

Taken Date
22/8/2022 at 08:51 am

Upload Date
22/8/2022 at 08:51 am

Uploaded By
Adrien Clements

File Name
[87BAC471-B90D-4B12-8...](#)



Environmental Audit

Description
silt fence rectified.
somewhat redundant now
as we have poured a strip
footing on the high side
which diverts any
overland flow.

Taken Date
22/8/2022 at 08:49 am

Upload Date
22/8/2022 at 08:49 am

Uploaded By
Adrien Clements

File Name
[64761A37-3491-4814-8...](#)



Environmental Audit

Description
Silt sock at private road
amended

Taken Date
22/8/2022 at 08:48 am

Upload Date
22/8/2022 at 08:48 am

Uploaded By
Adrien Clements

File Name
[B72F3367-5674-4B75-A...](#)



Environmental Audit

Description
additional hay bale
installed

Taken Date
22/8/2022 at 08:47 am

Upload Date
22/8/2022 at 08:48 am

Uploaded By
Adrien Clements

File Name
[3F1B3D44-FC64-4FBF-B...](#)



Environmental Audit

Description
gravel cleaned from gutter
and silt socks amended

Taken Date
22/8/2022 at 08:47 am

Upload Date
22/8/2022 at 08:47 am

Uploaded By
Adrien Clements

File Name
[3D7BCEA3-CF34-46E7-A...](#)



Environmental Audit

Description
gravel cleaned from gutter

Taken Date
22/8/2022 at 08:46 am

Upload Date
22/8/2022 at 08:47 am

Uploaded By
Adrien Clements

File Name
[D9237EC9-D8AE-4CAA-...](#)





