





Appendix G - Part 4


Surface Water and Flooding Impact Assessment



























































































ANNEXURE D FIGURES SHOWING THE PRELIMINARY HYDRAULIC CATEGORISATION AND PROVISIONAL HAZARD CLASSIFICATION OF LAND - 1% AEP












































ANNEXURE E FIGURES SHOWING THE IMPACT OF A PARTIAL BLOCKAGE OF THE M7 MOTORWAY TRANSVERSE DRAINAGE STRUCTURES ON FLOOD BEHAVIOUR – 1% AEP

