
### Appendix C – Site walkover photographs


## Site 1 – Former Painters/grit blasting area







Photograph 1.03 Photograph 1.04





Photograph 1.05

Photograph 1.06





Photograph 1.07

Photograph 1.08






Photograph 1.09 Photograph 1.10





Photograph 1.13

## Site 2 – Proposed vegetation clearance area








Photograph 2.03


Photograph 2.04



Photograph 2.05 outcropping sandstone on bend in road

### Site 3 – Terraced Gardens Area







Photograph 3.02 – close up of electrical building containing electrical switchboards. These structures will not be disturbed during proposed construction works.



Photograph 3.03 – Looking east along concrete 'path' on the second level of the terraced garden area. The concrete represents a remnant of a former cable tower crane and tracks.





Photograph 3.05 Shaded picnic area and toilet block

Photograph 3.06



Photograph 3.07 – gardening equipment storage shed

Site 4 – Haviland Park





Photograph 4.01 Photograph 4.02



Photograph 4.03

Photograph 4.04 Photograph of public display board located within Haviland Park. Haviland Park was utilised for the storage of stockpiles of gravel and sand during construction of the original dam wall

# Site 5a – Storage area









Photograph 5a.05

Photograph 5a.06



Photograph 5a.07

# Site 5b – Helipad/former houses





