

		PHOTOGRAPHIC LOG	
Client Name ARTC PS109315		Site Location Botany Freight Rail Line, Botany NSW.	
		Project Botany Rail Duplication EIS	

Photo No. 1	Date 06.07.2018	
Description View of the rail corridor access gate on the eastern side of the General Holmes Drive level crossing. Chainage 11.740 km.		

Photo No. 2	Date 06.07.2018	
Description General debris observed east of the General Holmes Drive level crossing Chainage 11.735 km (approximate).		

		PHOTOGRAPHIC LOG	
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS	

Photo No.	Date	
3	06.07.2018	
Description Significant earthworks observed in this area associated with the large scale construction site (John Holland). Unauthorised to proceed beyond this point due to narrow culvert/bridge. Chainage 11.600 km (approximate).		

Photo No.	Date	
4	06.07.2018	
Description View of the rail corridor access gate on the western side of the General Holmes Drive level crossing. Chainage 11.740 km.		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
5	06.07.2018	
Description View of the rail corridor facing west. Chainage 11.800 km (approximate).		

Photo No.	Date	
6	06.07.2018	
Description View of the rail corridor facing east. Chainage 11.800 km (approximate).		

		PHOTOGRAPHIC LOG	
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS	

Photo No.	Date	
7	06.07.2018	
Description View of the rail corridor facing west. Chainage 11.900 km (approximate).		

Photo No.	Date	
8	06.07.2018	
Description View of the rail corridor facing west. Chainage 11.950 km (approximate).		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
9	06.07.2018	
Description Groundwater monitoring well observed within the rail corridor. Chainage 12.000 km (approximate).		

Photo No.	Date	
10	06.07.2018	
Description View of the O'Riordan St Rail Bridge facing west. Unauthorised to proceed beyond this point due to narrow bridge. Chainage 12.200 km (approximate).		

		PHOTOGRAPHIC LOG	
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS	

Photo No.	Date	
11	06.07.2018	
Description View of the rail corridor access gate on Coleman Street. Chainage 12.650 km (approximate).		

Photo No.	Date	
12	06.07.2018	
Description View of electrical substation/maintenance building (1 of 2) Chainage 12.700 km (approximate).		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
13	06.07.2018	
Description View of the rail corridor facing north. Numerous fragments of ACM observed along building wall (right). Chainage 12.715 km (approximate).		

Photo No.	Date	
14	06.07.2018	
Description Close-up view of ACM sheet observed. Chainage 12.735 km (approximate).		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
15	06.07.2018	
Description Close-up view of ACM fragment observed. Chainage 12.735 km (approximate).		

Photo No.	Date	
16	06.07.2018	
Description View of the rail corridor facing west. Chainage 12.815 km (approximate).		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
17	06.07.2018	
Description View of the rail corridor facing east. Chainage 12.815 km (approximate).		

Photo No.	Date	
18	06.07.2018	
Description View of the rail corridor access gate on King Street. Chainage 12.910 km (approximate).		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
19	06.07.2018	
Description General debris and small uncharacterised stockpile observed. Chainage 12.910 km (approximate).		

Photo No.	Date	
20	06.07.2018	
Description General debris and rail sleepers storage area. Chainage 12.950 km (approximate).		

		PHOTOGRAPHIC LOG
Client Name ARTC PS109315	Site Location Botany Freight Rail Line, Botany NSW.	Project Botany Rail Duplication EIS

Photo No.	Date	
21	06.07.2018	
Description View of electrical substation/maintenance building (2 of 2). Chainage 12.975 km (approximate).		

Photo No.	Date	
22	06.07.2018	
Description View of Qantas Bridge facing west. Unauthorised to proceed beyond this point due to narrow rail corridor. Chainage 13.143 km (approximate).		



G2SJV Gateway to Sydney Joint Venture
WSP Australia Pty Limited and GHD Pty Ltd

ABN: 55 836 411 311



Project Office
Level 27 Ernst & Young Centre
680 George Street
Sydney NSW 2000

GPO Box 5394
Sydney NSW 2001

Tel: +61 2 9272 5100
Fax: +61 2 9272 5101