# **WaterNSW Work Summary**

## GW012325

Licence: Licence Status:

Authorised Purpose(s):

Intended Purpose(s): STOCK, DOMESTIC

Work Type: Bore Work Status: Abandoned Construct.Method: Cable Tool Owner Type: Private

**Commenced Date:** Final Depth: 45.70 m Completion Date: 01/02/1959 Drilled Depth: 45.70 m

Contractor Name: (None)

Driller:

**Assistant Driller:** 

Property: **Standing Water Level** 

Salinity Description: 501-1000 ppm GWMA: **GW Zone:** 

Yield (L/s):

### **Site Details**

Site Chosen By:

Parish Cadastre County Form A: BLIGH **TURRILL** 172

Licensed:

CMA Map: 8834-2S

River Basin: 421 - MACQUARIE RIVER **Grid Zone:** Scale:

Area/District:

Elevation: 0.00 m (A.H.D.) Northing: 6463861.000 Latitude: 31°55'40.3"S Elevation Source: (Unknown) **Easting:** 775163.000 Longitude: 149°54'37.2"E

GS Map: -MGA Zone: 55 Coordinate Source: GD., ACC. MAP

#### Construction

Negative depths indicate Above Ground Level; C-Cemented; SL-Slot Length; A-Aperture; GS-Grain Size; Q-Quantity; PL-Placement of Gravel Pack;

PC-Pressure Cemented: S-Sump: CE-Centralisers

Region: 80 - Macquarie-Western

Но	e Pipe	Component	Туре	From (m)	To (m)	Outside Diameter (mm)	Inside Diameter (mm)	Interval	Details
	1 1	Casing	Threaded Steel	-0.30	5.90	203			

Water Bearing Zones

		<u> </u>							
From (m)	To (m)	Thickness (m)	WBZ Type	S.W.L. (m)	D.D.L. (m)	Yield (L/s)	Hole Depth (m)	Duration (hr)	Salinity (mg/L)
6.70	7.30	0.60	Unconsolidated	5.20		0.76			

**Drillers Log** 

From	То	Thickness	Drillers Description	Geological Material	Comments
(m)	(m)	(m)			
0.00	0.61	0.61	Topsoil	Topsoil	
0.61	1.22	0.61	Basalt	Basalt	
1.22	1.83	0.61	Boulders Basalt	Boulders	
1.83	6.10	4.27	Boulders Gravel Clay	Boulders	
6.10	6.71	0.61	Clay	Clay	
6.71	7.32	0.61	Gravel	Gravel	
7.32	9.14	1.82	Clay	Clay	

17/11/2024, 12:44 realtimedata.waternsw.com.au/wgen/users/043349ba6de5449ab99ca229cf52ceb6/gw012325.agagpf\_org.wsr.htm?17318078...

9.	14 18.:	9.1	5 Sandstone	Sandstone	
18.	29 45.	'''		Clay	

### Remarks

17/10/2000: Coordinates surveyed on 18/9/2000.

03/07/2007: Nat Carling, 3-July-2007: Spoke to owner who advised that this mill does not existing anymore. Marked as abandoned.

\*\*\* End of GW012325 \*\*\*

Warning To Clients: This raw data has been supplied to the WaterNSW by drillers, licensees and other sources. WaterNSW does not verify the accuracy of this data. The data is presented for use by you at your own risk. You should consider verifying this data before relying on it. Professional hydrogeological advice should be sought in interpreting and using this data.