



Figure 39 Kangaroo Creek Swamp Waterhole 7 April 2014



Figure 40 Kangaroo Creek Swamp Waterhole 11 June 2014



Figure 41 Kangaroo Creek Swamp Waterhole 7 August 2014



**Kangaroo Creek Downstream Photo Monitoring: 30 August 2012 – 18  
September 2013**  
**Angus Place Colliery's LW910**

LW910 at Angus Place Colliery has not been mined as yet. For its location relative to Kangaroo Creek and Kangaroo Creek Swamp refer to Figure 2.2 in the Angus Place EIS.



Figure 1 Kangaroo Creek Downstream – Site 1 (Over LW910) 30 August 2012



Figure 2 Kangaroo Creek Downstream – Site 3 (Over LW910) 30 August 2012





Figure 3 Kangaroo Creek Downstream – Site 3 (Over LW910) 30 August 2012





Figure 4 Kangaroo Creek Downstream – Site 1 (Over LW910) 18 September 2013



Figure 5 Kangaroo Creek Downstream – Site 3 (Over LW910) 18 September 2013





Figure 6 Kangaroo Creek Downstream – Site 3 (Over LW910) 18 September 2013