

Parramatta Light Rail EIS **PART 2 Submission No. 1**
Victor P Taffa 23 August 2017

Route 1 Parramatta Park Line

Serving Rosehill Racecourse, Westmead, Parramatta Park, Parramatta Stadium

Route 2 North Ryde Line

Serving Macquarie University, Macquarie University Railway Station (Heavy Rail only), Macquarie Shopping Centre



Bridge Road Glebe Tram Overpass, 13 April 2017 some 60 years on



Pacific Highway, North Sydney Tram Overpass, 1957 with North Ryde to have a similar Tram Overpass across part of Epping Road

4/69a Darvall Road
West Ryde NSW 2114
PH: 02 9874 1542
PH: 0416 134 650

Achievements In Infrastructure

Bank Street Meadowbank Mail Boxes And Garbage Bin Bay

At 18-19 Bank Street Meadowbank I owned and lived in Unit 8. Minister for Veterans Affairs David Elliott also resided in the same block for some time.

Mail Box Unit and Garbage Bin Bay as organised and overseen by me containing:

- 21 Units Mail Box In Freestanding Red Brick Wall
- 1 Body Corporate Box
- 1 Space for Advertising Material
- 16 Bins in Red Brick Garbage Bin Bay

Garbage Bins had to be measured and enough room left to spare to get bins in and out of the Bin Bay.

I personally measured up the Bin Bay and gave required measurements to the Strata Company.

This Project would never have happened or ended so successfully had it not been for my persistence, determination and attention to detail.

Asking for this to happen did not occur at first request. However owners and residents were persuaded by me that monies had to be outlaid to build new Mail Box unit and Garbage Bin Bay.

Part of the problem with this project was that builders considered that this job was too small to worry about.

All 45 Photos taken by me illustrating start to finish of this project. Photos 1-24 are included here as follows:



NO. 1 Before construction began on left hand side of driveway



NO. 2 Before construction began on right hand side of driveway with broken brick wall



NO. 3 Before construction began with broken brick wall and leaning brick wall



NO. 4 Before construction began with broken brick wall and leaning brick wall



NO. 5 Front entrance of driveway with steep slope



NO. 6 Before construction began on right hand side of driveway



NO. 7 Before construction began facing left hand side of driveway



NO. 8 Before construction began in lawn area and garbage bin storage



NO. 9 Before construction began in lawn area and garbage bin storage



NO. 10 Before construction began in lawn area and garbage bin storage



NO. 11 Before construction began with broken brick wall and leaning brick wall



NO. 12 Before construction began in garden area and garbage bin storage



NO. 13 Demolished mail boxes, garbage bin storage with steep slope of driveway



NO. 14 Demolished mail boxes, garbage bin storage with steep slope of driveway



NO. 15 Preparing foundation of mail box brick wall



NO. 16 Preparing foundations for garbage bin bay



NO. 17 Preparing foundations for garbage bin bay



NO. 18 Preparing foundations for garbage bin bay



NO. 19 Preparing foundations for driveway brick wall and wider sweep of driveway



NO. 20 Foundation laid and marked for mail box wall and removal of solid asbestos sheets



NO. 21 Foundation marked for driveway brick wall and wider sweep of driveway



NO. 22 Mail box wall construction commences



NO. 23 Garbage bin bay construction commences



NO. 24 Mail box wall completed