

Road ways

Rushes Creek Road Intersection to the Oxley Highway.



As you can see in the picture from Google Street View the divided road and shoulder lines disappear in the distance as the road heads towards the proposed farm.

Also in the picture you can see that there has been a turn out merging lane added to the road for another high intensity farm with eight sheds that is located on the property to the right of the picture.

The dividing centre line is not present in the picture even before the intersection for the above mentioned farm for approximately 500m through a narrow section of the road with corners with low visibility. Centre line is then only present on the road for approximately 500m. The road continues with no safe shoulder or centre lining for approximately 17Km to proposed property entrance.

There is no safe turning lane into or out of the Lake Keepit State Park for traffic also with no dividing lines.

No signage is on the road for possible slow moving trucks and Turning trucks.

There appears to be no intersection development to Rushes Creek Road where the proposed far is to have entering and exiting traffic.