


Archival Photographic Recording of Queanbeyan Hospital

Collett St Queanbeyan NSW



Photographed by Nathanael Hughes
April 2006



nathanael hughes
photographer

April 2006


Archival Photographic Recording of Queanbeyan Hospital

The photographic recording has been completed to NSW Heritage Office archival standards. The buildings exterior, interior and surrounds have been documented using 120 and 35mm B&W film and colour transparencies. The images have been scanned and placed on CDR as (.jpg) files. Documentation has been converted to Acrobat pdf files for cross platform use and placed on CDR.

All Black and White negatives have been processed & proofed to archival standard and all film and transparencies have been placed in archival quality holders. Thumbnails of each image are included in the report and all documentation has been printed on high quality low acid laser paper. The position and direction of where the image was taken have been marked on the plan.

Only the buildings that have been proposed for demolition or major works were recorded for this report. All exteriors were photographed but a sampling approach was taken with the buildings interiors with the exception of Rusten House where a complete recording was done.

Site Location Map



Location	Description	Image
Main Hospital Building	NW elevation of administration section	
Image Reference Queanbeyan_120BW_R1_001.JPG		
Main Hospital Building	NE elevation of administration section	
Image Reference Queanbeyan_120BW_R1_002.JPG		
Main Hospital Building	NE elevation of administration section	
Image Reference Queanbeyan_120BW_R1_003.JPG		
Main Hospital Building	Northern corner elevation of Laundry section	
Image Reference Queanbeyan_120BW_R1_004.JPG		
Main Hospital Building	SE elevation of administration section	
Image Reference Queanbeyan_120BW_R1_005.JPG		

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_120BW_R1_006.JPG	SE elevation and entrance to administration section note memorial rose garden in foreground	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_007.JPG	1932 Ward section. Sectional view - NW end of NE elevation	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_008.JPG	1932 Ward section. Sectional view - Central NE elevation	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_009.JPG	1932 Ward section. Sectional view - SE end of NE elevation & NW end of NE elevation of Conference section	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_010.JPG	Sectional view - NE elevation of Wards, Pathology, X Ray & SE end of NE elevation of Conference section	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_120BW_R1_011.JPG	NE elevation of Wards, Pathology, X Ray & SE end of NE elevation of Conference section and Main Drive entrance to emergency	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_012.JPG	SE elevation of Wards, Pathology, X Ray	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_013.JPG	SE elevation of Conference, intensive care and NE elevation of Wards, Pathology, X Ray	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_014.JPG	SE elevation of Emergency, Obstetrics Section - main entrance	
Main Hospital Building Image Reference Queanbeyan_120BW_R1_015.JPG	SE elevation of Emergency, Obstetrics Section	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_120BW_R2_001.JPG	SE elevation of Emergency, Obstetrics Section	
Main Hospital Building Image Reference Queanbeyan_120BW_R2_002.JPG	SW elevation of Emergency, Obstetrics Section and Staff room	
Main Hospital Building Image Reference Queanbeyan_120BW_R2_003.JPG	SW elevation of Emergency, Obstetrics Section and Staff room	
Main Hospital Building Image Reference Queanbeyan_120BW_R2_004.JPG	NE elevation of Emergency, Obstetrics section	
Main Hospital Building Image Reference Queanbeyan_120BW_R2_005.JPG	NE elevation of Emergency, Obstetrics section	

Location	Description	Image
Main Hospital Building	SW elevation of Education Center section & private wing	
Image Reference Queanbeyan_120BW_R2_006.JPG		
Main Hospital Building	SW elevation of Laundry, Staff accommodation, infil with linen shed left of image	
Image Reference Queanbeyan_120BW_R2_007.JPG		
Main Hospital Building	Western corner elevation of Laundry, Staff accommodation and infil	
Image Reference Queanbeyan_120BW_R2_008.JPG		
Main Hospital Building	SW elevation of Educational center and driveway	
Image Reference Queanbeyan_120BW_R2_009.JPG		
Main Hospital Building	SW elevation of Laundry section	
Image Reference Queanbeyan_120BW_R2_010.JPG		

Location	Description	Image
Occupational Therapy	Northern corner elevation	
Image Reference Queanbeyan_120BW_R2_011.JPG		
Occupational Therapy	NE elevation	
Image Reference Queanbeyan_120BW_R2_012.JPG		
Occupational Therapy	Western corner elevation	
Image Reference Queanbeyan_120BW_R2_013.JPG		
Occupational Therapy	SE elevation	
Image Reference Queanbeyan_120BW_R2_014.JPG		
Occupational Therapy	SE end of SW elevation and entrance	
Image Reference Queanbeyan_120BW_R2_015.JPG		

Location	Description	Image
Occupational Therapy	NW end of SW elevation	
Image Reference Queanbeyan_120BW_R3_001.JPG		
Mental Health Building	NW elevation	
Image Reference Queanbeyan_120BW_R3_002.JPG		
Mental Health Building	NE elevation	
Image Reference Queanbeyan_120BW_R3_003.JPG		
Mental Health Building	Eastern corner elevation	
Image Reference Queanbeyan_120BW_R3_004.JPG		
Mental Health Building	NE elevation of SE wing	
Image Reference Queanbeyan_120BW_R3_005.JPG		


Location	Description	Image
Mental Health Building	SE elevation of SE wing	
Image Reference Queanbeyan_120BW_R3_006.JPG		
Mental Health Building	Southern corner elevation	
Image Reference Queanbeyan_120BW_R3_007.JPG		
Mental Health Building	SW elevation	
Image Reference Queanbeyan_120BW_R3_008.JPG		
Rusten House	NE end of NW elevation	
Image Reference Queanbeyan_120BW_R3_009.JPG		
Rusten House	SW end of NW elevation	
Image Reference Queanbeyan_120BW_R3_010.JPG		

Location	Description	Image
Rusten House	Northern corner elevation	
Image Reference Queanbeyan_120BW_R3_011.JPG		
Rusten House	Western corner elevation	
Image Reference Queanbeyan_120BW_R3_012.JPG		
Rusten House	Southern corner elevation	
Image Reference Queanbeyan_120BW_R3_013.JPG		
Rusten House	SE elevation	
Image Reference Queanbeyan_120BW_R3_014.JPG		
Rusten House	NE end of SE elevation	
Image Reference Queanbeyan_120BW_R3_015.JPG		

Location	Description	Image
Old Dental Building	Northern Corner elevation	
Image Reference Queanbeyan_120BW_R4_001.JPG		
Old Dental Building	NE elevation	
Image Reference Queanbeyan_120BW_R4_002.JPG		
Old Dental Building	Southern corner elevation	
Image Reference Queanbeyan_120BW_R4_003.JPG		
Old Dental Building	SE elevation	
Image Reference Queanbeyan_120BW_R4_004.JPG		
Community Health Building	SE elevation	
Image Reference Queanbeyan_120BW_R4_005.JPG		

Location	Description	Image
Community Health Building	SE elevation	
Image Reference Queanbeyan_120BW_R4_006.JPG		
Community Health Building	Southern corner elevation	
Image Reference Queanbeyan_120BW_R4_007.JPG		
Old Dental Building	Western corner elevation	
Image Reference Queanbeyan_120BW_R4_008.JPG		
Community Health Building	NW elevation	
Image Reference Queanbeyan_120BW_R4_009.JPG		
Community Health Building	SW elevation of NE wing and overview of playground	
Image Reference Queanbeyan_120BW_R4_010.JPG		

Location	Description	Image
Community Health Building	NE end of NW elevation	
Image Reference Queanbeyan_120BW_R4_011.JPG		
Community Health Building	SW end of NW elevation	
Image Reference Queanbeyan_120BW_R4_012.JPG		



Location	Description	Image
Main Hospital Building	NW elevation of administration section	
Image Reference Queanbeyan_120COL_R1_001.JPG		
Main Hospital Building	NE elevation of administration section	
Image Reference Queanbeyan_120COL_R1_002.JPG		
Main Hospital Building	NE elevation of administration section	
Image Reference Queanbeyan_120COL_R1_003.JPG		
Main Hospital Building	Northern corner elevation of Laundry section	
Image Reference Queanbeyan_120COL_R1_004.JPG		
Main Hospital Building	SE elevation of administration section	
Image Reference Queanbeyan_120COL_R1_005.JPG		

Location	Description	Image
Main Hospital Building	SE elevation and entrance to administration section note memorial rose garden in foreground	
Image Reference Queanbeyan_120COL_R1_006.JPG		
Main Hospital Building	1932 Ward section. Sectional view - NW end of NE elevation	
Image Reference Queanbeyan_120COL_R1_007.JPG		
Main Hospital Building	1932 Ward section. Sectional view - Central NE elevation	
Image Reference Queanbeyan_120COL_R1_008.JPG		
Main Hospital Building	1932 Ward section. Sectional view - SE end of NE elevation & NW end of NE elevation of Conference section	
Image Reference Queanbeyan_120COL_R1_009.JPG		
Main Hospital Building	Sectional view - NE elevation of Wards, Pathology, X-ray & SE end of NE elevation of Conference section	
Image Reference Queanbeyan_120COL_R1_010.JPG		

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_120COL_R1_011.JPG	NE elevation of Wards, Pathology, X-ray & SE end of NE elevation of Conference section and Main Drive entrance to emergency	
Main Hospital Building Image Reference Queanbeyan_120COL_R1_012.JPG	SE elevation of Wards, Pathology, X-ray	
Main Hospital Building Image Reference Queanbeyan_120COL_R1_013.JPG	SE elevation of Conference, intensive care and NE elevation of Wards, Pathology, X-ray	
Main Hospital Building Image Reference Queanbeyan_120COL_R1_014.JPG	SE elevation of Emergency, Obstetrics Section - main entrance	
Main Hospital Building Image Reference Queanbeyan_120COL_R1_015.JPG	SE elevation of Emergency, Obstetrics Section	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_120COL_R2_001.JPG	SE elevation of Emergency, Obstetrics Section	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_002.JPG	SW elevation of Emergency, Obstetrics Section and Staff room	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_003.JPG	SW elevation of Emergency, Obstetrics Section and Staff room	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_004.JPG	NE elevation of Emergency, Obstetrics section	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_005.JPG	NE elevation of Emergency, Obstetrics section	


Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_120COL_R2_006.JPG	SW elevation of Education Center section & private wing	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_007.JPG	SW elevation of Laundry, Staff accommodation, infil with linen shed left of image	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_008.JPG	Western corner elevation of Laundry, Staff accommodation and infil	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_009.JPG	SW elevation of Educational center and driveway	
Main Hospital Building Image Reference Queanbeyan_120COL_R2_010.JPG	SW elevation of Laundry section	


Location	Description	Image
Occupational Therapy	Northern corner elevation	
Image Reference Queanbeyan_120COL_R2_011.JPG		
Occupational Therapy	NE elevation	
Image Reference Queanbeyan_120COL_R2_012.JPG		
Occupational Therapy	Western corner elevation	
Image Reference Queanbeyan_120COL_R2_013.JPG		
Occupational Therapy	SE elevation	
Image Reference Queanbeyan_120COL_R2_014.JPG		
Occupational Therapy	SE end of SW elevation and entrance	
Image Reference Queanbeyan_120COL_R2_015.JPG		

Location	Description	Image
Occupational Therapy	NW end of SW elevation	
Image Reference Queanbeyan_120COL_R3_001.JPG		
Mental Health Building	NW elevation	
Image Reference Queanbeyan_120COL_R3_002.JPG		
Mental Health Building	NE elevation	
Image Reference Queanbeyan_120COL_R3_003.JPG		
Mental Health Building	Eastern corner elevation	
Image Reference Queanbeyan_120COL_R3_004.JPG		
Mental Health Building	NE elevation of SE wing	
Image Reference Queanbeyan_120COL_R3_005.JPG		

Location	Description	Image
Mental Health Building	SE elevation of SE wing	
Image Reference Queanbeyan_120COL_R3_006.JPG		
Mental Health Building	Southern corner elevation	
Image Reference Queanbeyan_120COL_R3_007.JPG		
Mental Health Building	SW elevation	
Image Reference Queanbeyan_120COL_R3_008.JPG		
Rusten House	NE end of NW elevation	
Image Reference Queanbeyan_120COL_R3_009.JPG		
Rusten House	SW end of NW elevation	
Image Reference Queanbeyan_120COL_R3_010.JPG		



Location	Description	Image
Rusten House	Northern corner elevation	
Image Reference Queanbeyan_120COL_R3_011.JPG		
Rusten House	Western corner elevation	
Image Reference Queanbeyan_120COL_R3_012.JPG		
Rusten House	Southern corner elevation	
Image Reference Queanbeyan_120COL_R3_013.JPG		
Rusten House	SE elevation	
Image Reference Queanbeyan_120COL_R3_014.JPG		
Rusten House	NE end of SE elevation	
Image Reference Queanbeyan_120COL_R3_015.JPG		



Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_001.jpg	Driveway and Memorial gardens facing SW from near Administration entrance	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_002.jpg	Memorial rose garden near near Administration entrance	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_003.jpg	Administration entrance	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_004.jpg	Administration section foyer entrance	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_005.jpg	Administration section NE SW hallway facing NE from foyer entrance	

Location	Description	Image
Main Hospital Building	Administration section NE SW hallway overview of plaques on wall	
Image Reference Queanbeyan_35mmBW_R1_006.jpg		
Main Hospital Building	Administration section NE SW hallway facing NE from central NW SE corridor	
Image Reference Queanbeyan_35mmBW_R1_007.jpg		
Main Hospital Building	1932 Wards section facing SE along central NW SE corridor	
Image Reference Queanbeyan_35mmBW_R1_008.jpg		
Main Hospital Building	1932 Wards section facing SE along central NW SE corridor near kitchen block	
Image Reference Queanbeyan_35mmBW_R1_009.jpg		
Main Hospital Building	Kitchen section NW side of kitchen	
Image Reference Queanbeyan_35mmBW_R1_010.jpg		

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_011.jpg	Kitchen section SW side of kitchen	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_012.jpg	Overview of Staff dining room	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_013.jpg	Education section foyer and old theatre entrance	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_014.jpg	view along corridor with intact period skirting boards and architrave	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_015.jpg	Private Wing Overview facing South from entrance	

Location	Description	Image
Main Hospital Building	Ramp on SW side of Conference section note life members board of left of image	
Image Reference Queanbeyan_35mmBW_R1_016.jpg		
Main Hospital Building	1932 Wards section facing SE along central NW SE hallway	
Image Reference Queanbeyan_35mmBW_R1_017.jpg		
Main Hospital Building	1932 Wards section facing NW along central NW SE hallway	
Image Reference Queanbeyan_35mmBW_R1_018.jpg		
Main Hospital Building	1932 Wards section overview of typical ward	
Image Reference Queanbeyan_35mmBW_R1_019.jpg		
Main Hospital Building	Conference section overview of conference room 1st floor	
Image Reference Queanbeyan_35mmBW_R1_020.jpg		



Location	Description	Image
Main Hospital Building	Obstetrics section facing SW along NE SW hallway from outside shop 1st floor	
Image Reference Queanbeyan_35mmBW_R1_021.jpg		
Main Hospital Building	Obstetrics section facing SW along NE SW hallway 1st floor	
Image Reference Queanbeyan_35mmBW_R1_022.jpg		
Main Hospital Building	Obstetrics section facing NE along NE SW hallway 1st floor	
Image Reference Queanbeyan_35mmBW_R1_023.jpg		
Main Hospital Building	Obstetrics section overview of ward 1st floor	
Image Reference Queanbeyan_35mmBW_R1_024.jpg		
Main Hospital Building	Wards Pathology X-ray section Ward in Eastern corner 1st floor	
Image Reference Queanbeyan_35mmBW_R1_025.jpg		

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_026.jpg	Wards Pathology X-ray section Ward in Eastern corner 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_027.jpg	Wards Pathology X-ray section Ward in Southern corner 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_028.jpg	Wards Pathology X-ray section Central stair well	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_029.jpg	Wards Pathology X-ray section Ground floor hallway to waiting room outside X-ray	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_030.jpg	Emergency section Ground floor, facing SW along corridor from outside lift	




Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_031.jpg	Emergency section Ground floor facing SE towards entrance	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_032.jpg	Emergency section Ground floor Historical Images Frame on wall outside reception on ground floor	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_033.jpg	Emergency section Ground floor Overview of area outside theatre	
Main Hospital Building Image Reference Queanbeyan_35mmBW_R1_034.jpg	Emergency section Ground floor Overview of recovery and area outside theatre	
Occupational Therapy Building Image Reference Queanbeyan_35mmBW_R2_001.jpg	Detail of Plaque on NE entrance	



Location	Description	Image
Occupational Therapy Building	View along corridor to offices	
Image Reference Queanbeyan_35mmBW_R2_002.jpg		
Occupational Therapy Building	Detail of typical ceiling and cornice from more recent refurbish	
Image Reference Queanbeyan_35mmBW_R2_003.jpg		
Occupational Therapy Building	Detail of windows in central office area	
Image Reference Queanbeyan_35mmBW_R2_004.jpg		
Occupational Therapy Building	Overview of kitchen in Southern corner	
Image Reference Queanbeyan_35mmBW_R2_005.jpg		
Occupational Therapy Building	Overview of Therapy room	
Image Reference Queanbeyan_35mmBW_R2_006.jpg		




Location	Description	Image
Occupational Therapy Building	Overview of Therapy room	
Image Reference Queanbeyan_35mmBW_R2_007.jpg		
Rusten House	Enclosed NW verandah in Western corner of building	
Image Reference Queanbeyan_35mmBW_R2_008.jpg		
Rusten House	Enclosed NW verandah in Western corner of building	
Image Reference Queanbeyan_35mmBW_R2_009.jpg		
Rusten House	Store in Western corner of building	
Image Reference Queanbeyan_35mmBW_R2_010.jpg		
Rusten House	Room in Western corner of building	
Image Reference Queanbeyan_35mmBW_R2_011.jpg		

Location	Description	Image
Rusten House	View along NW SE corridor to social workers room	
Image Reference Queanbeyan_35mmBW_R2_012.jpg		
Rusten House	View along NW SE corridor to NW entrance	
Image Reference Queanbeyan_35mmBW_R2_013.jpg		
Rusten House	Overview of group room	
Image Reference Queanbeyan_35mmBW_R2_014.jpg		
Rusten House	Overview of group room	
Image Reference Queanbeyan_35mmBW_R2_015.jpg		
Rusten House	Detail of pressed metal ceiling in group room	
Image Reference Queanbeyan_35mmBW_R2_016.jpg		




Location	Description	Image
Rusten House	Overview of kitchen	
Image Reference Queanbeyan_35mmBW_R2_017.jpg		
Rusten House	Overview of office	
Image Reference Queanbeyan_35mmBW_R2_018.jpg		
Rusten House	Overview of Social workers office in Southern corner of building	
Image Reference Queanbeyan_35mmBW_R2_019.jpg		
Rusten House	Overview of Social workers office in Southern corner of building	
Image Reference Queanbeyan_35mmBW_R2_020.jpg		
Rusten House	Detail of typical door in social workers office in Southern corner of building	
Image Reference Queanbeyan_35mmBW_R2_021.jpg		



Location	Description	Image
Rusten House	View along NW SE corridor in central part of building	
Image Reference Queanbeyan_35mmBW_R2_022.jpg		
Rusten House	View along NW SE corridor in central part of building	
Image Reference Queanbeyan_35mmBW_R2_023.jpg		
Rusten House	Overview of NW office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_024.jpg		
Rusten House	Overview of NW office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_025.jpg		
Rusten House	Overview of SE office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_026.jpg		



Location	Description	Image
Rusten House	Overview of SE office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_027.jpg		
Rusten House	Detail of intact period architrave's in SE office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_028.jpg		
Rusten House	Overview of resources room adjoining SE office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_029.jpg		
Rusten House	Overview of resources room adjoining SE office in central part of building	
Image Reference Queanbeyan_35mmBW_R2_030.jpg		
Rusten House	NW Bathroom adjacent to Resources room	
Image Reference Queanbeyan_35mmBW_R2_031.jpg		

Location	Description	Image
Rusten House	NW Bathroom adjacent to Resources room	
Image Reference Queanbeyan_35mmBW_R2_032.jpg		
Rusten House	NW verandah	
Image Reference Queanbeyan_35mmBW_R2_033.jpg		
Rusten House	NW verandah and entrances to Therapy room on left, store center frame and sexual assault workers rooms	
Image Reference Queanbeyan_35mmBW_R2_034.jpg		
Rusten House	Hallway to sexual assault workers rooms	
Image Reference Queanbeyan_35mmBW_R2_035.jpg		
Rusten House	Hallway to sexual assault workers rooms note typical door	
Image Reference Queanbeyan_35mmBW_R2_036.jpg		

Location	Description	Image
Rusten House	Detail of pressed metal ceiling in hallway	
Image Reference Queanbeyan_35mmBW_R3_001.jpg		
Rusten House	Overview of NW office in sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_002.jpg		
Rusten House	Detail of picture rail and painted over wallpaper in NW office in sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_003.jpg		
Rusten House	Detail of pressed metal ceiling in NW office in sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_004.jpg		
Rusten House	Overview of kitchenette in central room of sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_005.jpg		


Location	Description	Image
Rusten House	Overview of central room of sexual assault workers section door to WC in center of image	
Image Reference Queanbeyan_35mmBW_R3_006.jpg		
Rusten House	Office in SE part of sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_007.jpg		
Rusten House	Office in SE part of sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_008.jpg		
Rusten House	WC off central room in sexual assault workers section	
Image Reference Queanbeyan_35mmBW_R3_009.jpg		
Rusten House	Store off NW verandah	
Image Reference Queanbeyan_35mmBW_R3_010.jpg		

Location	Description	Image
Rusten House	Therapy room in NE end of building	
Image Reference Queanbeyan_35mmBW_R3_011.jpg		
Rusten House	Therapy room in NE end of building	
Image Reference Queanbeyan_35mmBW_R3_012.jpg		
Rusten House	Detail of pressed metal ceiling in Therapy room in NE end of building	
Image Reference Queanbeyan_35mmBW_R3_013.jpg		
Rusten House	Detail of pressed metal ceiling and cornice in Therapy room in NE end of building	
Image Reference Queanbeyan_35mmBW_R3_014.jpg		
Rusten House	Overview of fireplace in Therapy room in NE end of building	
Image Reference Queanbeyan_35mmBW_R3_015.jpg		

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmBW_R3_016.jpg	Kitchen on Eastern corner off therapy room in NE end of building	
Rusten House Image Reference Queanbeyan_35mmBW_R3_017.jpg	Kitchen on Eastern corner off therapy room in NE end of building	
Rusten House Image Reference Queanbeyan_35mmBW_R3_018.jpg	NE verandah	
Rusten House Image Reference Queanbeyan_35mmBW_R3_019.jpg	NE verandah	
Rusten House Image Reference Queanbeyan_35mmBW_R3_020.jpg	Detail of window on NE verandah	

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmBW_R3_021.jpg	Detail of typical vent on NE verandah	
Rusten House Image Reference Queanbeyan_35mmBW_R3_022.jpg	Detail of sandstone, rose vent on central part of NW elevation	
Rusten House Image Reference Queanbeyan_35mmBW_R3_023.jpg	Overview of store on SE side of building	
Mental Health Building Image Reference Queanbeyan_35mmBW_R3_024.jpg	View along NE SW corridor	
Mental Health Building Image Reference Queanbeyan_35mmBW_R3_025.jpg	View along NE SW corridor	

Location	Description	Image
Mental Health Building	View along NE SW corridor	
Image Reference Queanbeyan_35mmBW_R3_026.jpg		
Mental Health Building	Overview of typical office	
Image Reference Queanbeyan_35mmBW_R3_027.jpg		
Mental Health Building	Detail of typical window cornice and wall vents in office and through out building	
Image Reference Queanbeyan_35mmBW_R3_028.jpg		
Mental Health Building	Detail of typical door on offices	
Image Reference Queanbeyan_35mmBW_R3_029.jpg		
Mental Health Building	View along NW SE corridor	
Image Reference Queanbeyan_35mmBW_R3_030.jpg		

Location	Description	Image
Mental Health Building	View along NE SW corridor from SW end	
Image Reference Queanbeyan_35mmBW_R3_031.jpg		
Mental Health Building	View along NW SE corridor	
Image Reference Queanbeyan_35mmBW_R3_032.jpg		
Mental Health Building	Overview of SW end office in Southern corner of building note fireplace in center	
Image Reference Queanbeyan_35mmBW_R3_033.jpg		
Mental Health Building	Overview of NE end office in Southern corner of building	
Image Reference Queanbeyan_35mmBW_R3_034.jpg		
Mental Health Building	Overview of office in Eastern corner of SE wing	
Image Reference Queanbeyan_35mmBW_R3_035.jpg		

Site Name: Queanbeyan Hospital

Date: 4th April 2006

Location: Queanbeyan NSW

Film Type: 35mm B&W Ilford fp4 plus

ISO: 125

Roll Numbers 1-3

Location	Description	Image
Mental Health Building	Overview of conference room	
Image Reference Queanbeyan_35mmBW_R3_036.jpg		


Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_001.JPG	Driveway and Memorial gardens facing SW from near Administration entrance	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_002.JPG	Memorial rose garden near near Administration entrance	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_003.JPG	Administration entrance	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_004.JPG	Administration section foyer entrance	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_005.JPG	Administration section NE SW hallway facing NE from foyer entrance	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_006.JPG	Administration section NE SW hallway overview of plaques on wall	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_007.JPG	Administration section NE SW hallway facing NE from central NW SE corridor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_008.JPG	1932 Wards section facing SE along central NW SE corridor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_009.JPG	1932 Wards section facing SE along central NW SE corridor near kitchen block	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_010.JPG	Kitchen section NW side of kitchen	


Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_011.JPG	Kitchen section SW side of kitchen	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_012.JPG	Overview of Staff dining room	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_013.JPG	Education section foyer and old theatre entrance	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_014.JPG	view along corridor with intact period skirting boards and architrave	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_015.JPG	Private Wing Overview facing South from entrance	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_016.JPG	Ramp on SW side of Conference section note life members board of left of image	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_017.JPG	1932 Wards section facing SE along central NW SE hallway	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_018.JPG	1932 Wards section facing NW along central NW SE hallway	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_019.JPG	1932 Wards section overview of typical ward	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_020.JPG	Conference section overview of conference room 1st floor	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_021.JPG	Obstetrics section facing SW along NE SW hallway from outside shop 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_022.JPG	Obstetrics section facing SW along NE SW hallway 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_023.JPG	Obstetrics section facing NE along NE SW hallway 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_024.JPG	Obstetrics section overview of ward 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_025.JPG	Wards Pathology X-ray section Ward in Eastern corner 1st floor	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_026.JPG	Wards Pathology X-ray section Ward in Eastern corner 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_027.JPG	Wards Pathology X-ray section Ward in Southern corner 1st floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_028.JPG	Wards Pathology X-ray section Central stair well	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_029.JPG	Wards Pathology X-ray section Ground floor hallway to waiting room outside X-ray	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_030.JPG	Emergency section Ground floor, facing SW along corridor from outside lift	

Location	Description	Image
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_031.JPG	Emergency section Ground floor facing SE towards entrance	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_032.JPG	Emergency section Ground floor Historical Images Frame on wall outside reception on ground floor	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_033.JPG	Emergency section Ground floor Overview of area outside theatre	
Main Hospital Building Image Reference Queanbeyan_35mmCOL_R1_034.JPG	Emergency section Ground floor Overview of recovery and area outside theatre	
Occupational Therapy Building Image Reference Queanbeyan_35mmCOL_R2_001.JPG	Detail of Plaque on NE entrance	


Location	Description	Image
Occupational Therapy Building	View along corridor to offices	
Image Reference Queanbeyan_35mmCOL_R2_002.JPG		
Occupational Therapy Building	Detail of windows in central office area	
Image Reference Queanbeyan_35mmCOL_R2_003.JPG		
Occupational Therapy Building	Overview of kitchen in Southern corner	
Image Reference Queanbeyan_35mmCOL_R2_004.JPG		
Occupational Therapy Building	Overview of Therapy room	
Image Reference Queanbeyan_35mmCOL_R2_005.JPG		
Occupational Therapy Building	Overview of Therapy room	
Image Reference Queanbeyan_35mmCOL_R2_006.JPG		

Location	Description	Image
Rusten House	Enclosed NW verandah in Western corner of building	
Image Reference Queanbeyan_35mmCOL_R2_007.JPG		
Rusten House	Enclosed NW verandah in Western corner of building	
Image Reference Queanbeyan_35mmCOL_R2_008.JPG		
Rusten House	Store in Western corner of building	
Image Reference Queanbeyan_35mmCOL_R2_009.JPG		
Rusten House	Room in Western corner of building	
Image Reference Queanbeyan_35mmCOL_R2_010.JPG		
Rusten House	View along NW SE corridor to social workers room	
Image Reference Queanbeyan_35mmCOL_R2_011.JPG		

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R2_012.JPG	View along NW SE corridor to NW entrance	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_013.JPG	Overview of group room	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_014.JPG	Overview of group room	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_015.JPG	Detail of pressed metal ceiling in group room	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_016.JPG	Overview of kitchen	

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R2_017.JPG	Overview of office	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_018.JPG	Overview of Social workers office in Southern corner of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_019.JPG	Overview of Social workers office in Southern corner of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_020.JPG	Detail of typical door in social workers office in Southern corner of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_021.JPG	View along NW SE corridor in central part of building	

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R2_022.JPG	View along NW SE corridor in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_023.JPG	Overview of NW office in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_024.JPG	Overview of NW office in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_025.JPG	Overview of SE office in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_026.JPG	Overview of SE office in central part of building	

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R2_027.JPG	Detail of intact period architrave's in SE office in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_028.JPG	Overview of resources room adjoining SE office in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_029.JPG	Overview of resources room adjoining SE office in central part of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_030.JPG	NW Bathroom adjacent to Resources room	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_031.JPG	NW Bathroom adjacent to Resources room	

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R2_032.JPG	NW verandah	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_033.JPG	NW verandah and entrances to Therapy room on left, store center frame and sexual assault workers rooms	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_034.JPG	Hallway to sexual assault workers rooms note typical door	
Rusten House Image Reference Queanbeyan_35mmCOL_R2_035.JPG	Detail of pressed metal ceiling in hallway	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_001.JPG	Overview of NW office in sexual assault workers section	

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R3_002.JPG	Detail of picture rail and painted over wallpaper in NW office in sexual assault workers section	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_003.JPG	Detail of pressed metal ceiling in NW office in sexual assault workers section	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_004.JPG	Overview of kitchenette in central room of sexual assault workers section	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_005.JPG	Overview of central room of sexual assault workers section door to WC in center of image	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_006.JPG	Office in SE part of sexual assault workers section	


Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R3_007.JPG	Office in SE part of sexual assault workers section	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_008.JPG	WC off central room in sexual assault workers section	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_009.JPG	Store off NW verandah	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_010.JPG	Therapy room in NE end of building	
Rusten House Image Reference Queanbeyan_35mmCOL_R3_011.JPG	Therapy room in NE end of building	

Location	Description	Image
Rusten House	Detail of pressed metal ceiling and cornice in Therapy room in NE end of building	
Image Reference Queanbeyan_35mmCOL_R3_012.JPG		
Rusten House	Overview of fireplace in Therapy room in NE end of building	
Image Reference Queanbeyan_35mmCOL_R3_013.JPG		
Rusten House	Kitchen on Eastern corner off therapy room in NE end of building	
Image Reference Queanbeyan_35mmCOL_R3_014.JPG		
Rusten House	Kitchen on Eastern corner off therapy room in NE end of building	
Image Reference Queanbeyan_35mmCOL_R3_015.JPG		
Rusten House	NE verandah	
Image Reference Queanbeyan_35mmCOL_R3_016.JPG		

Location	Description	Image
Rusten House	NE verandah	
Image Reference Queanbeyan_35mmCOL_R3_017.JPG		
Rusten House	Detail of window on NE verandah	
Image Reference Queanbeyan_35mmCOL_R3_018.JPG		
Rusten House	Detail of typical vent on NE verandah	
Image Reference Queanbeyan_35mmCOL_R3_019.JPG		
Rusten House	Detail of sandstone, rose vent on central part of NW elevation	
Image Reference Queanbeyan_35mmCOL_R3_020.JPG		
Rusten House	Overview of store on SE side of building	
Image Reference Queanbeyan_35mmCOL_R3_021.JPG		

Location	Description	Image
Rusten House Image Reference Queanbeyan_35mmCOL_R3_022.JPG	Detail of sill on central SE section of building	
Mental Health Building Image Reference Queanbeyan_35mmCOL_R3_023.JPG	View along NE SW corridor	
Mental Health Building Image Reference Queanbeyan_35mmCOL_R3_024.JPG	View along NE SW corridor	
Mental Health Building Image Reference Queanbeyan_35mmCOL_R3_025.JPG	Overview of typical office	
Mental Health Building Image Reference Queanbeyan_35mmCOL_R3_026.JPG	Detail of typical window cornice and wall vents in office and through out building	



Location	Description	Image
Mental Health Building	Detail of typical door on offices	
Image Reference Queanbeyan_35mmCOL_R3_027.JPG		
Mental Health Building	View along NW SE corridor	
Image Reference Queanbeyan_35mmCOL_R3_028.JPG		
Mental Health Building	View along NE SW corridor from SW end	
Image Reference Queanbeyan_35mmCOL_R3_029.JPG		
Mental Health Building	View along NW SE corridor	
Image Reference Queanbeyan_35mmCOL_R3_030.JPG		
Mental Health Building	Overview of SW end office in Southern corner of building note fireplace in center	
Image Reference Queanbeyan_35mmCOL_R3_031.JPG		

Location	Description	Image
Mental Health Building	Overview of NE end office in Southern corner of building	
Image Reference Queanbeyan_35mmCOL_R3_032.JPG		
Mental Health Building	Overview of office in Eastern corner of SE wing	
Image Reference Queanbeyan_35mmCOL_R3_033.JPG		
Mental Health Building	Overview of conference room	
Image Reference Queanbeyan_35mmCOL_R3_034.JPG		

35mm Black and White Negatives



Rusten House


35mm Colour Transparencies



not to scale







Lower Ground Floor