



Key:

✕ Sample locations

— Investigation area



Figure 2 : Farm shed sample locations

19038 R02

Site: 771 Cudgen Road
Location: Cudgen, NSW
Details: Soil and groundwater investigation

Client: Lendlease
Drawn: Glen Chisnall
Source: Google Earth



Key:



Sample locations



Investigation area



Sedimentary fence



Former garage

SL19
X

SL20
X

Former residential house

SL22
X

SL21
X

Cudgen Road

1:282



Source: Six Maps

Figure 3: Residential house sample locations

19038 R02

Site: 771 Cudgen Road

Location: Cudgen, NSW

Details: Groundwater and soil investigation

Client: Lendlease

Drawn: Glen Chisnall

Source: Google Earth