

PHOTOS OF SITE AND SURROUNDS



Photo 1: View over the main quarry floor in a south westerly direction





Photo 2: View over the main quarry floor in a westerly direction



Photo 3: View over the processing area





Photo 4: View over the processing area



Photo 5: Main crushing and screening plant





Photo 6: Refuelling area



Photo 7: View of the main site access from the administration building





Photo 8: Weighbridge to the south of the administration building



Photo 9: Rail siding and loading facility to the south of the processing area







Job Ref: 14/0228 EIS – Martins Creek Quarry



Photo 11: Rail siding with Station Street to the right of the photo.



Photo 12: Intersection of Station Street and Grace Avenue/Cory Street



Photo 13: View towards Douglas Street along Cory Street in a southerly direction






Photo 14: View along Cory Street in a westerly direction towards the intersection with Station Street



Photo 15: Alternative access on Douglas Street (Viewed to the south)





Photo 16: Alternative access on Douglas Street (Viewed to the north, with processing area in the background)



Photo 17: Gostwyck Bridge on Dungog Road over the Paterson River





Photo 18: Intersection between Dungog Road and Gresford Road



Photo 19: Duke Street in Paterson





Photo 20: Level crossing on King Street in Paterson