



Issue

No.	Date	Description
A	18/05/2015	Original
B	05/01/2016	2nd Issue

Chkd
Gary Skov

Notes

- All bearings are oriented on MGA North
- Origin of levels SSM 20465 RL 76.809 (AHD71)
- The contour interval is 0.5 Metre
- Relationship of Improvements to boundaries if critical should be confirmed by a boundary survey and marked on site prior to construction
- No services search has been undertaken. Services shown are based on surface indicators evident at the date of

survey and plotted as a guide to the position and nature of the service, before any excavation on the site, the "Dial Before You Dig" service should be used (Phc 1100)

- Ridge, roof, eave and gutter heights have been obtained by an indirect method and are accurate for planning purposes only
- Gutter levels shown are measured to the lip of the gutter
- The spread and height of each tree is indicative only and specific details if critical will require further survey

Legends

TK	Top of Kerb	BW	Base of Wall
WM	Water Meter	KG	Kerb Gutter
GM	Gas Meter	EK	Electricity Kiosk
SIH	Sewer Inspection Hole	DB	Distribution Board
TF	Top of Fence	WV	Water Valve
PP	Power Pole	SV	Stop Valve
S.PIT	Sealed Pit	FH	Fire Hydrant
G.PIT	Grated Pit		
TW	Top of Wall		

Drawing Title

Survey Plan

Project Title

Taronga Zoo

at
Bradleys Head Road, Mosman NSW 2088
for

Date 16-02-2016

Scale 1:1500 @ A1

0 1m 2m 3m 4m 5m 6m

Drawing Number

13229