

3 November 2021

| REF: | monthly | report | 2110 |
|------|---------|--------|------|
|      |         |        |      |

#### **Transport for NSW**

Attention to:
Parramatta Light Rail

#### RE: Parramatta Light Rail – ER Monthly Report for October 2021

submits this report to the Secretary in accordance with:

- Condition A23 (i) of the Conditions of Approval for the Parramatta Light Rail project, ER is to prepare and submit to the Secretary and other relevant regulatory agencies, for information, an **Environmental Representative Monthly Report**, and;
- As required by the appointment as the approved Environmental Representative (DPIE letter dated 21/8/2018)

The attached summary details the requirements of the monthly report in accordance with the ER Protocol for works during the month of October 2021 for the Parramatta Light Rail project.

The report includes information for the following contractors/packages:

- PCPLR (CPBD) Infrastructure works
- GRCLR SOM

Yours sincerely,

Environmental Representative

| <u>Summary</u>     | Table  | for  | October   | 2021 | -Parramatta | Connect | Light | Rail | (CPBD) |   |
|--------------------|--------|------|-----------|------|-------------|---------|-------|------|--------|---|
| <u>Infrastruct</u> | ure Pa | ckag | <u>qe</u> |      |             |         |       |      |        |   |
|                    |        |      |           |      |             |         |       |      |        | _ |

## Key construction activities

#### ER team:

The following construction activities were undertaken in the reporting period:

#### AREA 1

#### Westmead

- Ongoing property adjustment, drainage, Combined Service Route (CSR), track works
- Urban design landscaping works continued

#### Cumberland

- Ongoing property adjustment, drainage, CSR, track works
- Urban design landscaping works commenced

#### North Parramatta

- Ongoing utility, property adjustment, drainage, CSR, track works
- Urban design landscaping works continued

#### AREA 2

#### West (CBD)

- Ongoing utility and services installations on Church Street and Macquarie Street
- Ongoing electrical and lighting works
- Ongoing Multifunction Pole works
- Drainage works along North Lennox Bridge, Macquarie Street
- Landscaping, paving and umbrella installation on **Church Street**
- Footpath works along Church Street and Macquarie Street
- Finishing works
- Intersection works:
  - Church/Phillip Street Intersection
  - Church/George Street Intersection

#### East (Smith Street to Arthur Street)

- Drainage works on Macquarie Street, Tramway Avenue
- Ongoing civil works (pavement, CSR, road works) along Macquarie Street, Harris Street / Robin Thomas Reserve, George Street, Tramway Avenue
- Track works along Macquarie Street George Street
- Intersection works:
  - Macquarie/Harris Street
  - George/Alfred Street

#### AREA 3

#### Camellia

James Ruse Drive Bridge fit out works and track works.

Monthly Report 2110 Page 2 of 12

#### Paving at Camellia Platform

Landscaping works

#### **Carlingford Line**

- ATL in Carlingford and at the stops
- CSR and track slab works at Rydalmere and Dundas Stops
- Rail grinding (Camellia to Carlingford).
- Soft landscaping works from Camellia to Carlingford
- Telopea & Carlingford Stop works ongoing
- Footpath connections from Camellia to Carlingford.

# Upcoming construction activities, monthly look ahead

#### Area 1:

- Continue drainage, CSR, property adjustment and track works at Westmead, Cumberland campus and North Parramatta
- Bridge deck pour followed by track slab and track

#### Area 2:

#### West (CBD)

- Eat Street (1B) Commence boxout for CSR and track slab
- Church Street continue of pavement and kerbing
- Church Street continue footpath works
- Church Street continue landscaping and MFP installation
- Church Street continue intersections finishing works (George St)
- Macquarie Street continue box out for CSR and track slab
- Macquarie Street continue track and slab installation
- Macquarie Street continue pavement and kerbing
- Macquarie Street continue footpath works
- Intersection closures:
  - Macquarie/Smith Street Intersection

#### East (Smith Street to Arthur Street)

- Macquarie Street continue box out for CSR and track slab
- Macquarie Street continue track and slab installation
- Macquarie Street continue pavement, kerbing and landscaping
- Macquarie Street continue MFP installation
- Harris Street continue drainage
- Harris Street sewer adjustment works
- Harris Street (RTR) grass track
- Harris Street (RTR) landscaping
- George Street continue box out for CSR, track slab and roads
- George Street continue track and slab installation
- George Street continue landscaping
- George Street property adjustments
- Tramway Avenue continue box out for CSR, track slab and roads
- Tramway Avenue continue paving and landscaping
- Tramway Avenue platform construction

Monthly Report 2110 Page 3 of 12

|                           | Tramway Avenue – box out for CSR and track slab  |  |
|---------------------------|--|--|
|                           | Intersection closures  |  |
|                           | Macquarie/Charles Street (Jan '22)   |  |
|                           | Macquarie/Harris Street  |  |
|                           | AREA 3:  |  |
|                           | <u>Camellia</u>  |  |
|                           |  |  |
|                           | <ul> <li>James Ruse Drive Bridge track works</li> </ul>  |  |
|                           | <u>Carlingford Line</u>  |  |
|                           | <ul> <li>ATL, CSR,drainage, platform and track works at Rydalmere<br/>and Dundas stops.</li> </ul>   |  |
|                           | <ul> <li>Soft landscaping works from Camellia to Carlingford</li> </ul>  |  |
|                           | <ul> <li>Footpath connections</li> </ul>   |  |
|                           | <ul> <li>Defect rectification works</li> </ul>   |  |
| Changes to project:       | Consistency Assessments  |  |
| get to project            | <ul> <li>Nil this reporting period</li> </ul>  |  |
|                           | Environmental Review   |  |
|                           | ER-078: Alexandra Ave Westmead TCS works Rev 01  |  |
| ED A skiniki sa           | There were four increasting a conducted by the FD during the   |  |
| ER Activities             | There were four inspections conducted by the ER during the reporting period:   |  |
| Site inspections :        | CPBD092 - 6 October 2021   |  |
|                           |  |  |
|                           | CPBD093 – 12 October 2021  |  |
|                           | CPBD094 – 19 October 2021  |  |
|                           | CPBD095 – 26 October 2021  |  |
| Audit                     | An external CPB systems audit was finalised during the reporting period  |  |
| Community consultation    | There were nine construction notifications issued for the period. IW 381, 369b, 387, 375, 376, 377, 379, 374a, 369a  |  |
| Complaints received       | There were 80 complaints in the period. There was 32 complaints about noise and vibration  |  |
| Environmental             | Environmental Incidents  |  |
| Performance/NCR/Incidents | 8 Oct – a member of the public (MOP) has driven into a water meter at 137 Arthur Street causing a leak into the kerb and pooling at the site access. There was no loss of water to stormwater.   |  |
|                           | 15 Oct – at the Church Street and Victoria Road intersection, a water main strike occurred following the breaking and removal of the temporary asphalt. The water main was identified 0.5 metres below the surface directly underneath the temporary asphalt and was more shallow then anticipated. No trenches or any other open excavations were present during the incident, meaning the water remained without sediment and mobilised off-site as clean water. |  |
|                           | 28 Oct - a water feed was struck at the corner of Pennant Hills Road and Church Street. The water was contained to site and there was no loss of water to stormwater   |  |
|                           | Non-compliances  |  |
|                           |  |  |

Monthly Report 2110 Page 4 of 12

| Lessons learnt/Opportunities for Improvement                   | <ul> <li>The following opportunity for improvement was raised by the ER during the reporting period:         <ul> <li>6 October 2021: Parramatta River bridge, southern abutment</li></ul></li></ul>   |
|--|--|
| Changes to Project Plans/Approvals                             | washout facilities are available for concrete pumps and chutes.  All CEMP subplans were updated and submitted for review. ER comments were sent to Contractor  |
| Meetings attended  | Env coordination meeting – 12/10/21 Env coordination meeting – 26/10/21 DPIE meeting – 2/10/21   |
| Documents reviewed and/or endorsed by ER this reporting period | Flexibility Provision endorsement  - Nil this reporting period   |
| Document issued by ER  | OOH approvals: Nil this reporting period.  |
|  | Minor Ancillary Facility approval: MAF-011 Lennox Bridge   |
| Requests or CAR's by ER  | Nil this reporting period  |
| Analysis of monitoring results                                 | 19 x noise monitoring, no exceedances of predictions associated with construction noise (including 4 x continuous noise loggers within Westmead/Cumberland hospital precinct and 10 x monthly ambient monitoring)  3 x continuous vibration monitors within Westmead/Cumberland hospital precinct.  DDG for 13A Grand Ave, Dundas, Telopea and Rydalmere for August, with 13A Grand Ave exceeding the TIM level. Water cart use was increased for this site. It is noted that 13A Grand Ave is now landscaped. DDG has been removed from Carlingford.  Asbestos air fibre monitoring was undertaken and no results exceeded the trigger limits.  1 x water discharge/dewatering events, within limits  No water quality monitoring was undertaken during the reporting period as there were no trigger events.  GHFF monitoring was undertaken on the following dates 27/9, 1/10, 7/10, 18/10 with no disturbance identified  Nest box monitoring was undertaken in September with the report expected in November |

Monthly Report 2110 Page 5 of 12

### **Photos**



Inspection CPBD094, 19/10/21

Area 1: Hawkesbury Rd – Earthworks.



Inspection CPBD095, 26/10/21

Area 3: Carlingford – paving and landscaping completed at Carlingford stop





Inspection CPBD095, 26/10/21

Area 3: Telopea – paving complete, landscaping taking place



Inspection CPBD095, 26/10/21

Area 3: Camellia stop



Inspection CPBD093, 12/10/21

Area 2: Robin Thomas Reserve – track being prepared for placement of vegetation

Monthly Report 2110 Page 8 of 12

# Summary Table for October 2021 - GRCLR - SOM

|   | The following construction activities were undertaken in October:           |  |
|---|---|--|
| Key construction activities                     | The following construction activities were undertaken in October.           |  |
| ER team:  | SAMF  |  |
|   | Site establishment - haul road construction                                 |  |
|   | Material import   |  |
|   | Erosion and sediment control installation                                   |  |
|   | Survey/site surveillance and validation works                               |  |
|   | Whole alignment   |  |
|   | Geotechnical and utilities investigation works at TPS sites                 |  |
| Upcoming construction activities,               | SAMF construction:  |  |
| monthly look ahead                              | Earthworks  |  |
|   | Drainage  |  |
|   | Depending on handover timing  |  |
|   | Site establishment – TPS 4, 6, 7 and BOCC (Dundas)                          |  |
| Changes to project:                             | Consistency Assessments   |  |
| analgee to project                              | <ul> <li>Nil this reporting period</li> </ul>                               |  |
|   | Environmental Reviews   |  |
|   | <ul> <li>Nil this reporting period</li> </ul>                               |  |
| ER Activities                                   | There were two inspections conducted by the ER during the reporting period: |  |
| Site inspections :                              | SOM001 - 6 October 2021   |  |
|   | SOM002 – 19 October 2021  |  |
|   |   |  |
| Audit   | Nil this reporting period   |  |
| Community consultation                          | 1 x notification distributed this reporting period                          |  |
| Complaints received                             | Nil this reporting period   |  |
| Environmental Performance/NCR/Incidents         | Nil this reporting period   |  |
| Lessons learnt/Opportunities for<br>Improvement | Nil this reporting period   |  |
| Changes to Project Plans/Approvals              | Updates to the following plans are pending for the next reporting period:   |  |
|   | • SWMP  |  |
|   | • WRMP  |  |
|   | • TTAMP   |  |
| Meetings attended                               | Meeting attended by ER via Teams:   |  |
|   | - 5 October 2021 (EPS)  |  |
|   | - 19 October 2021 (EPS)   |  |
|   | 13 OCCORCI 2021 (LF3)   |  |

Monthly Report 2110 Page 9 of 12

| Documents reviewed and endorsed | ECM001 – SAMF<br>ECM002 – TPS 4     |  |
|---------------------------------|-------------------------------------|--|
| by ER this reporting period     | ECM003 – TPS 6                      |  |
|                                 | ECM004 – TPS 7                      |  |
|                                 | Flexibility Provision endorsement   |  |
|                                 | - Nil this reporting period         |  |
| Document issued by ER           | OOH approvals :                     |  |
|                                 | Nil this reporting period           |  |
|                                 | Minor Ancillary Facility approval : |  |
|                                 | Nil this reporting period           |  |
| Requests or CAR's by ER         | Nil this reporting period           |  |
| Analysis of monitoring results  | Nil this reporting period           |  |

# Photos -



Inspection SOM001, 6/11/21
Grand Ave access, stabilisation has commenced.



Water pooling in building footprint.

Monthly Report 2110 Page 10 of 12



Inspection SOM002, 19/11/21

Grand Ave boundary – sediment fencing working effectively.

Monthly Report 2110 Page 11 of 12

# <u>Summary Table for October 2021 – Community Consultation</u>

| Activity   | Detail   |
|--|--|
| Reference Groups via video   | 28 Oct – Greater Parramatta Group (stakeholder engagement meeting) held  |
| conference call  | virtually  |
|  | 7 Oct: website clocks over two million views   |
| Community Information  | 15 Oct: Eat Street open for business   |
| Events   | 15 Oct: Stage 1 Eat Street Uncovered activation  |
|  | 19 Oct: Our Lady of Mercy College (OLMC) and PLR virtual event – project   |
|  | update and career discussion with successful women on the project  |
|  | 80 complaints received, with the majority in Parramatta CBD. Top complaints related to:  |
|  | Noise day works and night works  |
| Complaints:  | Property damage  |
|  | Traffic and parking, and   |
|  | Access   |
| Emandida   | 98 enquiries were received in October. Top enquiries related to access,  |
| Enquiries  | property damage, construction impacts and noise and vibration.   |
| Construction Notifications   | 10 construction notifications distributed in October   |
| distributed  | 9 for Infrastructure Works   |
| distributed  | 1 for Supply, Operate and Maintain   |
| Fact Sheets  | Nil this reporting period  |
| (uploaded to website)  |  |
| Business Activation activities Facebook posts (Parramatta Light Rail) https://www.facebook.com/P | 13 Facebook posts were uploaded during October 2021. The most popular Facebook post by reach was an aerial photo view of Parramatta, reaching 38,045 people. The most popular post by engagement was a post regarding the new paving in North Parramatta, with 4515 engagements. |
| <u>arramattaLightRail</u>  |  |
| PLR Quarterly Newsletter   | Nil this reporting period  |
|  | Website clocks over two million views  |
| Media Release  | Parramatta's Eat Street open for business  |

Monthly Report 2110 Page 12 of 12