



Image Source: Mount Owen (2013)
Data Source: Mount Owen (2014)

0 0.25 0.5 1.0 km
1:20 000

Legend

- Proposed Disturbance Area
- Verification Application Area
- Soil Sampling Site (previous check site)
- Soil Pit and Sampling Site
- Check Site (new)
- >10% Slope

File Name (A4): R17/3109_1032.dgn
20150909 9.40

FIGURE 2.3
Slopes > 10%